



report date: 2024-03-29

General information

Make	VAUXHALL
Model	AGILA DESIGN
Colour	Red
Year of manufacture	2009
Top speed	109 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	114 Nm at 4.400 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg
CO2 emission	131 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-02-05
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-03-06
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	14
Total items failed	3

MOT #16	2024-03-07 11:21
MOT test number	706938709078
Result	✓ Passed
Next expiry date	2025-03-06

MOT #15	2023-03-07 10:37
MOT test number	220307229894
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing 185/60/15 (5.2.3 (d) (ii))
Advice	Offside Front Tyre slightly damaged/cracking or perishing 185/60/15 (5.2.3 (d) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing 185/60/15 (5.2.3 (d) (ii))

MOT #14	2022-02-07 14:00
MOT test number	761151558317
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #13** 2022-02-07 11:28**MOT test number** 835929359573**Result** ✗ Failed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #12** 2021-03-06 12:00**MOT test number** 725821884001**Result** ✓ Passed**MOT #11** 2020-02-04 11:46**MOT test number** 356415451255**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #10** 2019-02-26 16:35**MOT test number** 803555644967**Result** ✓ Passed**MOT #9** 2019-02-26 16:35**MOT test number** 771569158955**Result** ✗ Failed**Pass with rectification** Offside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))



MOT #8	2018-02-13 10:32
---------------	------------------

MOT test number	840614924295
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #7	2017-02-09 11:26
---------------	------------------

MOT test number	122209556642
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2016-02-04 14:38
---------------	------------------

MOT test number	584586661346
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2015-03-02 14:35
---------------	------------------

MOT test number	565271165088
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2015-03-02 14:35
---------------	------------------

MOT test number	137251465444
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
--------------------------------	--

MOT #3	2014-01-30 13:01
---------------	------------------

MOT test number	308070734057
------------------------	--------------

Result	✓ Passed
---------------	----------

Notice	Slight cracking in rear tyre treads
---------------	-------------------------------------

MOT #2	2013-01-25 11:36
---------------	------------------

MOT test number	236905923083
------------------------	--------------

Result	✓ Passed
---------------	----------



MOT #1	2012-01-27 11:20
MOT test number	997387422092
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
6 March 2025

Tax status	Valid until 1 March
Days left	307
MOT expiry date	6 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-01-30
Last registration	2024-03-07
Complete history	See info



Registration #1	2009-01-30	27 mi
Registration #2	2012-01-27	14.824 mi
Registration #3	2013-01-25	26.850 mi
Registration #4	2014-01-30	34.912 mi
Registration #5	2015-03-02	38.563 mi
Registration #6	2016-02-04	414.419 mi
Registration #7	2017-02-09	207.084 mi
Registration #8	2018-02-13	47.477 mi
Registration #9	2019-02-26	50.391 mi
Registration #10	2020-03-02	51.377 mi
Registration #11	2021-03-02	51.377 mi
Registration #12	2022-03-02	51.377 mi
Registration #13	2023-03-02	51.377 mi
Registration #14	2024-03-02	51.377 mi
Registration #15	2025-03-02	51.377 mi
Registration #16	2026-03-02	51.377 mi
Registration #17	2027-03-02	51.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Max. allowed weight	1485 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	1096095