



report date: 2024-03-29

General information

Make	MINI
Model	ONE
Colour	Blue
Year of manufacture	2013
Top speed	116 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	153 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	52.3 mpg
CO2 emission	127 g/km
CO2 label	D





MOT history

MOT expiry date	2025-02-20
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	10
Total items failed	2

MOT #10	2024-02-21 15:34
MOT test number	100366819758
Result	✓ Passed
Next expiry date	2025-02-20

MOT #9	2023-02-15 14:01
MOT test number	158249000009
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #8	2022-02-16 13:04
MOT test number	876456969873
Result	✓ Passed
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #7	2020-11-23 14:03
MOT test number	240100501058
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #6** 2019-11-01 10:40**MOT test number** 406257145901**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Wear on outer edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge Wear on inner edge (5.2.3 (e))**MOT #5** 2018-11-02 09:49**MOT test number** 520696604381**Result** ✓ Passed**MOT #4** 2018-11-02 09:49**MOT test number** 933521083723**Result** ✗ Failed**Pass with rectification** Nearside Windscreen washer not working (3.5 (a))**MOT #3** 2017-11-24 12:02**MOT test number** 352424551221**Result** ✓ Passed**MOT #2** 2017-11-24 12:02**MOT test number** 186707655779**Result** ✗ Failed**Pass with rectification** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)



MOT #1	2016-11-24 16:11
MOT test number	960319174246
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	OSF tyre on 3mm



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
20 February 2025

Tax status	Valid until 1 March
Days left	305
MOT expiry date	20 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	GY63KEU
Plate since	2019-09-29
Current registration	GY63KEU
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2013-11-30
Last registration	2024-02-21
Complete history	See info



Registration #1	2013-11-30	11 mi
Registration #2	2016-11-24	16.336 mi
Registration #3	2017-11-24	26.260 mi
Registration #4	2017-11-24	26.260 mi
Registration #5	2018-11-02	31.206 mi
Registration #6	2018-11-02	31.206 mi
Registration #7	2019-05-29	35.277 mi
Registration #8	2019-05-29	35.277 mi
Registration #9	2019-05-29	35.277 mi
Registration #10	2019-05-29	35.277 mi
Registration #11	2019-05-29	35.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1060 kg
Max. allowed weight	1530 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	A474J474