



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	GOLF SE TDI BLUEMOTION
Colour	Grey
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	68.9 mpg
CO2 emission	109 g/km
CO2 label	B



**MOT history**

MOT expiry date	2024-06-12
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	24
Total items failed	3

MOT #11	2021-01-14 10:44
MOT test number	983734571016
Result	✓ Passed
Next expiry date	2022-01-24
Advice	Rear Registration plate insecure but not likely to fall off (0.1 (a))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #10	2020-01-11 13:21
MOT test number	850351294544
Result	✓ Passed

MOT #9	2019-01-21 10:09
MOT test number	636350106783
Result	✓ Passed
Minor	Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #8** 2019-01-21 10:09**MOT test number** 222659686813**Result** ✗ Failed**Minor** Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #7** 2018-01-23 15:51**MOT test number** 436183647413**Result** ✓ Passed**Advice** Registration plate deteriorated but not likely to be misread front and rear (6.3.1d)**Advice** Emission is to lean to measure**Advice** Both front discs are lipped**MOT #6** 2018-01-23 15:51**MOT test number** 277406512071**Result** ✗ Failed**Pass with rectification** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**Advice** Emission is to lean to measure**Pass with rectification** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**Advice** Registration plate deteriorated but not likely to be misread front and rear (6.3.1d)**Advice** Both front discs are lipped

**MOT #5** 2017-01-25 12:38**MOT test number** 965708664904**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Nearside Rear tyre worn on inner edge**Advice** Front wiper blades worn & noisy**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Rear rear tyre worn on inner edge**MOT #4** 2016-01-22 15:53**MOT test number** 539609234982**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #3** 2015-01-22 15:26**MOT test number** 395522525031**Result** ✓ Passed**Advice** Front registration plate delaminated but not likely to be misread (6.3.1d)**Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2014-01-17 17:28**MOT test number** 356457414052**Result** ✓ Passed



MOT #1	2013-01-21 16:26
MOT test number	105651723079
Result	✓ Passed
Notice	Under-trays fitted obscuring some underside components
Notice	Engine covers fitted obscuring some components in the engine bay



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
12 June 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	12 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 WP59ZXO
Plate since	2024-03-29
Current registration	 WP59ZXO
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2010-01-22
Last registration	2021-01-14
Complete history	See info



Registration #1	2010-01-22	12 mi
Registration #2	2013-01-21	38.952 mi
Registration #3	2014-01-17	48.898 mi
Registration #4	2015-01-22	58.366 mi
Registration #5	2016-01-22	64.376 mi
Registration #6	2017-01-25	71.602 mi
Registration #7	2018-01-22	78.376 mi
Registration #8	2019-01-22	85.150 mi
Registration #9	2020-01-22	91.924 mi
Registration #10	2021-01-14	98.698 mi
Registration #11	2022-01-14	105.472 mi
Registration #12	2023-01-14	112.246 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1781 mm
Height	1504 mm
Length	4534 mm
Wheel base	2578 mm
Kerb weight	1318 kg
Max. allowed weight	1960 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	CAY 080363