





report date: 2024-03-28

General information

Make	AUDI
Model	A4 TDI E SE
Colour	Grey
Year of manufacture	2009
Top speed	134 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	74.3 mpg
Consumption combined	61.4 mpg
CO2 emission	120 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-06-09

Pictures 7

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-08-14
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	21
Total items failed	4

MOT #12	2023-08-15 16:52
MOT test number	974878081484
Result	✓ Passed
Next expiry date	2024-08-14

MOT #11	2022-05-19 15:27
MOT test number	948774583977
Result	√ Passed

MOT #10	2021-05-17 11:55
MOT test number	151796575000
Result	✓ Passed
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

MOT #9	2020-05-22 12:48
MOT test number	169508640393

Advice Nearside Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #8 2017-12-05 16:47 **MOT** test number 557918979639 Result ✓ Passed **Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3) Advice Engine management light on Nearside Rear Brake pad(s) wearing thin (3.5.1g) Advice Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Offside Front Tyre worn close to the legal limit 2mm (4.1.E.1) **Advice**

2017-12-02 12:07 **MOT #7 MOT** test number 187260915636 Result × Failed Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) Advice Nearside Rear Brake pad(s) wearing thin (3.5.1g) **Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Advice Offside Front Tyre worn close to the legal limit 2mm (4.1.E.1) Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Nearside Rear Shock absorber has a light misting of oil (2.7.3) Advice Advice Engine management light on

MOT #6	2016-11-26 11:22
MOT test number	767920454606
Result	✓ Passed
Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3)	
Advice Nearside Rear Nail in tyre	

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #5

MOT test number

655345143967

Result

Advice Front brake discs slightly worn

MOT #4 2014-11-12 16:09
MOT test number 495546414370
Result ✓ Passed

MOT #3 2014-11-12 14:47
MOT test number 887326514361

Result X Failed

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #2 2013-11-29 10:15

MOT test number 207633733307

Result ✓ Passed

Notice Vehicle's internal headlight adjuster altered to recheck lights

Notice Under-trays fitted obscuring some underside components

MOT #1 2012-10-11 12:34

MOT test number 638715982267

Result ✓ Passed

CarCheck.co.uk page 5/12





report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 December
Days left	216
MOT expiry date	14 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



YH59WKE report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history	
---------------	--

Owner mistory		
For how long did the current and previous owner(s) have this AUDI? How many owners d Check it in the premium report and see all owner registrations. Download the full report		>

THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDR		

	More info >	
Plate changes		
See in this check if this AUDI had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK ZIS	
Plate since		
	More info >	

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



YH59WKE report date: 2024-03-28

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2009-10-28
Last registration	2023-08-15
Complete history	See info



Registration #1	2009-10-28	29 mi
Registration #2	2012-10-11	33.879 mi
Registration #3	2013-11-29	39.929 mi
Registration #4	2014-11-12	50.942 mi
Registration #5	2014-11-12	50.942 mi
Registration #6	2015-11-21	63.018 mi
Registration #7	2016-11-26	68.968 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es

7075.75.75

More info >

77.777 86

CarCheck.co.uk page 11/12



YH59WKE report date: 2024-03-28

Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	93%
Children	84%
Pedestrian	39%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1826 mm
Height	1427 mm
Length	4703 mm
Wheel base	2808 mm
Kerb weight	1475 kg
Max. allowed weight	2025 kg

Additional information

Fuel tank capacity	63 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5 pag	ge 12/12

Number of axles 2

Engine number CAG 277163