



YA06XNC

report date: 2024-03-29

General information

Make	FIAT
Model	GRAND PUNTO ACTIVE
Colour	Grey
Year of manufacture	-
Top speed	96 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	65 BHP
Max. torque	102 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg







Internet history

Entry 1

Date	2021-01-29
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)

**MOT history**

MOT #22	2023-02-07 16:43
MOT test number	477205578977
Result	✓ Passed
Next expiry date	2024-02-09
Advice	Offside Front Tyre worn close to legal limit/worn on edge worn on edges (5.2.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Coil spring corroded both rears (5.3.1 (b) (i))
Advice	Offside Front Direction indicator slightly discoloured (4.4.3 (a))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #21	2023-02-07 09:11
MOT test number	695393461530
Result	✗ Failed
Fail	Driver's view of the road through the swept area of the windscreen significantly affected by an obstruction (3.1 (a) (ii))
Advice	Offside Front Direction indicator slightly discoloured (4.4.3 (a))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Coil spring corroded both rears (5.3.1 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge worn on edges (5.2.3 (e))
Fail	Rear fog lamp light intensity significantly reduced (4.5.4 (a))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**MOT #20**

2022-01-26 15:36

MOT test number

996378860130

Result

✓ Passed

- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear tyre run flat damage to side wall recommend remove/inspection of inside
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Emissions erratic

MOT #19

2022-01-26 12:39

MOT test number

340034460459

Result

✗ Failed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Fail** Offside Parking brake inoperative on one side (1.4.1 (a))
- Advice** Offside Rear tyre run flat damage to side wall recommend remove/inspection of inside
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Nearside Front Service brake lagging in operation (1.2.1 (d))
- Fail** Brake lever has insufficient reserve travel (1.1.2 (a))
- Advice** Emissions erratic
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #18

2021-02-10 12:16

MOT test number

721324851906

Result

✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear note rear upper central stop lamp more than 50 percent working

**MOT #17** 2020-07-29 13:24**MOT test number** 291217388786**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #16** 2020-07-28 13:21**MOT test number** 448156384012**Result** ✗ Failed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**MOT #15** 2019-07-24 14:29**MOT test number** 754248940137**Result** ✓ Passed**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Oil leak, but not excessive driveshaft oil seal (8.4.1 (a) (i))**MOT #14** 2018-07-25 09:57**MOT test number** 456754703281**Result** ✓ Passed**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13** 2017-07-24 14:02**MOT test number** 271547169134**Result** ✓ Passed**MOT #12** 2017-07-24 10:02**MOT test number** 437061646706**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #11** 2016-07-29 14:20**MOT test number** 501267092118**Result** ✓ Passed**MOT #10** 2016-07-22 15:37**MOT test number** 451436220593**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**MOT #9** 2015-07-18 12:17**MOT test number** 639469595141**Result** ✓ Passed**Notice** Gear oil leak

**MOT #8** 2014-07-24 11:16**MOT test number** 465665504212**Result** ✓ Passed**Notice** Nearside windscreen wiper slightly split**Advice** Nearside Ball joint has slight play (2.2.B.1f)**Notice** Nearside rear door handle sticking**MOT #7** 2013-07-22 14:10**MOT test number** 996333603237**Result** ✓ Passed**Notice** Gearbox oil leak**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2013-07-22 11:43**MOT test number** 209923003215**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Gearbox oil leak**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #5** 2012-07-26 14:48**MOT test number** 569508702297**Result** ✓ Passed

**MOT #4** 2011-07-22 09:27**MOT test number** 399343101441**Result** ✓ Passed**Notice** Offside front tyre wearing on inner edge**MOT #3** 2010-07-26 14:43**MOT test number** 111227000257**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2009-07-09 12:08**MOT test number** 242680899190**Result** ✓ Passed**MOT #1** 2009-07-09 12:08**MOT test number** 652830999197**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2006-07-28
Last registration	2023-02-07
Complete history	See info



Registration #1	2006-07-28	14 mi
Registration #2	2009-07-09	15.665 mi
Registration #3	2010-07-26	18.731 mi
Registration #4	2011-07-22	22.378 mi
Registration #5	2012-07-26	25.175 mi
Registration #6	2013-07-22	26.561 mi
Registration #7	2013-07-22	26.561 mi
Registration #8	2014-07-24	30.339 mi
Registration #9	2015-07-18	32.929 mi
Registration #10	2016-07-22	36.232 mi
Registration #11	2016-07-29	36.232 mi
Registration #12	2017-07-24	40.863 mi
Registration #13	2018-07-24	45.494 mi
Registration #14	2019-07-24	50.125 mi
Registration #15	2020-07-24	54.756 mi
Registration #16	2021-07-24	59.387 mi
Registration #17	2022-07-24	64.018 mi
Registration #18	2023-02-07	68.649 mi
Registration #19	2023-02-07	68.649 mi
Registration #20	2023-02-07	68.649 mi
Registration #21	2023-02-07	68.649 mi
Registration #22	2023-02-07	68.649 mi
Registration #23	2023-02-07	68.649 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1015 kg
Max. allowed weight	2475 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Engine number	3180591
---------------	---------