





report date: 2024-03-28

General information

Make	HONDA
Model	ACCORD VTEC EX
Colour	Silver
Year of manufacture	2006
Top speed	134 mph
0 - 60 mph	10.6 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	153 BHP
Max. torque	190 Nm at 4.500 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Petrol
Consumption city	23.2 mpg
Consumption extra urban	44.8 mpg
Consumption combined	33.6 mpg
CO2 emission	200 g/km
CO2 label	J



CarCheck.co.uk page 1/16



report date: 2024-03-28

Internet history

Entry 1

Date 2021-09-26

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/16



MM06ZTT report date: 2024-03-28

MOT history

MOT expiry date	2024-09-11
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	66
Total items failed	1

MOT #16	2023-09-12 06:36
MOT test number	949945246592
Result	✓ Passed
Next expiry date	2024-09-11
Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	

CarCheck.co.uk page 3/16



report date: 2024-03-28

MOT #15 2023-09-01 13:32

MOT test number 220836644838

Result × Failed **MAJOR** Exhaust hydrocarbon content after 2nd fast idle exceeds default limits (8.2.1.2 (b)) **MAJOR** Offside Rear reflector missing (4.8.2 (a) (ii)) Minor Offside Front Lower Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i)) **MAJOR** Nearside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i)) Front Bumper insecure (6.1.4 (a) (i)) **MAJOR** Exhaust carbon monoxide content at idle exceeds default limits (8.2.1.2 (b)) **MAJOR Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii)) Minor Nearside Front Windscreen wiper blade defective (3.4 (b) (i)) **MAJOR** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b)) **MAJOR** Nearside Front Anti-roll bar linkage insecurely attached (5.3.3 (a) (i)) Nearside Front Upper Suspension arm ball joint excessively worn (5.3.4 (a) (i)) **MAJOR Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #14 2022-08-12 10:56

MOT test number 570663204001

Result \(\sqrt{Passed} \)

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1

Minor Battery insecure but not likely to fall from carrier (4.13 (a) (i))

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Minor Offside Windscreen wiper blade defective (3.4 (b) (i))

(b) (i))

CarCheck.co.uk page 4/16



report date: 2024-03-28

MOT #13 2021-08-24 13:51

MOT test number 236282147672

Result ✓ Passed **Advice** Front and rear number plates showing deterioration Advice Under shield Advice Exhaust has a minor leak of exhaust gases exhaust showing corrosion (6.1.2 (a)) Minor Battery insecure but not likely to fall from carrier (4.13 (a) (i)) Advice Rear sub-frame showing corrosion Advice Offside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) **Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Headlamp lenses showing deterioration Advice Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) Advice N/s and o/s front and rear brake discs showing corrosion Advice Nearside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice**

CarCheck.co.uk page 5/16



report date: 2024-03-28

MOT #12	2019-09-26 15:19
MOT test number	518571617601
Result	✓ Passed
Advice Exhaust has a minor leak of exhaust gases showing corrosion (6.1.2 (a))	
Advice Child seat fitted	
Advice Rear subframe showing corrosion	
Advice Front brake discs showing wear	
Advice Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Minor Battery insecure but not likely to fall from carrier (4.13 (a) (i))	
Advice Rear tyres worn on inner edges	
Advice Under shield	
Advice Front tyres wearing on edges	

MOT #11		2018-09-27 16:07
MOT test	number	141920437094
Result		✓ Passed
Advice	Front number plate showing deterioration	
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Advice	O/s/r tyre wearing on inner and outer edges	
Advice	Child seat fitted	
Advice	N/s and o/s rear brake back plates showing corrosion	
Advice	Under shield	

CarCheck.co.uk page 6/16



Advice

MM06ZTT

report date: 2024-03-28

MOT #10	2017-09-28 11:28
MOT test	number 135201820374
Result	✓ Passed
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice of dirt (2.5	Nearside Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress i.C.1a)
Advice	Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
Advice (2.4.G.2)	Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement
Advice	Under shield
Advice	Exhaust has a minor leak of exhaust gases front flexible section showing deterioration (7.1.2)
Advice	Offside Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Advice (2.4.G.2)	Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Front brake discs worn

MOT #9		2016-09-27 15:40
MOT test	number	584509030631
Result		✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	
Advice (2.5.C.1a)	Nearside Front Front constant velocity joint gaiter damaged, but prevent	ing the ingress of dirt

Nearside Rear Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 7/16



Advice

MM06ZTT

report date: 2024-03-28

2015-09-18 13:49 **MOT #8** 776757672750 **MOT** test number Result ✓ Passed

Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #7 2014-09-09 12:08

MOT test number 109902954207

Result ✓ Passed

MOT #6 2013-08-30 15:32

MOT test number 868322043200

Result ✓ Passed

Advice Nearside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2012-09-10 08:10

MOT test number 789604952299

Result ✓ Passed

MOT #4 2012-09-06 13:34

MOT test number 389460452209

Result × Failed

Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 8/16



MM06ZTT report date: 2024-03-28

 MOT #3
 2011-09-05 16:37

 MOT test number
 696658441218

 Result
 ✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2

MOT test number

403180540122

Result

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

 MOT #1
 2009-06-05 15:22

 MOT test number
 270956059126

 Result
 ✓ Passed

CarCheck.co.uk page 9/16



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	11 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 10/16



report date: 2024-03-28

Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category



Extra HONDA salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 11/16



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 12/16



report date: 2024-03-28

Owner	history
OWITEL	HISLULY

,		
For how long did the current and previous owner(s) have this HONDA? How many owner have? Check it in the premium report and see all owner registrations. Download the full		

	More info >	
Plate changes		
See in this check if this HONDA had different number plates.		
Number of plates		
Correct registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info >	

CarCheck.co.uk page 13/16



report date: 2024-03-28

Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 14/16



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-07-28
Last registration	2023-09-12
Complete history	See info



Registration #1	2006-07-28	21 mi
Registration #2	2009-06-05	38.147 mi
Registration #3	2010-05-20	45.255 mi
Registration #4	2011-09-05	54.649 mi
Registration #5	2012-09-06	60.333 mi
Registration #6	2012-09-10	60.333 mi
Registration #7	2013-08-30	66.542 mi
Registration #8	2014-09-09	72.945 mi
Registration #9	2015-09-18	77.527 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 au

More info >

CarCheck.co.uk page 15/16



report date: 2024-03-28

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1760 mm
Height	1445 mm
Length	4665 mm
Wheel base	2670 mm
Kerb weight	1401 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Engine number	K20Z21108111

CarCheck.co.uk page 16/16