

## **\$** SUZUKI




### General information

Make	SUZUKI
Model	SWIFT SZ-T BOOSTERJET
Colour	Grey
Year of manufacture	2018
Top speed	121 mph
0 - 60 mph	10.6 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	109 BHP
Max. torque	170 Nm at 3.500 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	49.5 mpg
Consumption extra urban	70.6 mpg
Consumption combined	61.4 mpg
CO2 emission	104 g/km
CO2 label	В







## Internet history

Entry 2	
Date	2021-06-29
Pictures	20
Listing price	View report









source: heycar.co.uk

#### Entry 1

Date


Pictures

Listing price

2021-06-05

19

View report



source: yesauto.com









# MOT history

MOT expiry date	2025-04-25
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	19
Total items failed	2

MOT #6		2024-04-17 11:32
MOT test	number	617465612554
Result		✓ Passed
Next expi	ry date	2025-04-25
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Exhaust flexi pipe deteriorated	
Advice	Offside Front Tyre worn close to legal limit/worn on edge At 3mm (5.2.3 (e))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge At 3mm (185/55/16)	(5.2.3 (e))

MOT #5		2024-04-17 09:51
MOT test	number	538396744982
Result		🗙 Failed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge At 3mm (5.2.3 (e))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
FailNearside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt(5.3.4 (b) (ii))		
Advice	Nearside Front Tyre worn close to legal limit/worn on edge At 3mm (185/55/16	) (5.2.3 (e))
Advice	Exhaust flexi pipe deteriorated	





MOT #4	2023-04-26 15:02
MOT test number	822613942676
Result	✓ Passed
Advice Offside Rear Child Seat fitted not allowing full inspection of adu utilising belt. Unable to fully check	ult belt Child seat fitted to OSR
Advice TPMS light illuminated.	
<b>Advice</b> Front Tyre worn close to legal limit/worn on edge Both front type slight cracking within the tread (5.2.3 (e))	res 4mm, wearing to inner edge and
Advice Nearside Rear Tyre slightly damaged NSR tyre showing signs of slightly out of shape. (5.2.3 (d) (ii))	of stepping on the inner edge and
MOT #3	2023-04-25 08:28
MOT test number	284609580815
Result	× Failed
Fail Nearside Front Coil spring fractured or broken NSF coil spring broken	ken, bottom coil (5.3.1 (b) (i))
<b>Advice</b> Front Tyre worn close to legal limit/worn on edge Both front type slight cracking within the tread (5.2.3 (e))	res 4mm, wearing to inner edge and
Advice Offside Rear Child Seat fitted not allowing full inspection of adu utilising belt. Unable to fully check	ult belt Child seat fitted to OSR
Advice TPMS light illuminated.	
Advice Nearside Rear Tyre slightly damaged NSR tyre showing signs of slightly out of shape. (5.2.3 (d) (ii))	of stepping on the inner edge and
MOT #2	2022-03-25 15:45
MOT test number	545962713787
Result	✓ Passed
MOT #1	2021-02-25 15:10
MOT test number	504435178658

Result



Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

🗸 Passed



Tax & MOT check

√ Taxed	✓ MOT
Tax due: 1 September 2024	Expires: 25 April 2025
Tax status	Valid until 1 September
Days left	124
MOT expiry date	25 April 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	F
First licence fee (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-





#### Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
	E Store
Date	1. E
Category	amt
Туре	

#### Extra SUZUKI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200

More info  $\rightarrow$ 





## Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
***********	
********	
*******	
***********	
********	
	More info >
Plate changes	
See in this check if this SUZUKI had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carrent registration	
Plate since	
	More info >





#### Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this SUZUKI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-03-10
Last registration	2024-04-17
Complete history	See info



Registration #1	2018-03-10	26 mi
Registration #2	2021-02-25	51.073 mi
Registration #3		11.777 esi
Registration #4		11.777 esi
Registration #5	2022-03-25	58.453 mi
Registration #6		11.777 esi
Registration #7		11.777 esi
Registration #8		11.777 est
Registration #9		10.200 est

More info >





# Safety ratings

NCAP rating	****
Adult	88%
Children	75%
Pedestrian	69%
Safety systems	44%
Overall rating	73%
Video	see crash video



Dimensions & weight	
Width	1735 mm
Height	1495 mm
Length	3840 mm
Wheel base	2450 mm
Kerb weight	865 kg
Max. allowed weight	1380 kg
Additional information	
Fuel tank capacity	37
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	K10C-1078457