





General information

Make	BMW
Model	530 530D SE TOURING
Colour	Grey
Year of manufacture	2004
Top speed	149 mph
0 - 60 mph	7.4 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	218 BHP
Max. torque	500 Nm at 2.000 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	25.4 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.3 mpg
CO2 emission	213 g/km
CO2 label	Κ







Internet history

Entry 1

Date Pictures 2021-10-12

14

Listing price

View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-20
MOT pass rate	75 %
MOT passed	18
Failed MOT tests	6
Total advice items	31
Total items failed	15

MOT #24	2023-11-22 09:37
MOT test number	219833542670
Result	✓ Passed
Next expiry date	2024-12-20

MOT #23	2022-12-15 10:52
MOT test number	974339984303
Result	✓ Passed
Advice Nearside steering tie rod has slight play	

MOT #22	2021-12-21 10:51
MOT test number	815296167777
Result	✓ Passed
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	





MOT #	21 20	21-12-17 07:53
MOT te	est number	824652124019
Result		🗙 Failed
Fail is 1.0m	Nearside Rear Tyre tread pattern not visible over the whole tread area when minimum onm (5.2.3 (e))	depth required
Fail	Nearside Position lamp not working (4.2.1 (a) (ii))	
Fail	Front Anti-roll bar pin or bush excessively worn both sides (5.3.4 (a) (i))	
Fail	Front Inner Track rod end ball joint has excessive play both sides (2.1.3 (b) (i))	
Fail	Headlamp not working on dipped beam both sides (4.1.1 (a) (ii))	
Advid	ce Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail	Headlamp has a product on the lens so that the light output is severely reduced both sig	des (4.1.4 (b))
Fail	Rear Lower Suspension arm pin or bush excessively worn inner, front bush, both sides (5.3.4 (a) (i))

MOT #20		2021-01-30 11:44
MOT test	number	944244399602
Result		✓ Passed
Advice	Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))	
Advice	Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))	

MOT #19	2021-01-21 10:12
MOT test number	762166787457
Result	🗙 Failed
Minor Trailer electrical socket insecure (4.10 (a) (i))	
Advice Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))	
Fail Central Brake pipe leaking on a hydraulic braking system (1.1.11 (b) (ii))	
Fail Central Brake pipe excessively corroded (1.1.11 (c))	
Advice Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))	





MOT #18	2019-07-12 11:00
MOT test number	183818842623
Result	✓ Passed
MOT #17	2018-07-21 12:22
MOT test number	564444018640
Result	✓ Passed
Advice Engine covers fitted obscuring view	

Advice Undertray fitted obscuring view

MOT #16		2017-07-22 13:19
MOT test i	number	265595367703
Result		🗸 Passed
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1d)	
Advice	Engine covers fitted obscuring view	
Advice	Undertray fitted obscuring view	

MOT #15	2016-07-22 11:17
MOT test	number 455085750733
Result	✓ Passed
Advice	Offside Front Lower Suspension arm has slight play in a ball joint most forward arm (2.4.G.2)
Advice	Nearside Front Suspension arm has slight play in a ball joint most forward arm (2.4.G.2)

MOT #14	2015-11-30 14:55	
MOT test	number 766269271758	1
Result	✓ Passed	ł
Advice (2.4.G.2)	Anti-roll bar rubber mounting deteriorated but not resulting in excessive movement both front	
Advice	O/s handbrake down on efficiency	





MOT #13	2015-11-21 10:18	
MOT test number	153430539834	
Result	🗙 Failed	
Fail Anti-roll bar linkage ball joint dust cover excessively damaged so that it n ingress of dirt both front (2.4.G.2)	o longer prevents the	
Fail Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)		
Advice Anti-roll bar rubber mounting deteriorated but not resulting in excessive movement both front (2.4.G.2)		
Advice O/s handbrake down on efficiency		

MOT #12	2014-11-14 15:03
MOT test number	828608114347
Result	✓ Passed
Notice Under-trays fitted obscuring some underside components	

MOT #11		2014-11-14 10:45
MOT test	number	568398614378
Result		🗙 Failed
Notice	Strong advise nearside rear tyre is on legal limit of 1.6mm	
Notice	Under-trays fitted obscuring some underside components	
Fail 0	ffside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Notice	Both rear tyres wearing in centre of tread	
Notice	Vehicle's internal headlight adjuster altered to recheck lights	

MOT #10	2013-11-22 11:42
MOT test number	258246323371
Result	✓ Passed



MOT #	9	2013-11-18 16:35
MOT te	est number	378092223303
Result		🗙 Failed
Fail	Offside front brake excessively fluctuating (3.7.B.3)	
Fail	Nearside front brake excessively fluctuating (3.7.B.3)	

MOT #8		2012-11-23 17:04
MOT test	number	907828522304
Result		✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	Under body cover fitted	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #7	2011-11-04 15:56
MOT test number	946468601341
Result	✓ Passed

MOT #6	2010-10-27 14:03
MOT test number	674870000321
Result	✓ Passed
Advice Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)	

MOT #5	2010-08-23 11:55
MOT test number	181645230253
Result	✓ Passed

MOT #4	2009-10-09 12:04
MOT test number	690602889219
Result	✓ Passed

VN54JRU

report date: 2024-03-29





MOT #3	2009-10-06 12:47
MOT test number	532559679256
Result	🗙 Failed
FailNearside Rear Tyre has ply or cords exposed (4.1.D.1b)AdviceOffside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #2	2008-10-06 10:05
MOT test number	870840988233
Result	✓ Passed
Advice Nearside Front Anti-roll bar rubber mounting deteriorated but not removement (2.4.G.2)	sulting in excessive
MOT #1	2007-09-24 17:13
MOT test number	253307667230
Result	✓ Passed
Notice Nail in nearside front tyre	



Tax & MOT check

✓ Taxed Tax due: 1 January 2025	✓ MOT Expires: 20 December 2024
Tax status	Valid until 1 January
Days left	248
MOT expiry date	20 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	К
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-





Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lashe
Туре	
Damage 2	AMPLE
Damage 2	E CUT D
Date	 *
Category	 amer
Туре	

Extra BMW salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

	More info >
Plate changes	
See in this check if this BMW had different number plate	S.
Number of plates	
Current registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2004-11-25
Last registration	2023-11-22
Complete history	See info



Registration #1	2004-11-25	25 mi
Registration #2	2007-09-24	31.471 mi
Registration #3	2008-10-06	41.442 mi
Registration #4	2009-10-06	54.593 mi
Registration #5	2009-10-09	54.633 mi
Registration #6	2010-08-23	64.103 mi
Registration #7	2010-10-27	64.138 mi
Registration #8	2011-11-04	71.783 mi
Registration #9	2012-11-23	79.724 mi
Registration #10	2013-11-18	86.856 mi
Registration #11	2013-11-22	86.897 mi
Registration #12	2014-11-14	94.704 mi
Registration #13	2014-11-14	94.708 mi
Registration #14		11.777 est
Registration #15		11.777 est
Registration #16		11.777 est
Registration #17		11.777 est
Registration #18		11.777 est
Registration #19		11.777 est
Registration #20		11.777 est
Registration #21		11.777 esi
Registration #22		11.777 est
Registration #23		11.777 est
Registration #24		11.777 mi
Registration #25		11.777 mi
Registration #26		11.777 est
CarCheck co.uk		nage 14/15

CarCheck.co.uk

More info >





Car features

S0225	Air conditioning
\$0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1846 mm
Height	1491 mm
Length	4843 mm
Wheel base	2886 mm
Kerb weight	2300 kg
Max. allowed weight	2300 kg
Additional information	
Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 15/15