



SA63BZS

report date: 2024-03-28

General information

Make	SUZUKI
Model	SX4 SZ3
Colour	Silver
Year of manufacture	2013
Top speed	115 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	156 Nm at 4.400 rpm
Engine capacity	1.586 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	45.6 mpg
CO2 emission	141 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-02-04
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-05-16
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	15
Total items failed	0

MOT #9	2023-05-09 09:44
MOT test number	487468511462
Result	✓ Passed
Next expiry date	2024-05-16
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	General corrosion to front subframe and rear axle

MOT #8	2022-05-17 07:51
MOT test number	124328667100
Result	✓ Passed
Advice	OSR tyre cracking
Advice	Rear brake discs corroding and pads worn
Advice	All brake hoses corroding at ends

MOT #7	2021-05-10 08:58
MOT test number	543671167987
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing surface cracking/perishing (5.2.3 (d) (ii))

**MOT #6** 2020-11-05 13:09**MOT test number** 253066877350**Result** ✓ Passed**Advice** Rear Brake pipe corroded, covered in grease or other material both (1.1.11 (c))**MOT #5** 2020-11-05 09:44**MOT test number** 580447461272**Result** ✗ Failed**Advice** Rear Brake pipe corroded, covered in grease or other material both (1.1.11 (c))**MAJOR** Front Brake pipe excessively corroded both (1.1.11 (c))**MAJOR** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #4** 2019-11-22 12:47**MOT test number** 885510505492**Result** ✓ Passed**MOT #3** 2018-12-28 13:51**MOT test number** 583831650070**Result** ✓ Passed**Advice** Brake fluid close to minimum mark (1.1.10 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing cracking between tread (5.2.3 (d) (ii))**Advice** Nearside Front Oil leak, but not excessive slight leak at gearbox (8.4.1 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))**MOT #2** 2017-09-25 15:18**MOT test number** 350920185649**Result** ✓ Passed**Advice** Offside Rear Tyre slightly perished and cracked between treads



MOT #1	2016-09-01 09:17
MOT test number	930717455223
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 May 2025

✓
MOT

Expires:
16 May 2024

Tax status	Valid until 1 May
Days left	368
MOT expiry date	16 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	 
Plate since	2019-09-29
Current registration	 
Plate since	2019-09-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2013-09-27
Last registration	2023-05-09
Complete history	See info



Registration #1	2013-09-27	12 mi
Registration #2	2016-09-01	40.614 mi
Registration #3	2017-09-25	49.660 mi
Registration #4	2018-12-28	63.298 mi
Registration #5	2019-11-22	71.441 mi
Registration #6	2020-11-05	76.764 mi
Registration #7	2020-11-05	76.764 mi
Registration #8	2020-11-05	76.764 mi
Registration #9	2020-11-05	76.764 mi
Registration #10	2020-11-05	76.764 mi
Registration #11	2020-11-05	76.764 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1755 mm
Height	1620 mm
Length	4235 mm
Wheel base	2500 mm
Kerb weight	1240 kg
Max. allowed weight	1650 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	M16A-1674084