



report date: 2024-03-29

General information

Make	BMW
Model	530 530D M SPORT GRAN TURISMO
Colour	Grey
Year of manufacture	2015
Top speed	152 mph
0 - 60 mph	6.2 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	255 BHP
Max. torque	560 Nm at 1.500 rpm
Engine capacity	2.993 cc
Cylinders	6
Fuel type	Diesel
Consumption city	41.5 mpg
Consumption extra urban	54.3 mpg
Consumption combined	48.7 mpg
CO2 emission	153 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-11-06
Pictures	49
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-04-08
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	11
Total items failed	2

MOT #9	2024-04-03 16:00
MOT test number	663383902330
Result	✓ Passed
Next expiry date	2025-04-08

MOT #8	2023-03-14 17:49
MOT test number	549200423726
Result	✓ Passed
Advice	Rear Tyre wheel/tyre protruding beyond wheel arch both osr/nsr (5.2.3 (f))
Advice	Rear parking brake weak requirements just met
Advice	Front Tyre wheel/tyre protruding beyond wheel arch both osf/nsf (5.2.3 (f))

MOT #7	2022-04-09 11:45
MOT test number	527082978783
Result	✓ Passed

MOT #6	2021-02-19 17:55
MOT test number	399423509879
Result	✓ Passed
Advice	Nearside Rear Nail in tyre
Minor	Nearside Front Side repeater lens defective which has no effect on emitted light side repeater lens cracked (4.4.1 (b) (i))

**MOT #5** 2021-02-10 17:32**MOT test number** 939057580462**Result** ✗ Failed**Fail** Rear Lower Boot lid cannot be secured in the closed position boot lid opening on its own during MOT test (6.2.1 (e))**Advice** Nearside Rear Nail in tyre**Minor** Nearside Front Side repeater lens defective which has no effect on emitted light side repeater lens cracked (4.4.1 (b) (i))**MOT #4** 2020-02-10 14:58**MOT test number** 136475401834**Result** ✓ Passed**Advice** Nearside Non obligatory mirror damaged**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement leading both (5.3.4 (a) (i))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #3** 2018-11-19 20:29**MOT test number** 713779101637**Result** ✓ Passed**MOT #2** 2018-11-16 01:43**MOT test number** 110994771135**Result** ✗ Failed**Fail** Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MOT #1** 2018-02-24 10:31**MOT test number** 487966306667**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
8 April 2025

Tax status	Valid until 1 May
Days left	366
MOT expiry date	8 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this BMW had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-02-27
Last registration	2024-04-03
Complete history	See info



Registration #1	2015-02-27	10 mi
Registration #2	2018-02-24	7.010 mi
Registration #3	2018-11-16	7.862 mi
Registration #4	2018-11-19	7.862 mi
Registration #5	2020-02-10	17.662 mi
Registration #6	2021-02-10	31.968 mi
Registration #7	2022-05-20	35.277 mi
Registration #8	2022-05-20	35.277 mi
Registration #9	2022-05-20	35.277 mi
Registration #10	2022-05-20	35.277 mi
Registration #11	2024-04-03	35.277 mi

More info >



Car features

The BMW factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete BMW factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1901 mm
Height	1559 mm
Length	5004 mm
Wheel base	3070 mm
Kerb weight	1940 kg
Max. allowed weight	2570 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	34519107