



MK59SOJ

report date: 2024-03-28

General information

Make	FIAT
Model	GRANDE PUNTO ACTIVE
Colour	Black
Year of manufacture	2009
Top speed	103 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-09-14
Pictures	28
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2023-10-22
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	18
Total items failed	10

MOT #15	2022-10-22 10:20
MOT test number	299403236936
Result	✓ Passed
Next expiry date	2023-10-22

MOT #14	2022-10-20 13:14
MOT test number	216333265010
Result	✗ Failed
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #13	2021-10-08 10:34
MOT test number	499509790066
Result	✓ Passed
Advice	Oil leak - sump plug
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12** 2021-10-08 10:34**MOT test number** 220693753621**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Oil leak - sump plug**MOT #11** 2020-10-23 14:31**MOT test number** 991480922435**Result** ✓ Passed**MOT #10** 2020-10-23 09:50**MOT test number** 800289638899**Result** ✗ Failed**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #9** 2019-10-08 14:10**MOT test number** 416731019303**Result** ✓ Passed

**MOT #8**

2019-10-08 08:48

MOT test number

658479699775

Result

✗ Failed

Advice

Wheel alignment req checking due to both front tyres wearing on the inner edge

Pass with rectification

Nearside Headlamp aim too low and too far to the right. (4.1.2 (a))

Fail

Offside Front Position lamp not working (4.2.1 (a) (ii))

Fail

Nearside Front Tyre has ply or cords exposed 175/65/15 (5.2.3 (d) (ii))

Pass with rectification

Windscreen washer not working (3.5 (a))

Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice

Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. 24% (1.2.1 (b) (i))

Fail

Nearside Front Position lamp not working (4.2.1 (a) (ii))

Pass with rectification

Offside Headlamp aim too low and too far to the right. (4.1.2 (a))

Fail

Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice

Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. 28% (1.2.1 (b) (i))

MOT #7

2018-09-20 11:58

MOT test number

903717385407

Result

✓ Passed

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6

2017-10-13 13:15

MOT test number

864065538447

Result

✓ Passed

**MOT #5** 2016-10-19 09:51**MOT test number** 137189348095**Result** ✓ Passed**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2015-09-28 15:47**MOT test number** 850232640172**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit *** 1.62mm *** (4.1.E.1)**MOT #3** 2014-09-01 13:53**MOT test number** 348414144229**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Exhaust backbox corroded**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2013-04-25 17:07**MOT test number** 255975213427**Result** ✓ Passed**MOT #1** 2012-09-12 11:41**MOT test number** 149466152282**Result** ✓ Passed**Notice** Child seat fitted to offside rear, seat belt not checked**Advice** Nearside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)



Tax & MOT check

✕
Untaxed

Tax expired:
12 November 2023

✕
MOT

Expired:
22 October 2023

Tax status	Expired at 12 November 2023
Days left	168 days too late
MOT expiry date	22 October 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-09-14
Last registration	2022-10-22
Complete history	See info



Registration #1	2009-09-14	26 mi
Registration #2	2012-09-12	16.173 mi
Registration #3	2013-04-25	19.801 mi
Registration #4	2014-09-01	24.935 mi
Registration #5	2015-09-28	32.183 mi
Registration #6	2016-10-19	40.546 mi
Registration #7	2017-10-13	42.557 mi
Registration #8	2018-09-20	50.123 mi
Registration #9	2019-10-08	64.082 mi
Registration #10	2020-05-20	75.377 mi
Registration #11	2020-05-20	75.377 mi
Registration #12	2020-05-20	75.377 mi
Registration #13	2020-05-20	75.377 mi
Registration #14	2020-05-20	75.377 mi
Registration #15	2020-05-20	75.377 mi
Registration #16	2020-05-20	75.377 mi
Registration #17	2020-05-20	75.377 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9519694