





### General information

| Make                | VOLKSWAGEN                          |
|---------------------|-------------------------------------|
| Model               | PASSAT GT TDI BLUEMOTION TECHNOLOGY |
| Colour              | Black                               |
| Year of manufacture | 2018                                |
| Top speed           | 137 mph                             |
| Gearbox             | 6 speed Manual                      |

## Engine & fuel consumption

| Power                   | 148 BHP             |
|-------------------------|---------------------|
| Max. torque             | 340 Nm at 1.750 rpm |
| Engine capacity         | 1.968 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 58.9 mpg            |
| Consumption extra urban | 74.3 mpg            |
| Consumption combined    | 68.9 mpg            |
| CO2 emission            | 112 g/km            |
| CO2 label               | С                   |






## Internet history

| Entry 1       |             |
|---------------|-------------|
| Date          | 2021-06-06  |
| Pictures      | 19          |
| Listing price | View report |









source: yesauto.com



## MOT history

| MOT expiry date    | 2025-03-05 |
|--------------------|------------|
| MOT pass rate      | 100 %      |
| MOT passed         | 4          |
| Failed MOT tests   | 0          |
| Total advice items | 2          |
| Total items failed | 0          |

| MOT #4    |  | 2024-02-22 10:00 |
|-----------|--|------------------|
| MOT test  | number   | 150393843464     |
| Result    |  | ✓ Passed         |
| Next expi | ry date  | 2025-03-05       |
| Advice    | Offside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))  |                  |
| Advice    | Nearside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |                  |

| MOT #3          | 2023-02-08 10:51 |
|-----------------|------------------|
| MOT test number | 979771810078     |
| Result          | ✓ Passed         |
|                 |                  |
| MOT #2          | 2022-03-01 16:23 |
| MOT test number | 542763177888     |
| Result          | ✓ Passed         |
|                 |                  |
| MOT #1          | 2021-03-06 03:05 |
| MOT test number | 685703495638     |
| Result          | ✓ Passed         |



Tax & MOT check

| √<br>Taxed                     | I |                          | ✓<br>MOT           |
|--------------------------------|---|--------------------------|--------------------|
| <b>Tax due:</b><br>1 June 2024 |   | Expires:<br>5 March 2025 |                    |
| Tax status                     |   |                          | Valid until 1 June |
| Days left                      |   |                          | 32                 |
| MOT expiry date                |   |                          | 5 March 2025       |
| Full MOT history               |   |                          | See MOT history    |

### Tax calculation

| Vehicle class  | 49         |
|--|------------|
| Band   | G          |
| First licence fee (12 months)                        | £ 210,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 255,00,- |
| Standard rate (12 months)                            | £ 180,00,- |
| Standard rate (6 months)                             | £ 99,00,-  |
| Premium rate (12 months)                             | £ 570,00,- |
| Premium rate (6 months)                              | £ 313,50,- |





#### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |        |
|----------|--------|
| Date     | FETTOR |
| Category | Lamp   |
| Туре     |        |
| Damage 2 | AMPLE  |
| Date     |        |
| Date     | OLE .  |
| Category | AM     |
| Туре     |        |

#### Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value          | 4 10.700 |
|-----------------------------|----------|
| Auction value               | 4 10.000 |
| Average private trade value | 4 10 700 |





### Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ***********  |             |
|--|-------------|
| *********  |             |
|  |             |
|  |             |
| **********   |             |
| NUMBER OF CONTRACTOR OF CONTRA |             |
|  |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this VOLKSWAGEN had different number plates.  |             |
| Number of plates   |             |
| Current registration   |             |
| Plate since  |             |
| Current registration   |             |
| Reds sizes   |             |
|  |             |





#### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |





## Mileage check

| Odometer                   | In miles        |
|----------------------------|-----------------|
| Mileage registrations      | 6               |
| First mileage registration | 2018-02-12      |
| Last registration          | 2024-02-22      |
| Complete history           | <u>See info</u> |



| Registration #1 | 2018-02-12 | 26 mi      |
|-----------------|------------|------------|
| Registration #2 | 2021-03-06 | 17.522 mi  |
| Registration #3 |            | 11.777 mi  |
| Registration #4 |            | 11.777 esi |
| Registration #5 |            | 11.777 mi  |
| Registration #6 |            | 11.117 esi |





### Car features

| S0225  | Air conditioning |
|--------|------------------|
| S0295  |                  |
| 50482  |                  |
| \$0501 |                  |
| S0566  |                  |
| S0567  |                  |
| S0569  |                  |

# Safety ratings

| NCAP rating    | ***             |
|----------------|-----------------|
| Adult          | 85%             |
| Children       | 87%             |
| Pedestrian     | 66%             |
| Safety systems | 76%             |
| Overall rating | 80%             |
| Video          | see crash video |



| Dimensions & weight    |                  |
|------------------------|------------------|
| Width                  | 1832 mm          |
| Height                 | 1456 mm          |
| Length                 | 4767 mm          |
| Wheel base             | 2712 mm          |
| Kerb weight            | 1475 kg          |
| Max. allowed weight    | 2020 kg          |
| Additional information |                  |
| Fuel tank capacity     | 66 I             |
| Fuel delivery          | Direct Injection |
| Number of doors        | 4                |
| CarCheck.co.uk         | page 10/1        |

| Number of seats | 5          |
|-----------------|------------|
| Number of axles | 2          |
| Engine number   | DFGA455698 |