





report date: 2024-03-29

General information

Make	NISSAN
Model	PULSAR TEKNA DIG-T XTRONIC
Colour	White
Year of manufacture	2016
Top speed	115 mph
0 - 60 mph	12.7 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	115 BHP
Max. torque	165 Nm at 1.750 rpm
Engine capacity	1.198 сс
Cylinders	4
Fuel type	Petrol
Consumption city	45.6 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-29


Internet history

Entry 2

Date 2021-10-25

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 1

Date	2021-10-09
Pictures	0
Listing price	View report

source: heycar.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

MOT expiry date	2024-10-18
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	8
Total items failed	9

MOT #8	2023-10-17 15:23
MOT test number	972263218880
Result	✓ Passed
Next expiry date	2024-10-18
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #7	2023-10-16 17:41
MOT test number	964075206827
Result	X Failed
Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	

MOT #6	2022-10-18 14:11
MOT test number	282257202899
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #5 2022-10-14 14:02

MOT test number 205058998651

Result X Failed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Fail Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4 2021-10-19 15:21

MOT test number 872065481902

Result ✓ Passed

MOT #3 2020-12-16 16:15

MOT test number 947967158415

Result \(\sqrt{Passed} \)

Advice Front tyres badly worn edges

MOT #2 2020-12-16 09:56

MOT test number 276697729047

Result X Failed

Fail Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #1 2019-12-20 16:02

MOT test number 586807487823

CarCheck.co.uk page 5/12



CA66GRX report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 December
Days left	215
MOT expiry date	18 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



CA66GRX report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

^ -		histor	-
- () ()	vnor	nictor	٦.
\smile	VIICI	пизсоп	·v

For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full re	

THE PARTY OF THE P	

	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Current registration	NK AN
Plate since	
Current registration	NK NE
Plate since	
	More info >

CarCheck.co.uk page 9/12



CA66GRX report date: 2024-03-29

Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-12-08
Last registration	2023-10-17
Complete history	See info



Registration #1	2016-12-08	7 mi
Registration #2	2019-12-20	24.298 mi
Registration #3	2020-12-16	27.138 mi
Registration #4	2020-12-16	27.138 mi
Registration #5		11.777 es
Registration #6	2021-10-19	30.344 mi
Registration #7		11.777 es
Registration #8		11.777 ea
Registration #9		0.77 ss
Registration #10		71.777 66
Registration #11		10,777 mg

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
S0566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	84%
Children	81%
Pedestrian	75%
Safety systems	68%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1768 mm
Height	1520 mm
Length	4387 mm
Wheel base	2700 mm
Kerb weight	1318 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	46 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12

Number of axles 2

Engine number 254452A