





General information

| Make | VOLVO |
|---------------------|----------------|
| Model | C30 R-DESIGN |
| Colour | Black |
| Year of manufacture | 2010 |
| Top speed | 115 mph |
| 0 - 60 mph | 11.2 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 100 BHP |
|-------------------------|---------------------|
| Max. torque | 150 Nm at 4.000 rpm |
| Engine capacity | 1.596 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 30.4 mpg |
| Consumption extra urban | 49.6 mpg |
| Consumption combined | 40.4 mpg |
| CO2 emission | 167 g/km |
| CO2 label | Н |







Internet history

| Entry 2 | |
|---------------|-------------|
| Date | 2022-07-20 |
| Pictures | 19 |
| Listing price | View report |



source: cargurus.co.uk

| Entry 1 | |
|---------------|-------------|
| Date | 2021-07-16 |
| Pictures | 2 |
| Listing price | View report |
| | |



source: autotrader.co.uk





MOT history

| MOT expiry date | 2024-08-22 |
|--------------------|------------|
| MOT pass rate | 80 % |
| MOT passed | 12 |
| Failed MOT tests | 3 |
| Total advice items | 4 |
| Total items failed | 4 |

| MOT #15 | 2023-08-23 10:03 |
|------------------|------------------|
| MOT test number | 742203295372 |
| Result | ✓ Passed |
| Next expiry date | 2024-08-22 |

| MOT #14 | 2022-07-25 09:12 |
|-----------------|------------------|
| MOT test number | 270802249413 |
| Result | ✓ Passed |

| MOT #13 | 2022-04-26 14:12 |
|-----------------|------------------|
| MOT test number | 439013599010 |
| Result | ✓ Passed |

| MOT #12 | 2022-04-26 13:31 |
|---|-------------------------------|
| MOT test number | 315206887673 |
| Result | 🗙 Failed |
| Fail Nearside Front Steering rack gaiter missing or no longer prevents the ing | ress of dirt (2.1.3 (g) (ii)) |

| MOT #11 | 2021-03-31 08:34 |
|-----------------|------------------|
| MOT test number | 378773493966 |
| Result | ✓ Passed |





| MOT #10 | | 2021-03-31 08:34 |
|-------------------------|---|------------------|
| MOT test number | | 763035721693 |
| Result | | 🗙 Failed |
| Pass with rectification | Offside Front Position lamp not working (4.2.1 (a) (ii)) | |
| Pass with rectification | Nearside Front Position lamp not working (4.2.1 (a) (ii)) | |

| MOT #9 | 2020-04-30 09:28 |
|--|------------------|
| MOT test number | 525140727713 |
| Result | Passed |
| Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #8 | 2019-04-17 07:47 |
|--|------------------|
| MOT test number | 726995518828 |
| Result | ✓ Passed |
| Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #7 | 2018-04-07 07:56 |
|-----------------|------------------|
| MOT test number | 653588795044 |
| Result | ✓ Passed |

| МОТ #6 | 2017-04-11 07:33 |
|-----------------|------------------|
| MOT test number | 126685940067 |
| Result | ✓ Passed |

| MOT #5 | | 2017-04-11 07:33 |
|-------------------------|-------------------------------------|------------------|
| MOT test number | | 781323324096 |
| Result | | 🗙 Failed |
| Pass with rectification | Nearside Headlamp aim too low (1.8) | |



| YH10VEV | |
|-------------------------|---|
| report date: 2024-03-28 | ; |

| MOT #4 | 2016-04-11 11:00 |
|--|------------------|
| MOT test number | 678461068273 |
| Result | ✓ Passed |
| Advice Front tyres are wearing on inner edge | |
| Advice Rear brake pads are getting low | |
| | |
| MOT #3 | 2015-04-13 09:54 |
| MOT test number | 409443205135 |
| Result | ✓ Passed |
| | |
| MOT #2 | 2014-04-22 11:46 |
| MOT test number | 796442914143 |
| Result | Passed |
| | |
| MOT #1 | 2013-04-29 13:25 |
| MOT test number | 785889413111 |
| Result | ✓ Passed |
| | |



Tax & MOT check

| √ Taxed | √ мот |
|--------------------------|----------------------------|
| Tax due: 1 April 2025 | Expires: 22 August 2024 |
| Tax status | Valid until 1 April |
| Days left | 338 |
| MOT expiry date | 22 August 2024 |
| Full MOT history | <u>See MOT history</u> |

Tax calculation

| Vehicle class | 48 |
|---|------------|
| Band | н |
| Single payment (12 months) | £ 290,00,- |
| Single six month payment | £ 159,50,- |
| Total payable by 12 monthly instalments | £ 304,50,- |





Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|----------|
| Date | FEIDO |
| Category | 4 ARAPE |
| Туре | |
| Damage 2 | AMPL |
| | F Stores |
| Date | 1.E |
| Category | ante |
| Туре | |

Extra VOLVO salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4.00.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ****** | |
|--|-------------|
| *********** | |
| ******* | |
| ****** | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this VOLVO had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 18 |
| First mileage registration | 2010-05-04 |
| Last registration | 2023-08-23 |
| Complete history | See info |



| Registration #1 | 2010-05-04 | 21 mi |
|------------------|------------|------------|
| Registration #2 | 2013-04-29 | 21.896 mi |
| Registration #3 | 2014-04-22 | 28.034 mi |
| Registration #4 | 2015-04-13 | 34.126 mi |
| Registration #5 | 2016-04-11 | 40.248 mi |
| Registration #6 | 2017-04-11 | 52.135 mi |
| Registration #7 | 2017-04-11 | 52.135 mi |
| Registration #8 | 2018-04-07 | 62.237 mi |
| Registration #9 | 2019-04-17 | 71.359 mi |
| Registration #10 | | 11.777 est |
| Registration #11 | | 11.777 est |
| Registration #12 | | 11.777 est |
| Registration #13 | | 11.777 esi |
| Registration #14 | | 11.777 est |
| Registration #15 | | 11.777 est |
| Registration #16 | | 11.777 est |
| Registration #17 | | 11.777 mi |
| Registration #18 | | 11.117 est |





Car features

| S0225 | Air conditioning |
|--------|------------------|
| \$0295 | |
| 50482 | |
| \$0501 | |
| \$0566 | |
| \$0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 91% |
| Children | 78% |
| Pedestrian | 26% |
| Safety systems | 71% |
| Overall rating | 73% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|-----------------------|
| Width | 1782 mm |
| Height | 1447 mm |
| Length | 4252 mm |
| Wheel base | 2640 mm |
| Kerb weight | 1299 kg |
| Max. allowed weight | 1700 kg |
| Additional information | |
| Fuel tank capacity | 55 I |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 3 |
| Number of seats CarCheck.co.uk | 4 page 12/12 |

| Number of axles | 2 |
|-----------------|--------|
| Engine number | 181935 |