



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 SPORT D V50
Colour	Blue
Year of manufacture	2009
Top speed	127 mph
0 - 60 mph	9.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	49.6 mpg
CO2 emission	153 g/km
CO2 label	G





Internet history

Entry 1

Date	2022-01-29
Pictures	8
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-06
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	33
Total items failed	11

MOT #19	2024-01-18 14:23
MOT test number	719888665626
Result	✓ Passed
Next expiry date	2025-02-06
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #18	2024-01-17 13:59
MOT test number	222985846507
Result	✗ Failed
Fail	Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Fail	Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #17	2023-01-31 11:18
MOT test number	421484198492
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #16** 2022-02-07 17:30**MOT test number** 454543143715**Result** ✓ Passed**MOT #15** 2022-02-03 11:29**MOT test number** 778073351032**Result** ✗ Failed

- Fail** Front Brakes imbalanced across an axle by more than 50% Axle 1 (1.2.1 (b) (ii))
- Fail** Offside Front Service brake excessively binding (1.2.1 (f))
- Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #14 2022-01-08 12:05**MOT test number** 468226215530**Result** ✓ Passed

- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Front Headlamp has less than 1/2 LEDs not functioning (4.1.1 (a) (i))
- Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Hand brake has slight travel

MOT #13 2021-01-11 16:08**MOT test number** 865955052647**Result** ✓ Passed

**MOT #12** 2020-01-10 15:54**MOT test number** 454984313698**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2019-01-14 12:02**MOT test number** 467815894367**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Engine covers and under shields fitted not allowing full inspection**MOT #10** 2018-01-24 13:14**MOT test number** 353863432685**Result** ✓ Passed**Advice** Shields and undertrays fitted not allowing full inspection**MOT #9** 2018-01-24 11:47**MOT test number** 414938759510**Result** ✗ Failed**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Shields and undertrays fitted not allowing full inspection**Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #8** 2017-02-08 08:49**MOT test number** 536611276616**Result** ✓ Passed**Advice** Shields and undertrays fitted not allowing full inspection

**MOT #7** 2017-02-07 10:26**MOT test number** 951988923770**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit and worn on inner edge (4.1.E.1)**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Shields and undertrays fitted not allowing full inspection**Advice** Offside Front Tyre worn close to the legal limit and worn on inner edge (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Parking brake lever has no reserve travel (3.1.6b)**Advice** Offside Rear Direction Indicator slightly discoloured (1.4.A.2f)**MOT #6** 2016-02-10 12:08**MOT test number** 678101261307**Result** ✓ Passed**MOT #5** 2015-02-10 09:49**MOT test number** 147611445094**Result** ✓ Passed



MOT #4 2014-02-20 09:56

MOT test number 429851554067

Result ✓ Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2014-02-20 09:56

MOT test number 906011754027

Result ✗ Failed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification Offside Rear Stop lamp not working (1.2.1b)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2013-02-13 11:18

MOT test number 206334543017

Result ✓ Passed

MOT #1 2012-02-15 15:22

MOT test number 795966942047

Result ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
6 February 2025

Tax status	Valid until 1 February
Days left	278
MOT expiry date	6 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	NL09DHE
Plate since	2019-09-29
Current registration	NL09DHE
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-03-04
Last registration	2024-01-18
Complete history	See info



Registration #1	2009-03-04	17 mi
Registration #2	2012-02-15	25.848 mi
Registration #3	2013-02-13	29.476 mi
Registration #4	2014-02-20	33.081 mi
Registration #5	2015-02-10	37.183 mi
Registration #6	2016-02-10	41.796 mi
Registration #7	2017-02-07	51.760 mi
Registration #8	2017-02-08	51.760 mi
Registration #9	2018-01-24	58.995 mi
Registration #10	2018-01-24	58.995 mi
Registration #11	2019-01-24	65.222 mi
Registration #12	2019-01-24	65.222 mi
Registration #13	2019-01-24	65.222 mi
Registration #14	2019-01-24	65.222 mi
Registration #15	2019-01-24	65.222 mi
Registration #16	2019-01-24	65.222 mi
Registration #17	2019-01-24	65.222 mi
Registration #18	2019-01-24	65.222 mi
Registration #19	2019-01-24	65.222 mi
Registration #20	2019-01-24	65.222 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1489 kg
Max. allowed weight	1960 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	521737