





report date: 2024-03-29

General information

Make	PEUGEOT
Model	107 ACTIVE
Colour	Black
Year of manufacture	2013
Top speed	100 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 сс
Cylinders	3
Fuel type	Petrol
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	А



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date 2021-07-07


Pictures 29

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

MOT history

MOT expiry date	2025-02-12
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	14
Total items failed	6

MOT #13		2024-02-06 16:03
MOT test	number	472871756294
Result		✓ Passed
Next expi	ry date	2025-02-12
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1	l.1.11 (c))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor	Indicator tell-tale inoperative (4.9.1 (a) (i))	
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material	(1.1.11 (c))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 155/65R14 (5	5.2.3 (e))

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #12 2024-02-05 09:16 **MOT** test number 617686610498 Result × Failed Fail Offside Headlamp aim too low (4.1.2 (a)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Offside Headlamp insecure (4.1.1 (c)) Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge 155/65R14 (5.2.3 (e)) Minor Indicator tell-tale inoperative (4.9.1 (a) (i)) Nearside Headlamp insecure (4.1.1 (c)) Fail **Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #11

MOT test number

992597179329

Result

Advice (i))

Advice (a) (i))

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (5.3.4 (a) (a) (i))

MOT #10		2023-02-10 11:01
MOT test number		462431963127
Result		X Failed
Pass with rectificatio	n Windscreen washer provides insu	fficient washer liquid (3.5 (a))
Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		
Advice Nearside From (a) (i))	nt Suspension arm pin or bush worn bu	ut not resulting in excessive movement (5.3.4

CarCheck.co.uk page 4/13



YB62DLU report date: 2024-03-29

MOT #9	2022-02-02 09:57

MOT test number 804428107275

MOT #8 2022-02-02 09:57

MOT test number 844111379626

Result × Failed

Pass with rectification Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #7 2021-01-26 09:09

MOT test number 849693063842

Result ✓ Passed

MOT #6 2020-01-25 09:26

MOT test number 567941596082

Result \(\sqrt{Passed} \)

MOT #5 2020-01-25 09:26

MOT test number 125912173250

Result X Failed

Pass with rectification Offside Headlamp aim too low (4.1.2 (a))

MOT #4 2019-01-26 08:59

MOT test number 643498498719

MOT #3 2018-02-03 09:00

MOT test number 446125681458

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #2	2017-02-04 11:15
MOT test number	373491585106
Result	✓ Passed
MOT #1	2016-02-06 08:56
MOT test number	132789553557
Result	✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



✓ MOT

Tax expired: 1 July 2022 **Expires:** 12 February 2025

Tax status	Expired at 1 July 2022
Days left	669 days too late
MOT expiry date	12 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 7/13



YB62DLU report date: 2024-03-29

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner	I-!
OWNER	nistory
	11136017

For how long did the current and previous owner(s) have this PEUGEOT? How many own have? Check it in the premium report and see all owner registrations. Download the full	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-02-13
Last registration	2024-02-06
Complete history	See info



Registration #1	2013-02-13	7 mi
Registration #2	2016-02-06	30.121 mi
Registration #3	2017-02-04	35.824 mi
Registration #4	2018-02-03	40.320 mi
Registration #5	2019-01-26	44.196 mi
Registration #6	2020-01-25	47.222 mi
Registration #7	2020-01-25	47.222 mi
Registration #8	2021-01-26	49.894 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		11.177 es

More info >

CarCheck.co.uk page 12/13



YB62DLU report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	68%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	66%
Video	see crash video



Dimensions & weight

Width	1855 mm
Height	1470 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	900 kg
Max. allowed weight	1180 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 13/13