





General information

Make	NISSAN
Model	LEAF ACENTA
Colour	Grey
Year of manufacture	2016
Top speed	87 mph
Gearbox	1 speed automatic

Engine & fuel consumption

Power	107 BHP	
Max. torque 254 Nm at 10.500 rpm		
Fuel type	Electricity	







Internet history

Entry 1	
Date	2021-09-07
Pictures	6
Listing price	View report









source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-16
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	11
Total items failed	3

MOT #8	2023-09-05 09:16
MOT test number	588989045693
Result	✓ Passed
Next expiry date 2024-09-1	
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	

МОТ #7	2023-09-01 11:08	
MOT test number	631814120426	
Result	🗙 Failed	
Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt		
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear most bush (5.3.4 (a) (i))		
Advice Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1	L.14 (a) (ii))	
Fail Front Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))		
Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		
Fail Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))		
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in exc rear most bush (5.3.4 (a) (i))	cessive movement	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		





MOT #6	2022-09-12 10:20
MOT test number	910689702459
Result	✓ Passed
MOT #5	2021-09-17 06:23
MOT test number	827739563637
Result	✓ Passed
МОТ #4	2021-02-19 13:42

MOT test	number 960419682799	
Result	✓ Passed	
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4	
Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		
Advice	Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #3	2020-03-06 13:56
MOT test number	117872160937
Result	✓ Passed
MOT #2	2019-09-02 09:44
MOT test number	373115933504
Result	✓ Passed
MOT #1	2019-09-02 08:38
MOT test number	848977711460
Result	🗙 Failed

Fail Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))



Tax & MOT check







Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

-
AMP
- A

Extra NISSAN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711

More info >





Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-09-30
Last registration	2023-09-05
Complete history	See info



Registration #1	2016-09-30	18 mi
Registration #2	2019-09-02	11.611 mi
Registration #3	2019-09-02	11.611 mi
Registration #4	2020-03-06	12.455 mi
Registration #5	2021-02-19	13.845 mi
Registration #6		11.777 est
Registration #7		11.177 esi
Registration #8		00.000 est
Registration #9		11.117 mi

More info >





Car features

S0225	Air conditioning
\$0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

Number of seats

Number of axles

NCAP rating	****
Adult	89%
Children	83%
Pedestrian	65%
Safety systems	84%
Overall rating	83%
Video	see crash video



Dimensions & weight	
Width	1770 mm
Height	1550 mm
Length	4445 mm
Wheel base	2700 mm
Kerb weight	1538 kg
Max. allowed weight	1945 kg
Additional information	
Fuel delivery	Not Applicable
Number of doors	5

5

2