



report date: 2024-03-29

General information

Make	VOLVO
Model	S40 D S
Colour	Grey
Year of manufacture	2010
Top speed	127 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	153 g/km
CO2 label	G





Internet history

Entry 1

Date	2022-05-02
Pictures	26
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-11-27
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	23
Total items failed	5

**MOT #16** 2023-11-28 16:56**MOT test number** 384350727043**Result** ✓ Passed**Next expiry date** 2024-11-27

- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Brake pedal wearing smooth (1.1.2 (c))
- Advice** Rear Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Front Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

**MOT #15** 2023-11-16 16:16**MOT test number** 526164384423**Result** ✗ Failed

- Advice** Rear Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Front Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Fail** Offside Rear Parking brake inoperative on one side (1.4.1 (a))

**MOT #14** 2022-11-02 10:30**MOT test number** 157625113203**Result** ✓ Passed**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #13** 2021-11-18 17:20**MOT test number** 583631073277**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #12** 2020-11-11 15:07**MOT test number** 597505499502**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Coil spring corroded both side (5.3.1 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #11** 2019-11-12 16:35**MOT test number** 893164125256**Result** ✓ Passed**MOT #10** 2018-11-06 14:03**MOT test number** 561834689756**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #9** 2017-11-02 16:35**MOT test number** 546971756141**Result** ✓ Passed**MOT #8** 2017-11-02 09:38**MOT test number** 441905841426**Result** ✗ Failed**Fail** Nearside Rear Anti-roll bar linkage fractured (2.4.G.1)**MOT #7** 2016-11-09 09:58**MOT test number** 988791479910**Result** ✓ Passed**Advice** Both front roll bar link balljoints, have slight play**Advice** Tread getting low on both front tyres**MOT #6** 2016-11-09 09:58**MOT test number** 223845991111**Result** ✗ Failed**Advice** Both front roll bar link balljoints, have slight play**Pass with rectification** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' camera on screen (8.3.1e)**Advice** Tread getting low on both front tyres**MOT #5** 2015-11-10 10:11**MOT test number** 717215620359**Result** ✓ Passed**MOT #4** 2014-10-21 11:30**MOT test number** 675464194239**Result** ✓ Passed



MOT #3	2013-11-15 11:34
MOT test number	769449013331
Result	✓ Passed

MOT #2	2013-11-14 16:58
MOT test number	477658913440
Result	✗ Failed
<div><div>Fail</div>Parking brake lever has no reserve travel (3.1.6b)</div>	

MOT #1	2012-12-21 10:18
MOT test number	155356752351
Result	✓ Passed
<div><div>Notice</div>Child seat fitted not allowing full inspection of adult belt</div>	



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
27 November 2024

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	32
<b>MOT expiry date</b>	27 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-09-29
Current registration	 *****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-02-13
Last registration	2023-11-28
Complete history	<a href="#">See info</a>



Registration #1	2010-02-13	24 mi
Registration #2	2012-12-21	34.945 mi
Registration #3	2013-11-14	37.524 mi
Registration #4	2013-11-15	37.524 mi
Registration #5	2014-10-21	43.019 mi
Registration #6	2015-11-10	66.618 mi
Registration #7	2016-11-09	78.742 mi
Registration #8	2016-11-09	78.742 mi
Registration #9	2017-11-02	90.339 mi
Registration #10	2018-05-29	95.377 mi
Registration #11	2018-05-29	95.377 mi
Registration #12	2018-05-29	95.377 mi
Registration #13	2018-05-29	95.377 mi
Registration #14	2018-05-29	95.377 mi
Registration #15	2018-05-29	95.377 mi
Registration #16	2018-05-29	95.377 mi
Registration #17	2018-05-29	95.377 mi
Registration #18	2018-05-29	95.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1446 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	667100