



T16MDW

report date: 2024-03-28

General information

Make	FORD
Model	TOURNEO 300 LIMITED TDCI
Colour	Black
Year of manufacture	2015
Top speed	98 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	92 kW / 125 HP / 123 BHP
Max. torque	350 Nm at 1.450 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	45.6 mpg
Consumption combined	42.2 mpg
CO2 emission	172 g/km
CO2 label	H





Internet history

Entry 1

Date	2022-05-07
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-26
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	33
Total items failed	0

MOT #9	2023-07-17 14:34
MOT test number	308778745463
Result	✓ Passed
Next expiry date	2024-07-26
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8**

2023-07-17 08:31

MOT test number

108232098847

Result**✗ Failed**

MAJOR Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MAJOR Nearside Brake pipe excessively corroded front to rear, rear section (1.1.11 (c))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))

MAJOR Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Exhaust has a major leak of exhaust gases (6.1.2 (a))

MOT #7

2022-07-23 10:53

MOT test number

972324720802

Result**✓ Passed**

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #6**

2021-07-24 09:15

MOT test number

356050467334

Result

✓ Passed

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #5**

2021-07-24 07:53

MOT test number

120025202091

Result

✗ Failed

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MAJOR** Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #4**

2020-07-27 09:20

MOT test number

926622195260

Result

✓ Passed

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**MOT #3**

2019-07-17 15:00

MOT test number

621857659023

Result

✓ Passed



MOT #2	2018-07-23 10:55
MOT test number	673836076396
Result	✓ Passed

MOT #1	2017-04-23 12:01
MOT test number	865371934028
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
26 July 2024

Tax status	Valid until 1 December
Days left	217
MOT expiry date	26 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-09-29
Current registration	 *****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-07-09
Last registration	2023-07-17
Complete history	See info



Registration #1	2015-07-09	22 mi
Registration #2	2017-04-23	42.964 mi
Registration #3	2018-07-23	55.370 mi
Registration #4	2019-07-17	64.075 mi
Registration #5	2020-07-27	74.687 mi
Registration #6	2021-07-24	90.223 mi
Registration #7	2022-05-20	105.759 mi
Registration #8	2022-05-20	121.295 mi
Registration #9	2022-05-20	136.831 mi
Registration #10	2022-05-20	152.367 mi
Registration #11	2023-07-17	167.903 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	85%
Pedestrian	62%
Safety systems	70%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2290 mm
Height	1976 mm
Length	5339 mm
Wheel base	3300 mm
Kerb weight	2171 kg
Max. allowed weight	3000 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	9
Number of axles	2

Engine number	FE56115
---------------	---------