





report date: 2024-03-29

General information

Make	KIA
Model	SORENTO CRDI KX-2
Colour	White
Year of manufacture	2014
Top speed	118 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	194 BHP
Max. torque	422 Nm at 2.500 rpm
Engine capacity	2.199 сс
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	155 g/km
CO2 label	G



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 2

Date	2022-01-24

Pictures 1

Listing price <u>View report</u>



source: autoonline.co.uk

Entry 1


Date	2021-12-10
Pictures	46

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2025-01-09
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	13
Total items failed	8

MOT #12	2024-01-08 09:46
MOT test number	265426925241
Result	✓ Passed
Next expiry date	2025-01-09

MOT #11		2023-01-04 09:42
MOT test	number	254184199021
Result		✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #10	2022-01-10 10:43
MOT test number	492288933219
Result	✓ Passed

MOT #9	2022-01-06 13:54
MOT test number	878674529116
Result	X Failed
Fail Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	
Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))	
Fail Offside Rear Seat belt not functioning as intended mid row seats (7.1.2 (c))	

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT test number

Result

Advice

Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT test number

Result

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

Pass with rectification Offside Rear Direction indicator not working (4.4.1 (a) (ii))

MOT #6

MOT test number

Result

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #5 2020-06-24 08:03 837449129379 **MOT** test number Result × Failed **Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Fail Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Fail Offside Front Tyre tread depth below requirements of 1.6mm plus tyre perished (5.2.3 (e)) Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #4	2019-05-15 08:43
MOT test number	866959375260
Result	✓ Passed
MOT #3	2018-05-16 12:54
MOT test number	602663051874
Result	✓ Passed
MOT #2	2018-05-16 08:59
MOT #2	2010-03-10 00:33
MOT test number	198816227299
MOT test number	198816227299
MOT test number Result	198816227299

MOT #1	2017-06-09 14:22
MOT test number	960193971308
Result	✓ Passed
Advice Slight wear on edges of both front tyres	

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	9 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report h		
THE PARTY OF THE P		

	More info	>
Plate changes		
See in this check if this KIA had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK N	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2014-06-10
Last registration	2024-01-08
Complete history	See info



Registration #1	2014-06-10	29 mi
Registration #2	2017-06-09	25.136 mi
Registration #3	2018-05-16	31.930 mi
Registration #4	2018-05-16	31.931 mi
Registration #5	2019-05-15	39.387 mi
Registration #6	2020-06-24	44.912 mi
Registration #7	2020-06-24	44.912 mi
Registration #8	2021-05-06	49.230 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 esi
Registration #12		11.777 es
Registration #13		91.777 esi
Registration #14		11.777 es
Registration #15		

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	87%
Children	84%
Pedestrian	44%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	1885 mm
Height	1700 mm
Length	4685 mm
Wheel base	2700 mm
Kerb weight	1891 kg
Max. allowed weight	2510 kg

Additional information

Fuel tank capacity	64 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 12/

Engine number

D4HBDH092511