





report date: 2024-03-28

General information

Make	HYUNDAI
Model	COUPE SE
Colour	Silver
Year of manufacture	2005
Top speed	124 mph
0 - 60 mph	10.6 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	141 BHP
Max. torque	186 Nm at 4.500 rpm
Engine capacity	1.975 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.7 mpg
Consumption extra urban	42.8 mpg
Consumption combined	33.2 mpg
CO2 emission	203 g/km
CO2 label	K



CarCheck.co.uk page 1/11



FL55NPE

report date: 2024-03-28

Internet history

Entry 2

Date 2021-11-14


Pictures 23

Listing price <u>View report</u>









source: yesauto.com

Entry 1


Date	2021-11-11

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-10-27
MOT pass rate	100 %
MOT passed	16
Failed MOT tests	0
Total advice items	12
Total items failed	0

MOT #16	2023-10-26 14:02
MOT test number	285048749670
Result	✓ Passed
Next expiry date	2024-10-27
Advice Offside Front wing slight corrosion	
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice Nearside Front wing slight corrosion	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #15	2022-10-21 12:19
MOT test number	786036299710
Result	✓ Passed
Advice Nearside Front wing at the lower fixing slight corrosion	

MOT #14	2021-10-26 10:38
MOT test number	385576013125
Result	✓ Passed
Advice All four shockers /coil springs various points of floor pan corroded	

CarCheck.co.uk page 3/11



MOT #13 2020-10-09 13:44

MOT test number 613459023537

Result ✓ Passed

Advice Exhaust system corroded / coil springs all four shockers corroded / various points of floor pan inner and out sill surface rust

MOT #12 2019-10-02 13:29

MOT test number 344504818971

Result
✓ Passed

Advice Rear exhaust box corroded

MOT #11 2018-10-24 12:25

MOT test number 969415336307

Result Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear rear exhaust box corroded

MOT #10 2017-10-02 15:10

MOT test number 972219785224

Result \(\sqrt{Passed} \)

MOT #9 2016-10-25 13:06

MOT test number 379287927611

Result \(\sqrt{Passed} \)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

MOT #8 2015-10-06 13:34

MOT test number 180533561475

CarCheck.co.uk page 4/11



MOT test number

Result

FL55NPE report date: 2024-03-28

693909479248

✓ Passed

MOT #7	2014-10-13 13:13
MOT test number	558906184206
Result	✓ Passed
MOT #6	2013-10-03 10:19
MOT test number	149126973253
Result	✓ Passed
MOT #5	2012-10-09 13:36
MOT test number	316303382221
Result	✓ Passed
MOT #4	2011-10-04 13:45
MOT test number	516397571284
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (3.5.1g)	
MOT #3	2010-10-01 11:29
MOT test number	224754870203
Result	✓ Passed
MOT #2	2009-10-06 15:06

MOT #1	2008-10-21 12:33
MOT test number	661935998200
Result	✓ Passed

CarCheck.co.uk page 5/11



Tax & MOT check



Tax status	Valid until 1 May
Days left	368
MOT expiry date	27 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 6/11



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/11



FL55NPE

report date: 2024-03-28

Owner	I-!
OWNER	nistory
	11136017

,		
For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full		NDAI

	More info	>
Plate changes		
See in this check if this HYUNDAI had different number plates.		
Number of plates		
Current registration	NE OK	
Plate since		0.00.00
Current registration	NIE NIE	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2005-10-27
Last registration	2023-10-26
Complete history	See info



Registration #1	2005-10-27	10 mi
Registration #2	2008-10-21	13.472 mi
Registration #3	2009-10-06	17.265 mi
Registration #4	2010-10-01	27.537 mi
Registration #5	2011-10-04	27.994 mi
Registration #6	2012-10-09	33.503 mi
Registration #7	2013-10-03	39.241 mi
Registration #8	2014-10-13	43.689 mi
Registration #9	2015-10-06	48.765 mi
Registration #10	2016-10-25	55.213 mi
Registration #11		11.177 es
Registration #12		11.117 es
Registration #13		11.177 es
Registration #14		11.117 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
50295	
60482	
60501	
60566	
60567	
60569	

Dimensions & weight

Width	1760 mm
Height	1330 mm
Length	4395 mm
Wheel base	2530 mm
Kerb weight	1412 kg
Max. allowed weight	1740 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	G4GC5273547

CarCheck.co.uk page 11/11