



report date: 2024-03-29

General information

Make	SUZUKI
Model	VITARA SZ5 DDIS ALLGRIP
Colour	Silver
Year of manufacture	2016
Top speed	112 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	70.6 mpg
Consumption combined	67.3 mpg
CO2 emission	111 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-06-18
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-06-28
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	9
Total items failed	6

MOT #10	2023-06-23 14:34
MOT test number	437514198442
Result	✓ Passed
Next expiry date	2024-06-28
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #9	2023-06-23 14:28
MOT test number	842214773914
Result	✗ Failed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Fail	Offside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #8	2022-06-15 09:39
MOT test number	879877309473
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7	2021-06-29 09:07
MOT test number	200666848699
Result	✓ Passed

**MOT #6** 2021-06-29 07:27**MOT test number** 559150301926**Result** ✗ Failed**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))**MOT #5** 2021-05-20 10:55**MOT test number** 943652724482**Result** ✓ Passed**MOT #4** 2021-05-20 10:55**MOT test number** 304592931161**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))**Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))**MOT #3** 2020-06-04 10:32**MOT test number** 435024909587**Result** ✓ Passed**Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))**Advice** Items removed from driver's view prior to test**MOT #2** 2020-06-04 09:59**MOT test number** 903589123415**Result** ✗ Failed**Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))**Advice** Items removed from driver's view prior to test**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))



MOT #1	2019-10-19 09:08
MOT test number	369694273838
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
28 June 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	28 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	KR66EUO
Plate since	2019-03-29
Current registration	KR66EUO
Plate since	2019-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2016-10-26
Last registration	2023-06-23
Complete history	See info



Registration #1	2016-10-26	19 mi
Registration #2	2019-10-19	44.171 mi
Registration #3	2020-06-04	49.908 mi
Registration #4	2020-06-04	49.908 mi
Registration #5	2021-05-20	53.699 mi
Registration #6	2021-05-20	53.699 mi
Registration #7	2023-06-23	53.699 mi
Registration #8	2023-06-23	53.699 mi
Registration #9	2023-06-23	53.699 mi
Registration #10	2023-06-23	53.699 mi
Registration #11	2023-06-23	53.699 mi
Registration #12	2023-06-23	53.699 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	85%
Pedestrian	76%
Safety systems	75%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1775 mm
Height	1610 mm
Length	4175 mm
Wheel base	2500 mm
Kerb weight	1370 kg
Max. allowed weight	1870 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	D16AA7812889