



report date: 2024-03-28

General information

Make	NISSAN
Model	ALMERA SE
Colour	Blue
Year of manufacture	2005
Top speed	110 mph
0 - 60 mph	12.5 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	114 BHP
Max. torque	163 Nm at 4.000 rpm
Engine capacity	1.769 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.6 mpg
Consumption extra urban	45.6 mpg
Consumption combined	36.2 mpg
CO2 emission	187 g/km
CO2 label	J





Internet history

Entry 2

Date	2021-10-28
Pictures	24
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-09-30
Pictures	24
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-12-03
MOT pass rate	57 %
MOT passed	16
Failed MOT tests	12
Total advice items	93
Total items failed	11

MOT #28	2023-12-04 17:33
MOT test number	448686092508
Result	✓ Passed
Next expiry date	2024-12-03
Advice	Power steering pump has slight seepage (2.1.5 (a))
Advice	Offside Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #27**

2023-11-29 11:34

MOT test number

218025287173

Result**✗ Failed**

MAJOR Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MAJOR Offside Front Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))

MAJOR Offside Front Headlamp insecure (4.1.1 (c))

Advice Power steering component has slight seepage from a component (2.1.5 (a))

Advice Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

DANGEROUS Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MAJOR Nearside Front Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))

MAJOR Parking brake efficiency below requirements (1.4.2 (a) (i))

MAJOR Nearside Front Headlamp insecure (4.1.1 (c))

MOT #26

2022-11-16 13:32

MOT test number

161213979320

Result**✓ Passed****MOT #25**

2022-11-16 13:32

MOT test number

624672777312

Result**✗ Failed**

Pass with rectification Nearside Front Headlamp not working on main beam (4.1.1 (a) (ii))

**MOT #24**

2021-11-26 12:02

MOT test number

430545187865

Result

✓ Passed

Advice Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Front and rear brake pads getting low**MOT #23**

2021-08-25 10:32

MOT test number

715960284512

Result

✗ Failed

MAJOR Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Brake fluid close to minimum mark (1.1.10 (d) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Advice** Child Seat fitted not allowing full inspection of adult belt**MAJOR** Central Exhaust has a major leak of exhaust gases center boxes blowing (6.1.2 (a))

**MOT #22**

2020-08-13 10:03

MOT test number

112778596769

Result

✓ Passed

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Central Exhaust has a minor leak of exhaust gases center box (6.1.2 (a))

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #21**

2020-08-12 09:46

MOT test number

807970541928

Result**✗ Failed**

- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Central Exhaust has a minor leak of exhaust gases center box (6.1.2 (a))
- MAJOR** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- MAJOR** Offside Front Headlamp aim not tested (4.1.2 (b))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Rear Exhaust has a major leak of exhaust gases back box (6.1.2 (a))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Child Seat fitted not allowing full inspection of adult belt
- MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))
- MAJOR** Offside Front Headlamp not working on main beam (4.1.1 (a) (ii))
- Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #20

2019-08-15 11:50

MOT test number

931612489364

Result**✓ Passed**

- Advice** Exhaust blow rear box
- Advice** Both rear tyres cracking on sidewall
- Advice** Power steering rack weeping

**MOT #19** 2019-08-14 08:19**MOT test number** 581112541790**Result** ✗ Failed**MAJOR** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Power steering rack weeping**Advice** Exhaust blow rear box**MAJOR** Windscreen washer not working (3.5 (a))**Advice** Both rear tyres cracking on sidewall**MOT #18** 2018-08-29 08:52**MOT test number** 570614395701**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**MOT #17** 2017-08-31 12:50**MOT test number** 294312052578**Result** ✓ Passed**Advice** Both rear tyres perishing**MOT #16** 2017-08-31 12:50**MOT test number** 793146678177**Result** ✗ Failed**Advice** Both rear tyres perishing**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)

**MOT #15** 2016-08-31 09:59**MOT test number** 719443449298**Result** ✓ Passed**Advice** Both rear tyres perishing**MOT #14** 2016-08-31 08:32**MOT test number** 964693885019**Result** ✗ Failed**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Stop lamp not working (1.2.1b)**Advice** Both rear tyres perishing**MOT #13** 2015-09-01 14:38**MOT test number** 704252834434**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #12** 2015-09-01 00:00**MOT test number** 612718903586**Result** ✗ Failed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #11** 2014-09-27 10:03**MOT test number** 375760774257**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**MOT #10** 2014-09-27 10:03**MOT test number** 806960074257**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Offside Headlamp aim too high (1.8)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**MOT #9** 2013-09-28 08:58**MOT test number** 246211373254**Result** ✓ Passed**Notice** Slight leak of oil from steering rack pinion oil seal**MOT #8** 2012-09-28 17:18**MOT test number** 676042472208**Result** ✓ Passed**Notice** Power steering rack weeping turret area**Notice** O/s/f and n/s/f a/r/b links worn/perished



MOT #7	2011-09-29 09:48
MOT test number	856152971226
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #6	2011-09-29 09:48
MOT test number	459262871266
Result	✗ Failed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Pass with rectification	Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Pass with rectification	Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #5	2010-09-28 16:19
MOT test number	702911370275
Result	✓ Passed
Notice	Front bumper and body has slight damage
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Notice	Nail in nearside rear tyre
Notice	Nearside rear tyre tread low on edge

**MOT #4**

2010-09-28 15:13

MOT test number

272471770227

Result**✗ Failed**

- Notice** Nearside rear tyre tread low on edge
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Notice** Nail in nearside rear tyre
- Notice** Front bumper and body has slight damage
- Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #3

2009-09-04 09:33

MOT test number

851117849226

Result**✓ Passed****MOT #2**

2008-09-10 16:43

MOT test number

753264158265

Result**✓ Passed**

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)

MOT #1

2008-09-08 16:03

MOT test number

324122958277

Result**✗ Failed**

- Fail** Offside Inner Front Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
3 December 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	3 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	29
First mileage registration	2005-09-09
Last registration	2023-12-04
Complete history	See info



Registration #1	2005-09-09	9 mi
Registration #2	2008-09-08	18.286 mi
Registration #3	2008-09-10	18.286 mi
Registration #4	2009-09-04	25.917 mi
Registration #5	2010-09-28	35.427 mi
Registration #6	2010-09-28	35.427 mi
Registration #7	2011-09-29	44.040 mi
Registration #8	2012-09-28	51.173 mi
Registration #9	2013-09-28	56.648 mi
Registration #10	2014-09-27	62.205 mi
Registration #11	2015-09-01	74.226 mi
Registration #12	2015-09-01	74.227 mi
Registration #13	2016-08-31	77.938 mi
Registration #14	2016-08-31	77.938 mi
Registration #15	2017-08-31	82.731 mi
Registration #16	2018-08-31	85.557 mi
Registration #17	2019-08-31	88.383 mi
Registration #18	2020-08-31	91.209 mi
Registration #19	2021-08-31	94.035 mi
Registration #20	2022-08-31	96.861 mi
Registration #21	2023-08-31	99.687 mi
Registration #22	2023-12-04	102.513 mi
Registration #23		
Registration #24		
Registration #25		
Registration #26		

Registration #27	2025-25-25	25,252,442
Registration #28	2025-25-25	25,252,442
Registration #29	2025-25-25	25,252,442

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1706 mm
Height	1448 mm
Length	4184 mm
Wheel base	2535 mm
Kerb weight	1199 kg
Max. allowed weight	1735 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number	412616
---------------	--------