





General information

| Make | MAZDA |
|---------------------|-------------------|
| Model | 3 SPORT NAV |
| Colour | Blue |
| Year of manufacture | 2015 |
| Top speed | 121 mph |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| Power | 118 BHP |
|-------------------------|---------------------|
| Max. torque | 210 Nm at 4.000 rpm |
| Engine capacity | 1.998 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 40.4 mpg |
| Consumption extra urban | 58.9 mpg |
| Consumption combined | 50.4 mpg |
| CO2 emission | 129 g/km |
| CO2 label | D |



| Internet history | |
|------------------|-------------|
| Entry 1 | |
| Date | 2021-02-01 |
| Pictures | 1 |
| Listing price | View report |



source: autoonline.co.uk



MOT history

| MOT expiry date | 2025-02-28 |
|--------------------|------------|
| MOT pass rate | 88 % |
| MOT passed | 7 |
| Failed MOT tests | 1 |
| Total advice items | 8 |
| Total items failed | 2 |

| MOT #8 | 2024-01-31 10:32 |
|------------------|------------------|
| MOT test number | 290306774721 |
| Result | ✓ Passed |
| Next expiry date | 2025-02-28 |

| MOT #7 | 2023-02-18 08:46 |
|-----------------|------------------|
| MOT test number | 314072857472 |
| Result | ✓ Passed |

| MOT #6 | 2022-02-05 12:41 |
|-----------------|------------------|
| MOT test number | 239923566379 |
| Result | ✓ Passed |

| MOT #5 | 2021-02-13 08:58 |
|-----------------|------------------|
| MOT test number | 317632180517 |
| Result | ✓ Passed |
| | |

| MOT #4 | 2020-02-08 09:20 |
|-----------------|------------------|
| MOT test number | 869717722647 |
| Result | ✓ Passed |





| MOT #3 | 2019-02-11 16:24 |
|--|------------------|
| MOT test number | 829380295501 |
| Result | ✓ Passed |
| | |
| MOT #2 | 2018-02-19 15:01 |
| MOT test number | 291135155884 |
| Result | ✓ Passed |
| Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1) | |
| Advice Offside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1) | |

| MOT #1 | 2018-02-16 15:38 |
|---|------------------|
| MOT test number | 716954523095 |
| Result | 🗙 Failed |
| Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1) | |
| Fail Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2) | |
| Advice Offside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1) | |
| FailFront Brake pad(s) less than 1.5 mm thick (3.5.1g) | |
| Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1) | |



Tax & MOT check

| ✓ Taxed Tax due: 1 March 2025 | ✓ MOT Expires: 28 February 2025 |
|--|--|
| Tax status | Valid until 1 March |
| Days left | 306 |
| MOT expiry date | 28 February 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|------------|
| Band | D |
| Single payment (12 months) | £ 150,00,- |
| Single six month payment | £ 82,50,- |
| Total payable by 12 monthly instalments | £ 157,50,- |





Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

| FE DO |
|------------|
| A PROPERTY |
| |
| AMPL |
| |
| AMPLE |
| |
| |

Extra MAZDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 6 10.700 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 11 200 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ********* | |
|--|-------------|
| ******** | |
| ******* | |
| ********** | |
| ******* | |
| | More info > |
| Plate changes | |
| See in this check if this MAZDA had different number plates. | |
| | |
| Number of plates | , |
| Number of plates Current registration | |
| Number of plates Correct registration Plate since | |
| Number of plates Correct registration Plate since Correct registration | |
| Number of plates Correct registration Fate since Fate since Fate since | 8000-20-20 |





Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 10 |
| First mileage registration | 2015-03-01 |
| Last registration | 2024-01-31 |
| Complete history | See info |



| Registration #1 | 2015-03-01 | 6 mi |
|------------------|------------|------------|
| Registration #2 | 2018-02-16 | 36.697 mi |
| Registration #3 | 2018-02-19 | 36.701 mi |
| Registration #4 | 2019-02-11 | 40.192 mi |
| Registration #5 | 2020-02-08 | 47.758 mi |
| Registration #6 | | 11.777 esi |
| Registration #7 | | 11.777 mi |
| Registration #8 | | 11.777 esi |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 11.117 esi |

More info >





Safety ratings

| NCAP rating | **** |
|----------------|------------------------|
| Adult | 92% |
| Children | 77% |
| Pedestrian | 66% |
| Safety systems | 81% |
| Overall rating | 83% |
| Video | <u>see crash video</u> |



| Dimensions & weight | |
|--|--------------------------|
| Width | 1795 mm |
| Height | 1465 mm |
| Length | 4465 mm |
| Wheel base | 2700 mm |
| Kerb weight | 1205 kg |
| Max. allowed weight | 1835 kg |
| | |
| Additional information | |
| Additional information Fuel tank capacity | 51 l |
| | 51 l Direct Injection |
| Fuel tank capacity | |
| Fuel tank capacity Fuel delivery | Direct Injection |
| Fuel tank capacity Fuel delivery Number of doors | Direct Injection 5 |