



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	COROLLA VVTI T SPIRIT
Colour	Red
Year of manufacture	2004
Top speed	118 mph
0 - 60 mph	10.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	150 Nm at 3.800 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	47.8 mpg
Consumption combined	40.3 mpg
CO2 emission	168 g/km
CO2 label	H





Internet history

Entry 2


Date	2021-10-24
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-10-03
Pictures	13
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2022-10-05
-----------------	------------

MOT pass rate	71 %
---------------	------

MOT passed	17
------------	----

Failed MOT tests	7
------------------	---

Total advice items	33
--------------------	----

Total items failed	12
--------------------	----

MOT #24	2021-09-30 15:58
---------	------------------

MOT test number	429931191584
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2022-10-05
------------------	------------

Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
--------	---

Advice	Rear Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
--------	---

Advice	Hand Brake require adjusting
--------	------------------------------

Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))
--------	---

Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))
--------	--

Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
--------	--

Advice	Rear Vehicle structure is corroded but structural rigidity is not significantly reduced Both Sides (6.1.1 (c) (i))
--------	--

Advice	Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
--------	---

Advice	Fuel tank straps corroded
--------	---------------------------

Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
--------	---

**MOT #23**

2021-09-29 10:30

MOT test number

276327026852

Result

✗ Failed

- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Hand Brake require adjusting
- Advice** Rear Vehicle structure is corroded but structural rigidity is not significantly reduced Both Sides (6.1.1 (c) (i))
- Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Fail** Offside Front Headlamp lens seriously defective (4.1.1 (b) (ii))
- Advice** Fuel tank straps corroded
- Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))

MOT #22

2020-10-06 10:56

MOT test number

834858058047

Result

✓ Passed

MOT #21

2019-12-16 10:11

MOT test number

544006046708

Result

✓ Passed

MOT #20

2018-12-11 12:09

MOT test number

124687190338

Result

✓ Passed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #19** 2018-12-11 11:10**MOT test number** 760273339134**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Front Service brake excessively binding both (1.2.1 (f))**MOT #18** 2018-01-10 08:00**MOT test number** 621676405254**Result** ✓ Passed**MOT #17** 2018-01-10 08:00**MOT test number** 350295466820**Result** ✗ Failed**Pass with rectification** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #16** 2017-08-04 09:34**MOT test number** 259361094472**Result** ✓ Passed**MOT #15** 2017-08-04 07:20**MOT test number** 167933560350**Result** ✗ Failed**Fail** Rear passenger door cannot be opened from outside the vehicle tailgate/boot (6.2.B.1c)**Fail** Offside Rear Exhaust has a major leak of exhaust gases silencer joint (7.1.2)**MOT #14** 2017-01-30 17:03**MOT test number** 862883407710**Result** ✓ Passed

**MOT #13** 2016-02-02 09:45**MOT test number** 545320607413**Result** ✓ Passed**MOT #12** 2016-02-01 16:47**MOT test number** 721071500324**Result** ✗ Failed**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Front coil spring broken (2.4.C.1a)**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #11** 2015-02-03 09:05**MOT test number** 469514535019**Result** ✓ Passed**MOT #10** 2014-02-06 09:03**MOT test number** 225577734000**Result** ✓ Passed**Advice** Offside Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #9** 2014-02-06 09:03**MOT test number** 416777134046**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Brake pipe slightly corroded (3.6.B.2c)**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Brake pipe slightly corroded (3.6.B.2c)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2013-02-06 16:44**MOT test number** 169287133008**Result** ✓ Passed**MOT #7** 2012-02-06 15:58**MOT test number** 378847032035**Result** ✓ Passed**MOT #6** 2012-02-06 13:06**MOT test number** 756547732033**Result** ✗ Failed**Fail** Rear registration plate deteriorated (6.3.1d)**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #5** 2011-02-03 15:05**MOT test number** 385264231097**Result** ✓ Passed



MOT #4	2010-01-28 16:03
MOT test number	771038620093
Result	✓ Passed
MOT #3	2009-01-30 15:41
MOT test number	353240739028
Result	✓ Passed
MOT #2	2008-02-01 12:31
MOT test number	230772638075
Result	✓ Passed
MOT #1	2007-02-01 10:37
MOT test number	610852037004
Result	✓ Passed
<div>NoticeFront pads getting low</div>	



Tax & MOT check

✕
Untaxed

Tax expired:
19 September 2021

✕
MOT

Expired:
5 October 2022

Tax status	Expired at 19 September
Days left	954 days too late
MOT expiry date	5 October 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-




Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2004-02-13
Last registration	2021-09-30
Complete history	See info



Registration #1	2004-02-13	21 mi
Registration #2	2007-02-01	25.010 mi
Registration #3	2008-02-01	32.786 mi
Registration #4	2009-01-30	38.895 mi
Registration #5	2010-01-28	44.520 mi
Registration #6	2011-02-03	49.682 mi
Registration #7	2012-02-06	56.326 mi
Registration #8	2012-02-06	56.326 mi
Registration #9	2013-02-06	61.216 mi
Registration #10	2014-02-06	65.760 mi
Registration #11	2015-02-03	70.364 mi
Registration #12	2016-02-01	74.575 mi
Registration #13	2016-02-02	74.575 mi
Registration #14	2016-02-02	74.575 mi
Registration #15	2016-02-02	74.575 mi
Registration #16	2016-02-02	74.575 mi
Registration #17	2016-02-02	74.575 mi
Registration #18	2016-02-02	74.575 mi
Registration #19	2016-02-02	74.575 mi
Registration #20	2016-02-02	74.575 mi
Registration #21	2016-02-02	74.575 mi
Registration #22	2016-02-02	74.575 mi
Registration #23	2016-02-02	74.575 mi
Registration #24	2016-02-02	74.575 mi
Registration #25	2016-02-02	74.575 mi
Registration #26	2016-02-02	74.575 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1220 kg
Max. allowed weight	1655 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	3ZZU520898