



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 D DRIVE R-DESIGN
Colour	Grey
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C






Internet history

Entry 1

Date	2022-06-21
Pictures	17
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-08
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	29
Total items failed	11

MOT #16	2023-08-09 13:08
MOT test number	692144523727
Result	✓ Passed
Next expiry date	2024-08-08
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Battery insecure but not likely to fall from carrier (4.13 (a) (i))

MOT #15	2022-09-26 17:08
MOT test number	286863721137
Result	✓ Passed
Minor	Battery insecure but not likely to fall from carrier (4.13 (a) (i))

**MOT #14**

2022-09-26 14:34

MOT test number

826439430186

Result**✗ Failed**

- Fail** Nearside Front Service brake excessively binding (1.2.1 (f))
- Fail** Nearside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Front Brakes imbalanced across an axle (1.2.1 (b) (i))
- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))
- Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

MOT #13

2020-12-05 10:34

MOT test number

842081588530

Result**✓ Passed**

- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))

MOT #12

2019-06-08 11:42

MOT test number

910036226810

Result**✓ Passed**

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear most bush of front arm (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear most bush of front arm (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))

**MOT #11** 2019-06-08 11:42**MOT test number** 495732094526**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear most bush of front arm (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))**Pass with rectification** Offside Front Road wheel fixing missing (5.2.1 (a) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear most bush of front arm (5.3.4 (a) (i))**MOT #10** 2018-06-27 14:13**MOT test number** 449032959991**Result** ✓ Passed**MOT #9** 2017-12-20 18:15**MOT test number** 649023036577**Result** ✓ Passed**Advice** Nearside Front Radius arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**Advice** Offside Front Radius arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**MOT #8** 2016-12-21 18:30**MOT test number** 327831896184**Result** ✓ Passed**MOT #7** 2016-12-21 18:30**MOT test number** 931348475549**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)

**MOT #6** 2015-12-16 13:28**MOT test number** 893882879079**Result** ✓ Passed**MOT #5** 2015-12-15 15:42**MOT test number** 327415042451**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #4** 2014-12-24 09:17**MOT test number** 236638554387**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #3** 2014-05-08 16:04**MOT test number** 127908924143**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Advice** Offside Rear Lower Tie bar/rod rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Nail in offside rear tyre**Advice** Nearside Rear Lower Tie bar/rod rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #2** 2014-05-08 11:45**MOT test number** 536918824152**Result** ✗ Failed**Advice** Nearside Rear Lower Tie bar/rod rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Nail in offside rear tyre**Fail** Nearside Headlamp aim too low (1.8)**Advice** Offside Rear Lower Tie bar/rod rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Nearside front tyre has sidewall damage**Notice** Under-trays fitted obscuring some underside components**Fail** Offside Rear Seat belt locking mechanism does not secure or release (5.2.5a)**MOT #1** 2013-05-29 14:02**MOT test number** 399239643158**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
8 August 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	8 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-28
Current registration	
Plate since	2019-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-05-28
Last registration	2023-08-09
Complete history	See info



Registration #1	2010-05-28	24 mi
Registration #2	2013-05-29	28.836 mi
Registration #3	2014-05-08	41.012 mi
Registration #4	2014-05-08	41.012 mi
Registration #5	2014-12-24	50.584 mi
Registration #6	2015-12-15	57.789 mi
Registration #7	2015-12-16	57.790 mi
Registration #8	2016-12-21	64.804 mi
Registration #9	2016-12-21	64.804 mi
Registration #10	2016-12-21	64.804 mi
Registration #11	2016-12-21	64.804 mi
Registration #12	2016-12-21	64.804 mi
Registration #13	2016-12-21	64.804 mi
Registration #14	2016-12-21	64.804 mi
Registration #15	2016-12-21	64.804 mi
Registration #16	2016-12-21	64.804 mi
Registration #17	2016-12-21	64.804 mi
Registration #18	2016-12-21	64.804 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1442 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	957553