



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 D2 R-DESIGN
Colour	Black
Year of manufacture	2011
Top speed	121 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C






Internet history

Entry 1

Date	2022-01-07
Pictures	23
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-26
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	30
Total items failed	3

MOT #13	2024-01-18 12:10
MOT test number	134679185329
Result	✓ Passed
Next expiry date	2025-01-26
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #12	2023-01-06 15:54
MOT test number	974448003171
Result	✓ Passed
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement LOWER ARM REAR BUSH (5.3.4 (a) (i))
Advice	UNDERSIDE CORRODED - MORE ADVANCED IN AREAS

**MOT #11**

2023-01-03 15:28

MOT test number

520468738160

Result**✗ Failed**

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement LOWER ARM REAR BUSH (5.3.4 (a) (i))

Fail Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement LOWER ARM REAR BUSH (5.3.4 (a) (i))

Fail Fuel system component leaking INJECTOR (6.1.3 (b) (i))

Advice UNDERSIDE CORRODED - MORE ADVANCED IN AREAS

MOT #10

2022-01-27 16:16

MOT test number

691071249467

Result**✓ Passed**

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #9

2022-01-26 17:08

MOT test number

975495633573

Result**✗ Failed**

Fail Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8

2021-03-22 09:17

MOT test number

653962028593

Result**✓ Passed**

Minor Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #7** 2020-03-30 08:25**MOT test number** 200006048473**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #6** 2019-03-07 09:56**MOT test number** 519066682715**Result** ✓ Passed**MOT #5** 2018-03-21 09:34**MOT test number** 616627522278**Result** ✓ Passed**Advice** Engine undertray loose**Advice** Nearside Front tyre has edge wear**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (rear bush) (2.4.G.2)**Advice** Covers and undertrays fitted**Advice** Offside Front tyre inner edge worn smooth and thin**Advice** Offside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Advice** Nearside Rear tyre has uneven wear(flat spot)**Advice** Play in steering rack inner joint(s)

**MOT #4** 2017-03-28 08:32**MOT test number** 517122438193**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Tyre wearing unevenly.

MOT #3 2016-04-21 08:32**MOT test number** 298847628143**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)

MOT #2 2015-04-22 10:54**MOT test number** 215542415120**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2014-04-23 10:21**MOT test number** 229723114182**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
26 January 2025

Tax status	Valid until 1 February
Days left	279
MOT expiry date	26 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-04-28
Last registration	2024-01-18
Complete history	See info



Registration #1	2011-04-28	27 mi
Registration #2	2014-04-23	40.822 mi
Registration #3	2015-04-22	63.858 mi
Registration #4	2016-04-21	88.968 mi
Registration #5	2017-03-28	112.611 mi
Registration #6	2018-03-21	126.731 mi
Registration #7	2019-03-07	140.001 mi
Registration #8	2020-03-30	154.369 mi
Registration #9	2021-03-29	168.737 mi
Registration #10	2022-03-29	183.105 mi
Registration #11	2023-03-29	197.473 mi
Registration #12	2024-01-18	211.841 mi
Registration #13	2024-01-18	211.841 mi
Registration #14	2024-01-18	211.841 mi
Registration #15	2024-01-18	211.841 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1359 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	1708102