



Mercedes-Benz



M66ASW


report date: 2024-03-28

General information

Make	MERCEDES
Model	S-Class S500
Colour	Black
Year of manufacture	2007
Top speed	155 mph
0 - 60 mph	5.4 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	382 BHP
Max. torque	529 Nm at 2.800 rpm
Engine capacity	5.462 cc
Cylinders	8
Fuel type	Petrol
Consumption city	16.1 mpg
Consumption extra urban	32.8 mpg
Consumption combined	23.9 mpg
CO2 emission	281 g/km
CO2 label	M





Internet history

Entry 3

Date	2022-01-24
Pictures	30
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 2

Date	2021-12-18
Pictures	30
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-09-16
Pictures	28
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2023-04-13
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	14
Total items failed	2

MOT #16	2022-04-14 08:39
MOT test number	451843146897
Result	✓ Passed
Next expiry date	2023-04-13

MOT #15	2021-03-05 15:18
MOT test number	813203359516
Result	✓ Passed
Advice	ABC- MALFUNCTION WARNING active body control..

MOT #14	2021-03-04 15:01
MOT test number	328681426129
Result	✗ Failed
MAJOR	Nearside Headlamp aim too low (4.1.2 (a))
MAJOR	Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))
MAJOR	Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a))
Advice	ABC- MALFUNCTION WARNING active body control..

**MOT #13** 2019-10-17 13:43**MOT test number** 278278478285**Result** ✓ Passed

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing the outer edge / and outer side wall.  
(5.2.3 (d) (ii))

**Advice** Engine covers fitted obscuring some components in the engine bay.

**Advice** Under-trays fitted obscuring some components to the underside.

**MOT #12** 2018-10-23 11:29**MOT test number** 675421108222**Result** ✓ Passed

**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #11** 2017-09-05 12:59**MOT test number** 508264159282**Result** ✓ Passed**MOT #10** 2017-03-08 10:47**MOT test number** 692255467015**Result** ✓ Passed**MOT #9** 2016-03-19 10:52**MOT test number** 212796165762**Result** ✓ Passed**MOT #8** 2015-02-18 15:04**MOT test number** 129189345440**Result** ✓ Passed

**MOT #7** 2015-02-18 14:38**MOT test number** 976949145040**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #6** 2014-01-30 13:42**MOT test number** 625340934028**Result** ✓ Passed**MOT #5** 2014-01-29 09:50**MOT test number** 507589124036**Result** ✗ Failed**Fail** Nearside Side repeater excessively deteriorated so that it is not visible from a reasonable distance (1.4.A.2e)**MOT #4** 2013-01-30 12:09**MOT test number** 929240433033**Result** ✓ Passed**MOT #3** 2012-02-18 09:49**MOT test number** 805109442038**Result** ✓ Passed**Notice** Nail in nearside front tyre**Notice** Fluid leak on undertrays**MOT #2** 2011-02-12 09:54**MOT test number** 417943641069**Result** ✓ Passed



MOT #1	2010-01-18 12:28
MOT test number	130848710059
Result	✓ Passed
Advice	Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-02-17
Last registration	2022-04-14
Complete history	<a href="#">See info</a>



Registration #1	2007-02-17	24 mi
Registration #2	2010-01-18	75.466 mi
Registration #3	2011-02-12	97.320 mi
Registration #4	2012-02-18	101.328 mi
Registration #5	2013-01-30	107.265 mi
Registration #6	2014-01-29	111.385 mi
Registration #7	2014-01-30	111.385 mi
Registration #8	2015-02-18	113.135 mi
Registration #9	2015-02-18	113.135 mi
Registration #10	2016-03-19	116.834 mi
Registration #11	2016-03-19	116.834 mi
Registration #12	2016-03-19	116.834 mi
Registration #13	2016-03-19	116.834 mi
Registration #14	2016-03-19	116.834 mi
Registration #15	2016-03-19	116.834 mi
Registration #16	2016-03-19	116.834 mi
Registration #17	2016-03-19	116.834 mi
Registration #18	2016-03-19	116.834 mi
Registration #19	2016-03-19	116.834 mi
Registration #20	2016-03-19	116.834 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1872 mm
Height	1473 mm
Length	5206 mm
Wheel base	3165 mm
Kerb weight	1985 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	27396130140454