



**GJ08MFU**

report date: 2024-03-28

General information

Make	FORD
Model	FUSION STYLE CLIMATE
Colour	Blue
Year of manufacture	2008
Top speed	102 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	124 Nm at 3.500 rpm
Engine capacity	1.388 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 1

Date	2022-01-27
Pictures	4
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-15
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	24
Total items failed	2

MOT #16	2023-08-09 16:47
MOT test number	495962590847
Result	✓ Passed
Next expiry date	2024-08-15
Minor	Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #15	2023-08-08 08:45
MOT test number	104374099159
Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))
Minor	Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
MAJOR	Offside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))
DANGEROUS	Nearside Front Brake pipe leaking on a hydraulic braking system (1.1.11 (b) (ii))
MAJOR	Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #14** 2022-08-05 11:52**MOT test number** 816014166298**Result** ✓ Passed**Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))**MOT #13** 2021-08-13 08:55**MOT test number** 186682454161**Result** ✓ Passed**MOT #12** 2021-08-13 08:55**MOT test number** 388312354155**Result** ✗ Failed**Pass with rectification** Offside Rear Position lamp not working (4.2.1 (a) (ii))**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #11** 2020-08-10 07:38**MOT test number** 696253699410**Result** ✓ Passed**MOT #10** 2019-08-16 13:38**MOT test number** 468442236533**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9** 2018-08-11 08:20**MOT test number** 179089153805**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge perished on outer edge (5.2.3 (e))**MOT #8** 2017-08-14 13:47**MOT test number** 404910502452**Result** ✓ Passed**MOT #7** 2017-03-15 14:55**MOT test number** 863273709887**Result** ✓ Passed**MOT #6** 2016-03-10 13:44**MOT test number** 350133796098**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2015-03-12 11:35**MOT test number** 976931075009**Result** ✓ Passed**Notice** N/s/f tyre on legal wear limit**Notice** N/s/r road wheel slightly out of shape**Notice** O/s/f tyre close to legal wear limits

**MOT #4** 2014-03-14 09:06**MOT test number** 738163774079**Result** ✓ Passed**Advice** Offside Rear Direction indicators slightly discoloured (1.4.A.2f)**MOT #3** 2013-03-20 12:45**MOT test number** 129359773424**Result** ✓ Passed**MOT #2** 2012-03-15 14:05**MOT test number** 315745872062**Result** ✓ Passed**MOT #1** 2011-03-17 13:03**MOT test number** 268286571056**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
15 August 2024

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	279
<b>MOT expiry date</b>	15 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2019-01-01
Current registration	<b>XXXXXX</b>
Plate since	2019-01-01

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-03-28
Last registration	2023-08-09
Complete history	<a href="#">See info</a>



Registration #1	2008-03-28	22 mi
Registration #2	2011-03-17	18.919 mi
Registration #3	2012-03-15	23.176 mi
Registration #4	2013-03-20	27.447 mi
Registration #5	2014-03-14	33.420 mi
Registration #6	2015-03-12	39.097 mi
Registration #7	2016-03-10	44.653 mi
Registration #8	2017-03-15	50.749 mi
Registration #9	2017-08-14	52.973 mi
Registration #10	2018-03-28	55.217 mi
Registration #11	2019-03-28	57.517 mi
Registration #12	2020-03-28	59.817 mi
Registration #13	2021-03-28	62.117 mi
Registration #14	2022-03-28	64.417 mi
Registration #15	2023-03-28	66.717 mi
Registration #16	2024-03-28	69.017 mi
Registration #17	2025-03-28	71.317 mi
Registration #18	2026-03-28	73.617 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1199 kg
Max. allowed weight	1605 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	8A48618