



report date: 2024-03-28

## General information

Make	VAUXHALL
Model	ANTARA SE CDTi
Colour	Black
Year of manufacture	2010
Top speed	112 mph
0 - 60 mph	10.3 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	150 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.991 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.5 mpg
Consumption extra urban	41.5 mpg
Consumption combined	37.2 mpg
CO2 emission	198 g/km
CO2 label	J





Internet history

Entry 2

Date	2021-09-22
Pictures	14
Listing price	<a href="#">View report</a>



source: yesauto.com

Entry 1

Date	2021-09-11
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-31
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	42
Total items failed	0

MOT #15	2023-11-01 15:01
---------	------------------

MOT test number	874736825019
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-10-31
------------------	------------

Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Central Front Brake pad(s) wearing thin both (1.1.13 (a) (ii))
Advice	Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Central Front Exhaust has a minor leak of exhaust gases flexi (6.1.2 (a))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Central Rear Brake pad(s) wearing thin both (1.1.13 (a) (ii))
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Central Front Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #14**

2022-10-21 10:19

**MOT test number**

273179365223

**Result**

✓ Passed

- Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Front Exhaust has a minor leak of exhaust gases flexi (6.1.2 (a))
- Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #13**

2021-10-28 10:04

**MOT test number**

719038329529

**Result**

✓ Passed

**MOT #12**

2020-12-16 15:57

**MOT test number**

814117844860

**Result**

✓ Passed

- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Front Brake hose has slight corrosion to ferrule nearside / offside to calipers (1.1.12 (f) (i))
- Advice** Front Brake pipe clips or supports missing, pipe adequately supported nearside / offside brackets loose (1.1.11 (d) (i))
- Advice** Slight corrosion to rear subframe and various suspension components

**MOT #11** 2020-12-16 11:57**MOT test number** 880319867846**Result** ✗ Failed**MAJOR** Nearside Side repeater not working (4.4.1 (a) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Slight corrosion to rear subframe and various suspension components**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**MAJOR** Exhaust has a major leak of exhaust gases rear silencer missing (6.1.2 (a))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Front Brake hose has slight corrosion to ferrule nearside / offside to calipers (1.1.12 (f) (i))**Advice** Front Brake pipe clips or supports missing, pipe adequately supported nearside / offside brackets loose (1.1.11 (d) (i))**MAJOR** Nearside Parking brake inoperative on one side (1.4.1 (a))**MOT #10** 2019-12-10 14:30**MOT test number** 965696036974**Result** ✓ Passed**MOT #9** 2019-12-06 11:42**MOT test number** 298601109565**Result** ✗ Failed**MAJOR** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MAJOR** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**MOT #8** 2018-12-29 11:23**MOT test number** 115153696957**Result** ✓ Passed

**MOT #7** 2018-12-28 10:45**MOT test number** 997533794367**Result** ✗ Failed**MAJOR** Front Windscreen washer not working (3.5 (a))**MAJOR** Nearside Headlamp aim too low (4.1.2 (a))**MAJOR** Headlamp cleaning device for LED or HID headlamp inoperative (4.1.6 (a) (ii))**MAJOR** Offside Headlamp aim too low (4.1.2 (a))**Advice** Offside Front Nail in tyre**MOT #6** 2018-02-14 14:13**MOT test number** 529915089325**Result** ✓ Passed**MOT #5** 2017-01-12 09:50**MOT test number** 880409655524**Result** ✓ Passed**Advice** Offside Front suspension has slight movement at a wishbone pin or bush rearmost (2.5.A.1c)**Advice** Nearside Front suspension has slight movement at a wishbone pin or bush rearmost (2.5.A.1c)**MOT #4** 2016-01-12 10:28**MOT test number** 965675302153**Result** ✓ Passed**MOT #3** 2015-02-10 10:25**MOT test number** 128671145452**Result** ✓ Passed



MOT #2	2014-01-28 12:16
MOT test number	117808624401
Result	✓ Passed

MOT #1	2013-01-28 10:52
MOT test number	775278023065
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
31 October 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	187
<b>MOT expiry date</b>	31 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	J
<b>Single payment (12 months)</b>	£ 365,00,-
<b>Single six month payment</b>	£ 200,75,-
<b>Total payable by 12 monthly instalments</b>	£ 383,25,-





Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 <b>VE59XEX</b>
Plate since	2019-06-29
Current registration	 <b>VE59XEX</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-01-26
Last registration	2023-11-01
Complete history	<a href="#">See info</a>



Registration #1	2010-01-26	20 mi
Registration #2	2013-01-28	49.388 mi
Registration #3	2014-01-28	59.742 mi
Registration #4	2015-02-10	72.319 mi
Registration #5	2016-01-12	84.605 mi
Registration #6	2017-01-12	98.194 mi
Registration #7	2018-02-14	110.981 mi
Registration #8	2018-12-28	119.514 mi
Registration #9	2018-12-29	119.575 mi
Registration #10	2019-01-29	120.377 mi
Registration #11	2019-02-28	121.277 mi
Registration #12	2019-03-28	122.177 mi
Registration #13	2019-04-27	123.077 mi
Registration #14	2019-05-27	123.977 mi
Registration #15	2019-06-26	124.877 mi
Registration #16	2019-07-26	125.777 mi
Registration #17	2019-08-25	126.677 mi
Registration #18	2019-09-24	127.577 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2085 mm
Height	1747 mm
Length	4576 mm
Wheel base	2707 mm
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	1317545K