



report date: 2024-03-28

General information

Make	VAUXHALL
Model	MERIVA TECH LINE
Colour	White
Year of manufacture	2016
Top speed	110 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	130 Nm at 4.000 rpm
Engine capacity	1.398 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	140 g/km
CO2 label	E






Internet history

Entry 1


Date	2021-10-01
Pictures	12
Listing price	View report



Video viewing

Book a video viewing with one of our team.
See the vehicle from the comfort of your own home.

[Visit our website for more info](#)





source: cargurus.co.uk



MOT history

MOT expiry date	2024-12-21
MOT pass rate	56 %
MOT passed	5
Failed MOT tests	4
Total advice items	28
Total items failed	16

MOT #9	2023-12-18 16:42
MOT test number	341819634153
Result	✓ Passed
Next expiry date	2024-12-21

MOT #8	2023-12-12 11:17
MOT test number	113704681780
Result	✗ Failed
Fail	Offside Front Suspension arm ball joint likely to become detached (5.3.4 (a) (ii))
Fail	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
Fail	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))



MOT #7

2022-12-15 12:50

MOT test number

519781770319

Result

✓ Passed

- Advice

Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice

Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Minor

Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice

Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice

Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice

Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #6** 2022-12-14 10:20**MOT test number** 440135375329**Result** ✗ Failed

- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))
- Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #5 2021-12-22 11:19**MOT test number** 987931980202**Result** ✓ Passed

**MOT #4**

2021-08-20 12:43

MOT test number

460990302074

Result

✓ Passed

- Advice** Nearside Front tyre slight damage to outer wall
- Advice** Damage to o/s/f wing
- Advice** Brake disc worn, pitted or scored, but not seriously weakened all discs corroded (1.1.14 (a) (ii))
- Advice** Service light on dash

MOT #3

2021-08-18 10:59

MOT test number

884419756493

Result

✗ Failed

- Advice** Service light on dash
- Advice** Nearside Front tyre slight damage to outer wall
- Fail** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure tread (5.2.3 (d) (ii))
- Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Damage to o/s/f wing
- Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Fail** Electronic power steering warning lamp indicates a system malfunction (2.6 (a))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened all discs corroded (1.1.14 (a) (ii))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))



MOT #2	2019-04-09 15:31
MOT test number	609421144964
Result	✓ Passed
Advice	Nearside Front door mirror loose
Advice	Offside Front bumper & wing damaged

MOT #1	2019-04-09 10:54
MOT test number	174845136409
Result	✗ Failed
Fail	Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords on limit (5.2.3 (d) (i))
Advice	Offside Front bumper & wing damaged
Advice	Nearside Front door mirror loose



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
21 December 2024

Tax status	Valid until 1 March
Days left	307
MOT expiry date	21 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 BA16WFFV
Plate since	2019-06-29
Current registration	 BA16WFFV
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-04-25
Last registration	2023-12-18
Complete history	See info



Registration #1	2016-04-25	17 mi
Registration #2	2019-04-09	22.182 mi
Registration #3	2019-04-09	22.182 mi
Registration #4	2021-08-18	25.089 mi
Registration #5	2021-08-20	25.097 mi
Registration #6	2023-12-18	25.277 mi
Registration #7	2023-12-18	25.277 mi
Registration #8	2023-12-18	25.277 mi
Registration #9	2023-12-18	25.277 mi
Registration #10	2023-12-18	25.277 mi
Registration #11	2023-12-18	25.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	77%
Pedestrian	55%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1994 mm
Height	1615 mm
Length	4300 mm
Wheel base	2644 mm
Kerb weight	1376 kg
Max. allowed weight	1905 kg

Additional information

Fuel tank capacity	54 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	B14XER -19MG7042LDD