



report date: 2024-03-28

General information

Make	FORD
Model	MONDEO GHIA TDCI
Colour	Grey
Year of manufacture	-
Top speed	133 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	153 BHP
Max. torque	360 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	33.6 mpg
Consumption extra urban	55.4 mpg
Consumption combined	44.8 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-01-21
Pictures	19
Listing price	View report



source: yesauto.com

**MOT history****MOT #19**

2023-11-30 11:05

MOT test number

574171279667

Result**✗ Failed**

- Fail** Offside Rear Brake hose excessively deteriorated (1.1.12 (b) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Front Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Fail** Nearside Rear Brake hose excessively deteriorated (1.1.12 (b) (ii))
- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Fail** Nearside Front Prop shaft joint constant velocity boot no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Offside Front Track rod end ball joint worn to the extent there is a serious risk of detachment (2.1.3 (b) (ii))
- Fail** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))

**MOT #18** 2022-12-12 09:58**MOT test number** 771111470694**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #17** 2021-12-03 11:53**MOT test number** 749237348474**Result** ✓ Passed**MOT #16** 2021-12-01 14:17**MOT test number** 342060523674**Result** ✗ Failed**Fail** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))**Fail** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))**MOT #15** 2020-10-14 15:46**MOT test number** 418354352645**Result** ✓ Passed**Advice** Nearside Play in steering rack inner joint(s)**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #14** 2020-10-14 09:01**MOT test number** 235737706552**Result** ✗ Failed**Fail** Nearside Side repeater not working (4.4.1 (a) (ii))**Advice** Nearside Play in steering rack inner joint(s)**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Fail** Offside Parking brake inoperative on one side (1.4.1 (a))**Fail** Exhaust system insecure (6.1.2 (a))**MOT #13** 2019-10-21 12:56**MOT test number** 369556637190**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge very close (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge very close (5.2.3 (e))**Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**MOT #12** 2018-10-18 09:51**MOT test number** 652636206822**Result** ✓ Passed

**MOT #11** 2017-07-14 11:43**MOT test number** 394249053559**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #10** 2016-07-28 07:51**MOT test number** 941783267050**Result** ✓ Passed**MOT #9** 2015-07-29 12:04**MOT test number** 396850515422**Result** ✓ Passed**Notice** O/s driveshaft seal leaking**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Sub-frame rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #8** 2014-07-24 08:53**MOT test number** 647025904203**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Centre Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #7** 2013-08-02 10:14**MOT test number** 259444413200**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Engine water leak**MOT #6** 2012-07-21 10:19**MOT test number** 388573602420**Result** ✓ Passed**Advice** Nearside Rear Direction indicators slightly discoloured (1.4.A.2f)**Notice** N/S Front tyre has cuts in the outside edge of tread**Advice** Offside Rear Direction indicators slightly discoloured (1.4.A.2f)**MOT #5** 2011-07-30 10:16**MOT test number** 275631811219**Result** ✓ Passed**MOT #4** 2010-08-07 08:33**MOT test number** 711779710279**Result** ✓ Passed**Advice** Offside Front Front constant velocity joint gaiter deteriorated (2.5.C.1a)**MOT #3** 2010-07-31 10:32**MOT test number** 511962710266**Result** ✗ Failed**Advice** Offside Front Front constant velocity joint gaiter deteriorated (2.5.C.1a)**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)



MOT #2	2009-06-10 12:08
MOT test number	583611669117
Result	✓ Passed

MOT #1	2008-06-13 12:10
MOT test number	620895568191
Result	✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	EX05ZLE
Plate since	2019-03-28
Current registration	EX05ZLE
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-03-31
Last registration	2023-11-30
Complete history	See info



Registration #1	2005-03-31	25 mi
Registration #2	2008-06-13	10.751 mi
Registration #3	2009-06-10	15.192 mi
Registration #4	2010-07-31	34.170 mi
Registration #5	2010-08-07	34.189 mi
Registration #6	2011-07-30	48.428 mi
Registration #7	2012-07-21	53.865 mi
Registration #8	2013-08-02	59.477 mi
Registration #9	2014-07-24	66.482 mi
Registration #10	2015-07-29	73.074 mi
Registration #11	2016-06-20	75.277 mi
Registration #12	2017-06-20	75.277 mi
Registration #13	2018-06-20	75.277 mi
Registration #14	2019-06-20	75.277 mi
Registration #15	2020-06-20	75.277 mi
Registration #16	2021-06-20	75.277 mi
Registration #17	2022-06-20	75.277 mi
Registration #18	2023-06-20	75.277 mi
Registration #19	2024-06-20	75.277 mi
Registration #20	2025-06-20	75.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1958 mm
Height	1441 mm
Length	4804 mm
Wheel base	2754 mm
Max. allowed weight	2190 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

5K75537