



report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO POP
Colour	White
Year of manufacture	2013
Top speed	97 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	54.3 mpg
CO2 emission	126 g/km
CO2 label	D





Internet history

Entry 1

Date	2022-05-05
Pictures	50
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-24
MOT pass rate	57 %
MOT passed	8
Failed MOT tests	6
Total advice items	34
Total items failed	17

MOT #14	2023-07-18 11:04
MOT test number	698059641165
Result	✓ Passed
Next expiry date	2024-07-24
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13	2023-07-18 10:10
MOT test number	242648146902
Result	✗ Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

MOT #12	2022-07-25 10:09
MOT test number	751748690557
Result	✓ Passed

**MOT #11**

2022-07-22 08:54

MOT test number

971648867280

Result**✗ Failed**

- Fail** Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))
- Fail** Reversing lamp inoperative (4.6.1 (a))
- Fail** Nearside Rear Position lamp light intensity significantly reduced (4.2.3 (a) (ii))
- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

MOT #10

2021-11-16 16:06

MOT test number

593822364158

Result**✓ Passed**

- Advice** Engine coolant level low.. Radiator leaking
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Exhaust rear heatshield heavily deteriorated
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- Advice** Nearside front coil spring not correctly seated
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))
- Advice** Exhaust system heavily deteriorated
- Advice** 195/55/16
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))

**MOT #9**

2021-11-13 11:38

MOT test number

984118243471

Result**✗ Failed****Advice** 195/55/16**Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))**Advice** Engine coolant level low.. Radiator leaking**Advice** Exhaust rear heatshield heavily deteriorated**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside front coil spring not correctly seated**Fail** Stop lamp(s) all not working (4.3.1 (a) (iii))**Fail** Nearside Front Brake hose excessively twisted (1.1.12 (b) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))**Advice** Exhaust system heavily deteriorated**MOT #8**

2020-11-21 14:42

MOT test number

616523631810

Result**✓ Passed****Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Rear rear brakes juddering on brake test**Advice** Rear exhaust backbox outer casing corroded but not leaking**Advice** General underbody corrosion

**MOT #7** 2020-11-21 12:21**MOT test number** 589098942839**Result** ✗ Failed**Advice** General underbody corrosion**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Rear rear brakes juddering on brake test**Fail** Front Brakes imbalanced across an axle front discs face damaged preventing full use of brake pad face. juddering/grabbing on brake test (1.2.1 (b) (i))**Advice** Rear exhaust backbox outer casing corroded but not leaking**MOT #6** 2019-10-24 09:20**MOT test number** 574625600180**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #5** 2019-10-22 14:46**MOT test number** 340072549925**Result** ✗ Failed**Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Fail** Rear fog lamp not working (4.5.1 (a) (ii))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #4** 2018-10-12 09:06**MOT test number** 779035205938**Result** ✓ Passed



MOT #3	2017-10-17 07:40
MOT test number	314211891046
Result	✓ Passed

MOT #2	2017-10-16 13:21
MOT test number	937914200227
Result	✗ Failed
<div><div>Advice</div> Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)</div> <div><div>Fail</div> Nearside Front coil spring broken (2.4.C.1a)</div> <div><div>Fail</div> Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)</div> <div><div>Advice</div> Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)</div> <div><div>Fail</div> Offside Front coil spring broken (2.4.C.1a)</div>	

MOT #1	2016-08-18 17:00
MOT test number	995126544371
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
24 July 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	24 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-07-29
Last registration	2023-07-18
Complete history	See info



Registration #1	2013-07-29	13 mi
Registration #2	2016-08-18	22.296 mi
Registration #3	2017-10-16	27.708 mi
Registration #4	2017-10-17	27.708 mi
Registration #5	2018-10-12	34.888 mi
Registration #6	2019-10-22	41.845 mi
Registration #7	2019-10-24	41.846 mi
Registration #8	2020-11-21	44.732 mi
Registration #9	2020-11-21	44.732 mi
Registration #10	2020-11-21	44.732 mi
Registration #11	2020-11-21	44.732 mi
Registration #12	2020-11-21	44.732 mi
Registration #13	2020-11-21	44.732 mi
Registration #14	2020-11-21	44.732 mi
Registration #15	2020-11-21	44.732 mi
Registration #16	2020-11-21	44.732 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1015 kg
Max. allowed weight	1575 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	0596130