





report date: 2024-03-29

General information

Make	MERCEDES
Model	B-CLASS B170 SE
Colour	Grey
Year of manufacture	2009
Top speed	112 mph
0 - 60 mph	12.0 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	114 BHP
Max. torque	155 Nm at 4.000 rpm
Engine capacity	1.699 сс
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	39.8 mpg
CO2 emission	171 g/km
CO2 label	Н



CarCheck.co.uk page 1/13



report date: 2024-03-29


Internet history

Entry 1

Date 2021-07-27

Pictures 29

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-11-18
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	12
Total items failed	4

MOT #16	2023-11-18 14:14
MOT test number	691652222788
Result	✓ Passed
Next expiry date	2024-11-18

MOT #15	2023-11-18 14:14
MOT test number	115608764877
Result	★ Failed
Pass with rectification (ii))	Nearside Front Anti-roll bar linkage ball joint likely to become detached (5.3.4 (a)
Pass with rectification longer prevents the ingress	Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no of dirt (6.1.7 (g) (ii))

MOT #14	2022-11-19 14:12
MOT test number	159776056934
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #13 2021-11-11 11:05 **MOT** test number 684957330054 ✓ Passed Result Minor Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i)) **Advice** Under trays fitted. **Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a)) Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) Minor Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i)) Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

 MOT #12
 2020-10-30 08:44

 MOT test number
 112280853943

 Result
 ✓ Passed

MOT #11 2019-05-02 07:51

MOT test number 919154989894

Result ✓ Passed

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #10

MOT test number

878088695089

Result

Advice Rear Brake pipe slightly corroded (3.6.B.2c)

 MOT #9
 2017-05-15 14:49

 MOT test number
 910788430668

 Result
 ✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #8 2016-06-08 13:33

MOT test number 456843722069

Result
✓ Passed

MOT #7 2015-06-13 13:45

MOT test number 355394265107

Notice Under-trays fitted obscuring some underside components

MOT #6 2015-06-11 13:40

MOT test number 309492865129

Result X Failed

Notice Under-trays fitted obscuring some underside components

Fail Nearside Rear coil spring broken (2.4.C.1a)

MOT #5 2014-05-31 12:32

MOT test number 878541954131

Result
✓ Passed

MOT #4 2014-05-31 12:32

MOT test number 806511054149

Result X Failed

Pass with rectification Nearside Front Headlamp not working on dipped beam (1.7.5a)

MOT #3 2013-06-10 13:46

MOT test number 638881563187

Result ✓ Passed

Advice Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #2

MOT test number

S55493672105

Result

MOT #1

2012-01-16 13:51

MOT #1	2012-01-16 13:51
MOT test number	367136512008
Result	✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	18 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category
Type

Damage 2

Date

Category Type



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downlo <u>here</u> .	

	More info >
Plate changes See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	NK SIK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-03-10
Last registration	2023-11-18
Complete history	See info



Registration #1	2009-03-10	14 mi
Registration #2	2012-01-16	33.991 mi
Registration #3	2012-06-21	35.398 mi
Registration #4	2013-06-10	47.853 mi
Registration #5	2014-05-31	61.372 mi
Registration #6	2015-06-11	74.826 mi
Registration #7	2015-06-13	74.875 mi
Registration #8	2016-06-08	87.982 mi
Registration #9	2017-05-15	97.368 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1777 mm
Height	1603 mm
Length	4270 mm
Wheel base	2778 mm
Kerb weight	1310 kg

Additional information

Fuel tank capacity	54 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	26694030573646

CarCheck.co.uk page 13/13