





report date: 2024-03-28

General information

Make	PEUGEOT
Model	108 ACTIVE
Colour	Purple
Year of manufacture	2018
Top speed	99 mph
0 - 60 mph	13.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	95 Nm at 4.300 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	56.5 mpg
Consumption extra urban	78.5 mpg
Consumption combined	68.9 mpg
CO2 emission	95 g/km
CO2 label	A



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 4

Date 2021-08-10

Pictures 21

Listing price <u>View report</u>









source: heycar.co.uk

Entry 3

Date 2021-08-01

Pictures 10

Listing price <u>View report</u>










source: autoonline.co.uk

Entry 2

Date 2021-07-23

Pictures 16

Listing price <u>View report</u>









source: yesauto.com

Entry 1

Pictures 12

Listing price <u>View report</u>

CarCheck.co.uk page 2/12









source: cargurus.co.uk



report date: 2024-03-28

MOT history

MOT expiry date	2024-08-17
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	17
Total items failed	0

MOT #6	2023-08-02 15:00
MOT test number	550871927781
Result	✓ Passed
Next expiry date	2024-08-17
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #5	2023-07-31 12:58	
MOT test number	478964454870	
Result	X Failed	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		
Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		
DANGEROUS Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))		

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #4 2022-08-18 12:43 **MOT** test number 692166179362 Result ✓ Passed **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Advice Offside Rear Nail in tyre **Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #3 2022-08-18 11:13 **MOT** test number 222919795688 Result × Failed **DANGEROUS** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii)) **Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Offside Rear Nail in tyre Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #2	2021-08-16 14:29
MOT test number	289342854344
Result	✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #1 2021-06-03 14:30 MOT test number 969386121889

Result ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	17 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Е
First licence fee (12 months)	£ 165,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



furthe scinors

BP18MBF

report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this PEUGEOT had different number plates. about of pliates

More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2018-06-08
Last registration	2023-08-02
Complete history	See info



Registration #1	2018-06-08	20 mi
Registration #2	2021-06-03	9.220 mi
Registration #3		11.777 es
Registration #4		71.777 66
Registration #5		11.777 es
Registration #6		71.777 66
Registration #7		D.777 es
Registration #8		71.777 66
Registration #9		11.777 mi
Registration #10		71.777 66
Registration #11		11.777 au

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Dimensions & weight

Width	1615 mm
Height	1460 mm
Length	3475 mm
Wheel base	2340 mm
Kerb weight	840 kg
Max. allowed weight	1240 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	8468735

CarCheck.co.uk page 12/12