





report date: 2024-03-28

General information

Make	HYUNDAI
Model	SANTA FE CRDI PREMIUM
Colour	Black
Year of manufacture	2012
Top speed	118 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	194 BHP
Max. torque	422 Nm at 2.500 rpm
Engine capacity	2.199 сс
Cylinders	4
Fuel type	Diesel
Consumption city	32.1 mpg
Consumption extra urban	50.4 mpg
Consumption combined	41.5 mpg
CO2 emission	176 g/km
CO2 label	I



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-10-18

Pictures 19

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	torv.
101	C I	1115	IUI V
	•		tory

MOT expiry date	2024-11-25
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	5
Total items failed	3

MOT #13	2023-11-18 14:04
MOT test number	463153622040
Result	✓ Passed
Next expiry date	2024-11-25

MOT #12	2022-10-29 14:05
MOT test number	893719656952
Result	✓ Passed

MOT #11	2021-11-15 10:58
MOT test number	970896783320
Result	✓ Passed

MOT #10		2021-11-15 10:58
MOT test number		451877259343
Result		× Failed
Pass with rectification	Offside Headlamp aim too low (4.1.2 (a))	

MOT #9	2020-11-26 12:20
MOT test number	732089095656
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #8 2019-11-22 11:44

MOT test number 838966313690

Result
✓ Passed

MOT #7 2018-09-05 14:28

MOT test number 230272271806

Result ✓ Passed

MOT #6 2018-09-05 10:39

MOT test number 319618943008

Result X Failed

MAJOR Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #5 2017-11-30 12:26

MOT test number 706585260953

Result

Passed

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Offside Front Suspension arm synthetic bush deteriorated but not resulting in excessive

movement (2.4.G.2)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Front Suspension arm synthetic bush deteriorated but not resulting in excessive

movement (2.4.G.2)

MOT #4 2016-12-05 12:05

MOT test number 371127605237

Result
✓ Passed

MOT #3 2016-01-26 12:29

MOT test number 862014128684

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #2		2015-01-26 11:40
MOT test number		749726225080
Result		✓ Passed
MOT #1		2015-01-26 11:40
MOT test number		506596825022
Result		X Failed
Pass with rectification	Nearside Front Headlamp aim too high (1.8)	
Pass with rectification	Offside Front Headlamp aim too high (1.8)	

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 November
Days left	186
MOT expiry date	25 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner	biotom
UWNEI	nisioiv

e when mistery	
For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
and the same of th	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	
Current registration	AIC
Plate since	
Current registration	NE N
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-01-31
Last registration	2023-11-18
Complete history	See info



Registration #1	2012-01-31	19 mi
Registration #2	2015-01-26	22.513 mi
Registration #3	2016-01-26	32.416 mi
Registration #4	2016-12-05	42.163 mi
Registration #5	2017-11-30	54.192 mi
Registration #6	2018-09-05	61.839 mi
Registration #7	2018-09-05	61.839 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



EN61XRY report date: 2024-03-28

Car features

50225	Air conditionin
50295	
50482	
60501	
60566	
60567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1890 mm
Height	1760 mm
Length	4660 mm
Wheel base	2700 mm
Kerb weight	1920 kg
Max. allowed weight	2570 kg

Additional information

Fuel tank capacity	70	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12