





report date: 2024-03-29

General information

Make	HONDA
Model	CR-V I-DTEC SE PLUS NAVI
Colour	Blue
Year of manufacture	2017
Top speed	113 mph
0 - 60 mph	11.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	300 Nm at 2.000 rpm
Engine capacity	1.597 cc
Cylinders	4
Fuel type	Diesel
Consumption city	61.4 mpg
Consumption extra urban	67.3 mpg
Consumption combined	64.2 mpg
CO2 emission	115 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 2

Date 2021-08-08


Pictures 7

Listing price <u>View report</u>









source: yesauto.com

Entry 1

Date 2021-08-05

Pictures 8

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

MOT expiry date	2024-08-30
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	11
Total items failed	4

MOT #5		2023-08-29 16:01
MOT test	number	730948967906
Result		✓ Passed
Next expi	ry date	2024-08-30
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #4	2023-08-29 11:34
MOT test number	833061478820
Result	× Failed
Fail Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #3	2022-08-31 14:25
MOT test number	462866414298
Result	✓ Passed
MOT #2	2021-08-18 08:11
MOT test number	767073820761
Result	✓ Passed
MOT #1	2020-10-29 10:26
MOT test number	658966641043
Result	✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 November
Days left	185
MOT expiry date	30 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full is	
manana and a same and	

	More info >
Plate changes	
See in this check if this HONDA had different number plates.	
Number of plates	,
Current registration	NIE NIE NIE
Plate since	
Current registration	NK SIK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-11-16
Last registration	2023-08-29
Complete history	See info



Registration #1	2017-11-16	6 mi
Registration #2	2020-10-29	30.427 mi
Registration #3		11.777 es
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Safety ratings

NCAP rating	****	
Adult	93%	
Children	74%	
Pedestrian	68%	
Safety systems	66%	
Overall rating	81%	
Video	see crash video	



Dimensions & weight

Width	1820 mm
Height	1685 mm
Length	4605 mm
Wheel base	2630 mm
Kerb weight	1592 kg
Max. allowed weight	2100 kg

Additional information

Fuel tank capacity	58 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	N16A23103755

CarCheck.co.uk page 11/11