



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	IX20 STYLE
Colour	Blue
Year of manufacture	2013
Top speed	104 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	137 Nm at 5.000 rpm
Engine capacity	1.396 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	50.4 mpg
CO2 emission	140 g/km
CO2 label	E







Internet history

Entry 1

Date	2021-09-09
Pictures	14
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-09-25
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	31
Total items failed	13

MOT #13	2023-09-26 15:32
MOT test number	562698774107
Result	✓ Passed
Next expiry date	2024-09-25
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #12	2023-09-14 06:58
MOT test number	250118965667
Result	✗ Failed
Fail	Nearside Front Outer Track rod end ball joint has excessive play (2.1.3 (b) (i))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Fail	Brake lever has insufficient reserve travel (1.1.2 (a))
Fail	Nearside Front Inner Steering linkage ball joint has excessive play (2.1.3 (b) (i))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #11**

2022-09-05 11:36

MOT test number

965119995606

Result

✓ Passed

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**MOT #10**

2021-09-17 07:30

MOT test number

171103047316

Result

✓ Passed

MOT #9

2021-09-16 14:01

MOT test number

653286815808

Result

✗ Failed

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #8**

2020-12-04 15:32

MOT test number

518475442417

Result

✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #7** 2020-11-27 11:44**MOT test number** 408783206789**Result** ✗ Failed**Fail** Nearside Front Windscreen washer not working (3.5 (a))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Front Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Offside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #6** 2019-05-28 15:34**MOT test number** 829954555387**Result** ✓ Passed**Advice** Rear Tyre slightly damaged/cracking or perishing both rear side wall perished/ cracking (5.2.3 (d) (ii))

**MOT #5** 2019-05-27 11:19**MOT test number** 794813083511**Result** ✗ Failed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Offside Parking brake inoperative on one side (1.4.1 (a))**Advice** Offside Rear handbrake lever not fully returning**MOT #4** 2018-05-30 16:14**MOT test number** 917724717351**Result** ✓ Passed**Advice** Offside Rear Nail in tyre**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge worn (5.2.3 (e))



MOT #3	2018-05-30 16:14
MOT test number	904573254621
Result	✗ Failed
<div>Pass with rectification</div> Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Advice	Offside Rear Nail in tyre
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Offside Front Tyre worn close to legal limit/worn on edge inner edge worn (5.2.3 (e))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))

MOT #2	2017-05-30 16:17
MOT test number	741803873872
Result	✓ Passed

MOT #1	2016-09-19 11:30
MOT test number	534370523286
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
25 September 2024

Tax status	Valid until 1 April
Days left	338
MOT expiry date	25 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-10-17
Last registration	2023-09-26
Complete history	See info



Registration #1	2013-10-17	21 mi
Registration #2	2016-09-19	13.197 mi
Registration #3	2017-05-30	15.081 mi
Registration #4	2018-05-30	22.108 mi
Registration #5	2018-05-30	22.108 mi
Registration #6	2019-05-27	26.593 mi
Registration #7	2019-05-28	26.607 mi
Registration #8	2020-11-27	32.724 mi
Registration #9	2020-11-27	32.724 mi
Registration #10	2020-11-27	32.724 mi
Registration #11	2020-11-27	32.724 mi
Registration #12	2020-11-27	32.724 mi
Registration #13	2020-11-27	32.724 mi
Registration #14	2020-11-27	32.724 mi
Registration #15	2020-11-27	32.724 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	85%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1600 mm
Length	4100 mm
Wheel base	2615 mm
Kerb weight	1268 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4FADZ542673