



report date: 2024-03-28

General information

Make	VOLVO
Model	V70 D3 SE
Colour	Silver
Year of manufacture	2010
Top speed	137 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	163 BHP
Max. torque	400 Nm at 1.400 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	51.4 mpg
CO2 emission	144 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-06-17
Pictures	48
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-03-03
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	13
Total items failed	7

MOT #16	2024-03-04 10:05
MOT test number	321069900060
Result	✓ Passed
Next expiry date	2025-03-03

MOT #15	2023-07-11 15:00
MOT test number	618163900998
Result	✓ Passed
Advice	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))

MOT #14	2023-07-11 08:23
MOT test number	590161837664
Result	✗ Failed
Advice	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))
Fail	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Minor	Nearside Rear Tyre obviously under inflated (5.2.3 (l))
Fail	Offside Front Outline marker lamp not working (4.2.1 (a) (ii))
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13** 2022-07-11 08:17**MOT test number** 776391219856**Result** ✓ Passed**MOT #12** 2021-08-11 12:20**MOT test number** 166642187821**Result** ✓ Passed**MOT #11** 2021-08-09 10:07**MOT test number** 195251931271**Result** ✗ Failed

**Fail** Nearside Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail** Offside Front All outline marker lamps not working (4.2.1 (a) (ii))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10** 2021-03-16 10:32**MOT test number** 812525438488**Result** ✓ Passed

**Advice** Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Offside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #9** 2020-03-09 10:20**MOT test number** 487958720198**Result** ✓ Passed**MOT #8** 2019-03-12 08:51**MOT test number** 241966789479**Result** ✓ Passed

**MOT #7** 2018-03-08 12:36**MOT test number** 906086527674**Result** ✓ Passed**MOT #6** 2018-03-08 08:53**MOT test number** 322560239147**Result** ✗ Failed

**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

**Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)

**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

**MOT #5** 2017-03-15 09:28**MOT test number** 731974191666**Result** ✓ Passed**MOT #4** 2016-03-17 09:54**MOT test number** 292761631777**Result** ✓ Passed**MOT #3** 2015-03-19 10:20**MOT test number** 745638875078**Result** ✓ Passed

**Notice** Under-trays fitted obscuring some underside components

**MOT #2** 2014-03-19 09:07**MOT test number** 895958074038**Result** ✓ Passed

**Notice** Under-trays fitted obscuring some underside components



MOT #1	2013-10-25 09:30
MOT test number	335358893490
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
3 March 2025

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	126
<b>MOT expiry date</b>	3 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-10-28
Last registration	2024-03-04
Complete history	<a href="#">See info</a>



Registration #1	2010-10-28	9 mi
Registration #2	2013-10-25	43.999 mi
Registration #3	2014-03-19	45.421 mi
Registration #4	2015-03-19	49.268 mi
Registration #5	2016-03-17	52.481 mi
Registration #6	2017-03-15	56.507 mi
Registration #7	2018-03-08	60.050 mi
Registration #8	2018-03-08	60.052 mi
Registration #9	2019-03-12	65.256 mi
Registration #10	2019-03-12	65.257 mi
Registration #11	2019-03-12	65.257 mi
Registration #12	2019-03-12	65.257 mi
Registration #13	2019-03-12	65.257 mi
Registration #14	2019-03-12	65.257 mi
Registration #15	2019-03-12	65.257 mi
Registration #16	2019-03-12	65.257 mi
Registration #17	2019-03-12	65.257 mi
Registration #18	2019-03-12	65.257 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	43%
Safety systems	71%
Overall rating	77%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2097 mm
Height	1484 mm
Length	4628 mm
Wheel base	2778 mm
Kerb weight	1643 kg
Max. allowed weight	2180 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

**Engine number**

870929