





### General information

Make	VAUXHALL
Model	VECTRA VVT EXCLUSIV
Colour	White
Year of manufacture	2008
Top speed	126 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 3.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.2 mpg
CO2 emission	173 g/km
CO2 label	Н







# Internet history

Entry 1	
Date	2022-02-11
Pictures	12
Listing price	View report



source: cargurus.co.uk



## MOT history

MOT expiry date	2025-02-01
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	11
Total items failed	8

MOT #18	2024-01-31 12:04
MOT test number	933533245515
Result	✓ Passed
Next expiry date	2025-02-01

MOT #17		2024-01-31 12:04
MOT test number		435707504098
Result		🗙 Failed
Pass with rectification	Nearside Rear Direction indicator incorrect colour (4.4.3 (a))	
Pass with rectification	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))	

MOT #16	2023-01-18 15:12
MOT test number	332887093605
Result	✓ Passed

MOT #15	2023-01-17 09:06	
MOT test number	387003030451	
Result	🗙 Failed	
<b>Fail</b> Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))		
<b>Fail</b> Offside Front Coil spring fractured or broken (5.3.1 (b) (i))		



HV58	MKJ
report date:	2024-03-29

2021-05-18 08:21

MOT #14		2022-02-02 11:01
MOT test	number	136030457542
Result		✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Nearside Front Nail in tyre	

# MOT #13

MOT test	<b>number</b> 387629	311639
Result	· · · · · · · · · · · · · · · · · · ·	Passed
Advice Nearside Front Tyre slightly damaged/cracking or perishing cracking in tread (5.2.3 (d) (ii))		
Advice	Offside Front Tyre slightly damaged/cracking or perishing cracking in tread (5.2.3 (d) (ii))	

MOT #12	2020-05-26 08:32
MOT test number	570552423067
Result	✓ Passed

MOT #11	2019-04-23 09:39
MOT test number	928908893710
Result	✓ Passed

MOT #10	2018-04-23 14:59
MOT test number	107749922960
Result	✓ Passed
Advice Front tyres starting to perish	



MOT #9	2018-04-23 14:01
MOT test number	190905520395
Result	🗙 Failed
Fail Offside Rear coil spring broken (2.4.C.1a)	
Advice Front tyres starting to perish	
MOT #8	2017-04-26 14:37
MOT test number	718443419395
Result	✓ Passed
MOT #7	2016-07-13 15:48
MOT test number	597167703968
Result	✓ Passed
MOT #6	2015-07-18 11:37
MOT test number	217429895474
Result	🗸 Passed

MOT #5	2014-08-18 14:42
MOT test number	315000034468
Result	✓ Passed

MOT #4	2013-08-29 15:36
MOT test number	375701843286
Result	✓ Passed

HV58MKJ

report date: 2024-03-29





MOT #3	2013-08-29 15:36
MOT test number	377831043424
Result	× Failed
Pass with rectification	Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)
Pass with rectification	Offside Headlamp aim too high (1.8)
Pass with rectification	Nearside Headlamp aim too high (1.8)

MOT #2	2012-09-01 11:20
MOT test number	787235042222
Result	✓ Passed

MOT #1		2011-08-17 15:42
MOT test	number	587249221222
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Rear Direction indicators slightly discoloured (1.4.A.2f)	
Notice	Nail in nearside front tyre	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	



Tax & MOT check

✓ Taxed	✓ MOT
<b>Tax due:</b> 1 May 2025	<b>Expires:</b> 1 February 2025
Tax status	Valid until 1 May
Days left	366
MOT expiry date	1 February 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-





#### Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FET A
Category	L AMP
Туре	
Damage 2	AMPLE
Date	4
Category	AMPL
Туре	

#### Extra VAUXHALL salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





## Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

**********	
AND	
**********	
********	
	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





#### Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-10-31
Last registration	2024-01-31
Complete history	See info



Registration #1	2008-10-31	18 mi
Registration #2	2011-08-17	20.025 mi
Registration #3	2012-09-01	24.895 mi
Registration #4	2013-08-29	28.214 mi
Registration #5	2014-08-18	31.705 mi
Registration #6	2015-07-18	34.028 mi
Registration #7	2016-07-13	36.170 mi
Registration #8	2017-04-26	37.405 mi
Registration #9	2018-04-23	45.019 mi
Registration #10	2018-04-23	45.019 mi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		11.777 mi
Registration #19		11.117 esi





Safety ratings

NCAP rating

Video

see crash video



2036 mm
1460 mm
4596 mm
2700 mm
1350 kg
1885 kg
61
Multi-Point Injection
5
5
20KV4564