



report date: 2024-03-28

General information

Make	VOLVO
Model	S60 D3 SE LUX
Colour	Silver
Year of manufacture	2013
Top speed	127 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	350 Nm at 2.250 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C







Internet history

Entry 3

Date	2021-07-24
Pictures	16
Listing price	View report



source: yesauto.com

Entry 2

Date	2021-07-02
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 1

Date	2021-07-02
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-20
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	10
Total items failed	4

MOT #10	2023-05-19 13:19
MOT test number	957665424866
Result	✓ Passed
Next expiry date	2024-05-20

MOT #9	2023-05-16 10:13
MOT test number	354106226977
Result	✗ Failed
Fail	Front Brake pad(s) worn down to wear indicator axle 1 (1.1.13 (a) (i))
Fail	Front Brake disc significantly and obviously worn axle 1 (1.1.14 (a) (i))

MOT #8	2022-05-20 10:48
MOT test number	361950562586
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #7** 2021-05-21 13:35**MOT test number** 174424136378**Result** ✓ Passed

- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Coil spring corroded both sides (5.3.1 (b) (i))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened all 4 (1.1.14 (a) (ii))
- Advice** Rear Outer Suspension arm pin or bush worn but not resulting in excessive movement both trailing arms (5.3.4 (a) (i))

MOT #6 2019-02-11 14:24**MOT test number** 575720662170**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5 2019-02-11 14:24**MOT test number** 415022339599**Result** ✗ Failed

- Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4 2018-02-21 10:26**MOT test number** 236139592390**Result** ✓ Passed**MOT #3** 2018-02-21 10:25**MOT test number** 940549834208**Result** ✗ Failed

- Pass with rectification** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)



MOT #2	2017-02-22 12:07
MOT test number	141909687708
Result	✓ Passed

MOT #1	2016-02-26 15:48
MOT test number	942598889246
Result	✓ Passed

Advice Rear Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
20 May 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	20 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-05-01
Last registration	2023-05-19
Complete history	See info



Registration #1	2013-05-01	11 mi
Registration #2	2016-02-26	80.331 mi
Registration #3	2017-02-22	94.754 mi
Registration #4	2018-02-21	106.668 mi
Registration #5	2018-02-21	106.668 mi
Registration #6	2019-02-11	124.727 mi
Registration #7	2019-02-11	124.727 mi
Registration #8	2019-02-11	124.727 mi
Registration #9	2019-02-11	124.727 mi
Registration #10	2019-02-11	124.727 mi
Registration #11	2019-02-11	124.727 mi
Registration #12	2019-02-11	124.727 mi
Registration #13	2019-02-11	124.727 mi
Registration #14	2019-02-11	124.727 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	see crash video



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2776 mm
Kerb weight	1605 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number	1259958
---------------	---------