



report date: 2024-03-29

General information

Make	MAZDA
Model	MX-5 I
Colour	Grey
Year of manufacture	2006
Top speed	122 mph
0 - 60 mph	9.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	124 BHP
Max. torque	166 Nm at 4.500 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.5 mpg
Consumption extra urban	48.7 mpg
Consumption combined	38.7 mpg
CO2 emission	174 g/km
CO2 label	H





Internet history

Entry 2

Date	2021-02-01
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)

Entry 1

Date	2021-01-21
Pictures	10
Listing price	View report



source: [yesauto.com](#)



MOT history

MOT expiry date	2025-04-24
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	17
Total items failed	11

MOT #21	2024-04-25 12:38
MOT test number	256763925184
Result	✓ Passed
Next expiry date	2025-04-24
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #20	2024-04-22 13:34
MOT test number	302375251334
Result	✗ Failed
Fail	Offside Side repeater not working (4.4.1 (a) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Fail	Offside Rear Subframe mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Fail	Nearside Rear Subframe mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))

**MOT #19** 2023-04-13 08:48**MOT test number** 236132079849**Result** ✓ Passed**MOT #18** 2022-04-14 11:57**MOT test number** 626138906412**Result** ✓ Passed**MOT #17** 2021-03-01 12:58**MOT test number** 811029720088**Result** ✓ Passed**MOT #16** 2020-08-08 10:07**MOT test number** 580775492173**Result** ✓ Passed**Advice** Exhaust emits blue smoke during acceleration (8.2.1.2 (g))**Advice** Exhaust emissions excessively erratic, only just through emissions test**MOT #15** 2019-08-08 14:28**MOT test number** 564645052696**Result** ✓ Passed**MOT #14** 2019-08-08 10:44**MOT test number** 242357274716**Result** ✗ Failed**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Front Service brake excessively binding (1.2.1 (f))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #13** 2018-08-07 14:29**MOT test number** 313666257867**Result** ✓ Passed**MOT #12** 2018-08-06 11:23**MOT test number** 104336604120**Result** ✗ Failed**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Front Service brake excessively binding (1.2.1 (f))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Anti-roll bar linkage insecurely attached (5.3.3 (a) (i))**MOT #11** 2017-07-19 16:01**MOT test number** 104291552973**Result** ✓ Passed**MOT #10** 2016-08-02 10:04**MOT test number** 391133443513**Result** ✓ Passed**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #9** 2015-07-29 15:33**MOT test number** 868560315253**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #8** 2015-07-28 13:40**MOT test number** 749689305292**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #7** 2014-08-11 12:25**MOT test number** 386973524278**Result** ✓ Passed**MOT #6** 2014-08-11 12:25**MOT test number** 227943224287**Result** ✗ Failed**Pass with rectification** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)**MOT #5** 2013-06-25 11:22**MOT test number** 249126573472**Result** ✓ Passed**MOT #4** 2012-07-05 10:07**MOT test number** 279357082168**Result** ✓ Passed**MOT #3** 2011-07-04 10:57**MOT test number** 386955281184**Result** ✓ Passed



MOT #2	2010-06-19 09:14
MOT test number	170500470109
Result	✓ Passed
MOT #1	2009-06-23 10:18
MOT test number	612754979105
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
24 April 2025

Tax status	Valid until 1 September
Days left	125
MOT expiry date	24 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2006-07-05
Last registration	2024-04-25
Complete history	See info



Registration #1	2006-07-05	29 mi
Registration #2	2009-06-23	14.035 mi
Registration #3	2010-06-19	22.982 mi
Registration #4	2011-07-04	26.466 mi
Registration #5	2012-07-05	28.474 mi
Registration #6	2013-06-25	30.470 mi
Registration #7	2014-08-11	35.564 mi
Registration #8	2015-07-28	43.569 mi
Registration #9	2015-07-29	43.572 mi
Registration #10	2016-08-02	56.018 mi
Registration #11	2017-07-19	63.760 mi
Registration #12	2018-08-06	69.585 mi
Registration #13	2019-08-06	75.410 mi
Registration #14	2020-08-06	81.235 mi
Registration #15	2021-08-06	87.060 mi
Registration #16	2022-08-06	92.885 mi
Registration #17	2023-08-06	98.710 mi
Registration #18	2024-04-25	104.535 mi
Registration #19	2024-04-25	104.535 mi
Registration #20	2024-04-25	104.535 mi
Registration #21	2024-04-25	104.535 mi
Registration #22	2024-04-25	104.535 mi
Registration #23	2024-04-25	104.535 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1680 mm
Height	1225 mm
Length	3975 mm
Wheel base	2265 mm
Max. allowed weight	1365 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	L8322559