



PEUGEOT




report date: 2024-03-29

General information

Make	PEUGEOT
Model	307 S HDI
Colour	Blue
Year of manufacture	2005
Top speed	111 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	215 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	65.7 mpg
Consumption combined	57.7 mpg
CO2 emission	129 g/km
CO2 label	D





Internet history

**Entry 1**

Date	2021-07-05
Pictures	8
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-11-01
MOT pass rate	64 %
MOT passed	16
Failed MOT tests	9
Total advice items	80
Total items failed	20

MOT #25 2023-10-27 16:03

MOT test number 819931763555

Result ✔ Passed

Next expiry date 2024-11-01

- Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

MOT #24 2022-11-01 12:45

MOT test number 535177700861

Result ✔ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



MOT #23 2022-10-31 10:52

MOT test number 122355298245

Result ✗ Failed

- Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #22 2021-11-02 11:53

MOT test number 896392304176

Result ✓ Passed

- Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Suspension component mounting prescribed area is corroded but not considered excessive offside & nearside underbody / chassis leg (5.3.6 (a) (i))
- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))



MOT #21 2021-11-01 12:05

MOT test number 133798072055

Result ✗ Failed

**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Advice** Rear Suspension component mounting prescribed area is corroded but not considered excessive offside & nearside underbody / chassis leg (5.3.6 (a) (i))

**Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

**Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))

**Fail** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))

**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #20 2020-10-26 10:48

MOT test number 568448147915

Result ✓ Passed

**Advice** Offside Inner Suspension rod ball joint has slight play RACK JOINT (5.3.4 (a) (i))

**Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))



<b>MOT #19</b>	2019-10-28 13:45
<b>MOT test number</b>	336753961054
<b>Result</b>	✓ Passed
<b>Minor</b>	Offside Headlamp lens slightly defective (4.1.1 (b) (i))
<b>Minor</b>	Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
<b>Minor</b>	Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

<b>MOT #18</b>	2019-10-28 13:45
<b>MOT test number</b>	649328363622
<b>Result</b>	✗ Failed
<b>Minor</b>	Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
<b>Pass with rectification</b>	Nearside Headlamp aim too high (4.1.2 (a))
<b>Minor</b>	Offside Headlamp lens slightly defective (4.1.1 (b) (i))
<b>Pass with rectification</b>	Offside Headlamp aim too high (4.1.2 (a))
<b>Minor</b>	Nearside Headlamp lens slightly defective (4.1.1 (b) (i))

<b>MOT #17</b>	2018-10-23 11:51
<b>MOT test number</b>	819994959414
<b>Result</b>	✓ Passed
<b>Minor</b>	Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
<b>Minor</b>	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
<b>Minor</b>	Offside Headlamp lens slightly defective (4.1.1 (b) (i))



**MOT #16** 2018-10-22 10:52

**MOT test number** 476424734481

**Result** ✗ Failed

- Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))
- Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #15** 2017-10-02 11:47

**MOT test number** 895874436750

**Result** ✓ Passed

- Advice** Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)
- Advice** Nearside Rear tyre worn on edge

**MOT #14** 2017-10-02 11:47

**MOT test number** 319402322200

**Result** ✗ Failed

- Advice** Nearside Rear tyre worn on edge
- Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)
- Pass with rectification** Nearside Rear Inner Rear position lamp(s) not working (1.1.A.3b)
- Advice** Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)



**MOT #13** 2016-10-17 13:58

**MOT test number** 275574931188

**Result** ✔ Passed

- Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Nearside Front Direction indicator slightly discoloured (1.4.A.2f)

**MOT #12** 2016-10-17 13:58

**MOT test number** 281415033580

**Result** ✘ Failed

- Pass with rectification** Offside Stop lamp not working (1.2.1b)
- Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Nearside Front Direction indicator slightly discoloured (1.4.A.2f)

**MOT #11** 2015-10-19 11:45

**MOT test number** 828012270460

**Result** ✔ Passed

- Advice** Slight play in steering inner joints
- Advice** Oil leak

**MOT #10** 2015-10-19 09:26

**MOT test number** 307079344863

**Result** ✘ Failed

- Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords outer sidewall (4.1.D.1a)
- Advice** Slight play in steering inner joints
- Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords inner sidewall (4.1.D.1a)
- Advice** Oil leak



<b>MOT #9</b>	2014-10-14 10:32
<b>MOT test number</b>	986687784252
<b>Result</b>	✓ Passed

<b>MOT #8</b>	2013-10-16 10:29
<b>MOT test number</b>	968859383298
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
<b>Advice</b>	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
<b>Advice</b>	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
<b>Advice</b>	Offside Front Tyre worn close to the legal limit (4.1.E.1)

<b>MOT #7</b>	2012-10-30 14:35
<b>MOT test number</b>	446814602346
<b>Result</b>	✓ Passed
<b>Notice</b>	O/s/f tyre scrubbing
<b>Notice</b>	Rear axle bushes perished
<b>Notice</b>	Nail in nearside rear tyre

<b>MOT #6</b>	2012-10-30 12:30
<b>MOT test number</b>	295394902317
<b>Result</b>	✗ Failed
<b>Notice</b>	Rear axle bushes perished
<b>Notice</b>	Nail in nearside rear tyre
<b>Fail</b>	Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)
<b>Notice</b>	O/s/f tyre scrubbing



<b>MOT #5</b>	2011-10-24 10:52
<b>MOT test number</b>	707677591216
<b>Result</b>	✓ Passed

<b>MOT #4</b>	2010-10-15 10:26
<b>MOT test number</b>	932918780289
<b>Result</b>	✗ Failed

- Notice** Exhaust manifold heat sheild loose
- Advice** Offside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)
- Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)
- Notice** Wipers leave slight smear
- Advice** Nearside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)
- Notice** Engine under guard fitted obstructing view
- Pass with rectification** Nearside Headlamp aim too low (1.8)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

<b>MOT #3</b>	2010-10-15 10:26
<b>MOT test number</b>	514658380219
<b>Result</b>	✓ Passed

- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Offside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)
- Notice** Exhaust manifold heat sheild loose
- Advice** Nearside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)
- Notice** Wipers leave slight smear
- Notice** Engine under guard fitted obstructing view



**MOT #2** 2009-10-13 12:33

**MOT test number** 964816589257

**Result** ✓ Passed

**MOT #1** 2008-10-28 09:01

**MOT test number** 581332908362

**Result** ✓ Passed

**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 May 2025

✓  
**MOT**

**Expires:**  
1 November 2024

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	367
<b>MOT expiry date</b>	1 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-




Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



**Vehicle valuation**

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

**More info** >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	LT55YFE
Plate since	2024-03-29
Current registration	LT55YFE
Plate since	2024-03-29

More info >



**Finance check**

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.


<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



Mileage check

<b>Odometer</b>	In miles
<b>Mileage registrations</b>	26
<b>First mileage registration</b>	2005-09-21
<b>Last registration</b>	2023-10-27
<b>Complete history</b>	<a href="#">See info</a>



<b>Registration #1</b>	2005-09-21	6 mi
<b>Registration #2</b>	2008-10-28	51.345 mi
<b>Registration #3</b>	2009-10-13	66.511 mi
<b>Registration #4</b>	2010-10-15	81.811 mi
<b>Registration #5</b>	2011-10-24	94.809 mi
<b>Registration #6</b>	2012-10-30	106.378 mi
<b>Registration #7</b>	2012-10-30	106.380 mi
<b>Registration #8</b>	2013-10-16	115.989 mi
<b>Registration #9</b>	2014-10-14	126.228 mi
<b>Registration #10</b>	2015-10-19	137.295 mi
<b>Registration #11</b>	2015-10-19	137.298 mi
<b>Registration #12</b>	2016-10-17	150.179 mi
<b>Registration #13</b>	2016-10-17	150.179 mi
<b>Registration #14</b>	2016-10-17	150.179 mi
<b>Registration #15</b>	2016-10-17	150.179 mi
<b>Registration #16</b>	2016-10-17	150.179 mi
<b>Registration #17</b>	2016-10-17	150.179 mi
<b>Registration #18</b>	2016-10-17	150.179 mi
<b>Registration #19</b>	2016-10-17	150.179 mi
<b>Registration #20</b>	2016-10-17	150.179 mi
<b>Registration #21</b>	2016-10-17	150.179 mi
<b>Registration #22</b>	2016-10-17	150.179 mi
<b>Registration #23</b>	2016-10-17	150.179 mi
<b>Registration #24</b>	2016-10-17	150.179 mi
<b>Registration #25</b>	2016-10-17	150.179 mi
<b>Registration #26</b>	2016-10-17	150.179 mi

**More info** >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1746 mm
Height	1512 mm
Length	4202 mm
Wheel base	2608 mm
Kerb weight	1306 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

---

**Engine number**

JB390064134