





report date: 2024-03-28

General information

Make	BMW
Model	518 518D SE
Colour	Silver
Year of manufacture	2013
Top speed	132 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	141 BHP
Max. torque	360 Nm at 1.750 rpm
Engine capacity	1.995 сс
Cylinders	4
Fuel type	Diesel
Consumption city	52.3 mpg
Consumption extra urban	70.6 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 5

Date 2024-02-05

Pictures 0

Listing price View report

source: carcraft.co.uk

Entry 4

Date 2024-01-09

Pictures

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 3

Date 2021-09-02

Pictures 9

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 2

Date	2021-09-01
Pictures	9

Listing price <u>View report</u>

CarCheck.co.uk page 2/12









source: autotrader.co.uk

Entry 1

Date	2021-06-14	
Pictures	1	
Listing price	<u>View report</u>	



source: autotrader.co.uk



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	torv.
101	C I	1115	IUI V
	•		tory

MOT expiry date	2025-02-17
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	14
Total items failed	3

MOT #12	2024-02-09 10:16
MOT test number	476896245834
Result	✓ Passed
Next expiry date	2025-02-17

MOT #11	2024-02-07 10:49
MOT test number	486003491700
Result	★ Failed
Fail Offside Front Position	amp with a multiple light source more than 1/2 not functioning (4.2.1 (a) (ii))

MOT #10	2023-02-07 09:41
MOT test number	439761683735
Result	✓ Passed
MOT #9	2022-02-18 15:57
MOT test number	805209773807
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT test number

Result

Advice Nearside Rear Tyre worn close to legal limit/worn on edge Inner edge (5.2.3 (e))

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge Inner edge (5.2.3 (e))

 MOT #7
 2020-10-30 16:37

 MOT test number
 780827074263

 Result
 ✓ Passed

MOT #6 2019-12-20 12:52 **MOT** test number 752668237480 Result ✓ Passed **Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

		2010 10 10 12 00
MOT #5		2018-12-19 13:02
MOT test	number	691739029556
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #4	2017-12-14 10:43
MOT test number	807131535964
Result	✓ Passed
MOT #3	2016-12-23 11:30
MOT test number	769753948738
Result	✓ Passed
MOT #2	2016-11-17 17:03
MOT test number	783768709090
Result	★ Failed
Advice Offside Rear Tyre worn close to the legal limit 2mm (4.1.E.1)	
Advice Both front tyre starting to wear outer edges	
Fail Nearside Rear Inner Tyre has ply or cords exposed (4.1.D.1b)	

MOT #1		2016-09-20 09:44
MOT test	number	387654720853
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 February
Days left	279
MOT expiry date	17 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra BMW salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report		ve?

	More info	>
Plate changes		
See in this check if this BMW had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK MIS MIS	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2013-09-27
Last registration	2024-02-09
Complete history	See info



Registration #1	2013-09-27	7 mi
Registration #2	2016-09-20	25.987 mi
Registration #3	2016-11-17	26.907 mi
Registration #4	2016-12-23	26.918 mi
Registration #5	2017-12-14	35.958 mi
Registration #6	2018-12-19	44.845 mi
Registration #7	2019-12-20	54.137 mi
Registration #8	2020-10-30	61.155 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	95%
Children	83%
Pedestrian	78%
Safety systems	100%
Overall rating	90%
Video	see crash video



Dimensions & weight

Width	1860 mm
Height	1475 mm
Length	4907 mm
Wheel base	2968 mm
Kerb weight	1615 kg
Max. allowed weight	2225 kg

Additional information

Fuel tank capacity	70 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5 p	age 12/12

Number of axles 2

Engine number 88598715