



report date: 2024-03-28

General information

Make	VOLVO
Model	V70 D4 SE LUX
Colour	Silver
Year of manufacture	2015
Top speed	137 mph
0 - 60 mph	8.1 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	178 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	67.3 mpg
Consumption combined	60.1 mpg
CO2 emission	122 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-02-06
Pictures	2
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-02-17
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	8
Total items failed	3

MOT #9 2024-01-31 12:45

MOT test number 101248099727

Result ✓ Passed

Next expiry date 2025-02-17

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))

MOT #8 2023-02-06 14:25

MOT test number 583045980741

Result ✓ Passed

MOT #7 2022-02-15 15:04

MOT test number 946995743981

Result ✓ Passed

MOT #6 2021-02-18 11:10

MOT test number 496931741851

Result ✓ Passed

**MOT #5** 2021-02-12 14:12**MOT test number** 418320676850**Result** ✗ Failed

Fail Offside Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Advice Offside Rear Outer Tyre slightly damaged/cracking or perishing distorted inner and nail in tread (5.2.3 (d) (ii))

MOT #4 2020-06-23 14:37**MOT test number** 103487338470**Result** ✓ Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3 2020-06-23 08:40**MOT test number** 869762051138**Result** ✗ Failed

Fail Central Rear Seat belt retracting mechanism defective (7.1.2 (e))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #2 2019-06-20 08:48**MOT test number** 751125908529**Result** ✓ Passed**MOT #1** 2018-06-12 11:06**MOT test number** 499615070342**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
17 February 2025

Tax status	Valid until 1 February
Days left	278
MOT expiry date	17 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-28
Current registration	 XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-06-30
Last registration	2024-01-31
Complete history	See info



Registration #1	2015-06-30	17 mi
Registration #2	2018-06-12	32.597 mi
Registration #3	2019-06-20	40.092 mi
Registration #4	2020-06-23	46.685 mi
Registration #5	2020-06-23	46.685 mi
Registration #6	2020-06-23	46.685 mi
Registration #7	2020-06-23	46.685 mi
Registration #8	2020-06-23	46.685 mi
Registration #9	2020-06-23	46.685 mi
Registration #10	2020-06-23	46.685 mi
Registration #11	2020-06-23	46.685 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	43%
Safety systems	71%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	2106 mm
Height	1547 mm
Length	4814 mm
Wheel base	2816 mm
Kerb weight	1757 kg
Max. allowed weight	2290 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1290784