



report date: 2024-03-28

General information

Make	NISSAN
Model	ALMERA SE
Colour	Beige
Year of manufacture	2005
Top speed	108 mph
0 - 60 mph	13.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	121 BHP
Max. torque	128 Nm at 2.800 rpm
Engine capacity	1.497 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.8 mpg
CO2 emission	160 g/km
CO2 label	G






Internet history

Entry 1

Date	2022-03-02
Pictures	36
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-04-01
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	30
Total items failed	12

MOT #20	2022-03-30 16:16
MOT test number	869189564172
Result	✓ Passed
Next expiry date	2023-04-01
Advice	Rear Shock absorbers has light misting of oil both (5.3.2 (b))

MOT #19	2021-03-15 11:33
MOT test number	796235143323
Result	✓ Passed
Advice	Nearside Front Outer Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Power steering component has slight seepage from a component Rack (2.1.5 (a))
Advice	Offside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))
Advice	Offside Front Outer Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))
Advice	Offside Rear Brake disc back plate corroded

**MOT #18**

2021-03-15 08:51

MOT test number

495597694734

Result**✗ Failed****Fail** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))**Advice** Nearside Front Outer Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Power steering component has slight seepage from a component Rack (2.1.5 (a))**Advice** Offside Rear Brake disc back plate corroded**Advice** Offside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Offside Front Outer Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))**MOT #17**

2020-03-20 13:40

MOT test number

306486354326

Result**✓ Passed****Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #16**

2020-03-19 11:46

MOT test number

886741962872

Result**✗ Failed****Fail** Nearside Headlamp light intensity severely reduced (4.1.4 (a))**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Fail** Offside Front Service brake excessively binding (1.2.1 (f))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))

**MOT #15** 2019-04-02 11:45**MOT test number** 724666662470**Result** ✓ Passed**Advice** Oil leak, but not excessive From sump-corroded and porous (8.4.1 (a) (i))**MOT #14** 2018-02-20 11:31**MOT test number** 328009391285**Result** ✓ Passed**MOT #13** 2017-02-28 11:07**MOT test number** 155274549996**Result** ✓ Passed**Advice** Central Rear seat belt not checked.not able to access.**Advice** Offside Front tyre worn on edge/worn close to limit**MOT #12** 2016-03-03 13:30**MOT test number** 217584861734**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit and craking (4.1.E.1)

**MOT #11**

2016-03-02 16:31

MOT test number

611898410468

Result**✗ Failed****Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Offside Rear Stop lamp not working (1.2.1b)**Advice** Offside Rear Tyre worn close to the legal limit and craking (4.1.E.1)**Fail** Nearside Rear rear parking brake recording little or no effort (3.7.B.6a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #10**

2015-09-05 09:45

MOT test number

146477578342

Result**✓ Passed****Advice** Brake disc worn, pitted or scored, but not seriously weakened both side front (3.5.1i)**MOT #9**

2015-09-05 09:45

MOT test number

561115691537

Result**✗ Failed****Advice** Brake disc worn, pitted or scored, but not seriously weakened both side front (3.5.1i)**Pass with rectification** Front position lamp(s) not working o/s/f (1.1.A.3b)**MOT #8**

2014-10-22 13:18

MOT test number

207115894294

Result**✓ Passed****Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #7** 2013-10-18 14:50**MOT test number** 728141093281**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2012-10-19 16:43**MOT test number** 617793192214**Result** ✓ Passed**MOT #5** 2012-10-19 10:18**MOT test number** 458723592278**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #4** 2011-10-21 13:49**MOT test number** 725134391287**Result** ✓ Passed**MOT #3** 2010-10-19 12:30**MOT test number** 964402690240**Result** ✓ Passed



MOT #2	2009-10-19 13:21
MOT test number	391072599485
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2008-10-13 11:26
MOT test number	363367788423
Result	✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
31 August 2022

✕
MOT

Expired:
1 April 2023

Tax status	Expired at 31 August 2022
Days left	606 days too late
MOT expiry date	1 April 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-10-28
Last registration	2022-03-30
Complete history	See info



Registration #1	2005-10-28	8 mi
Registration #2	2008-10-13	13.077 mi
Registration #3	2009-10-19	21.259 mi
Registration #4	2010-10-19	29.399 mi
Registration #5	2011-10-21	37.533 mi
Registration #6	2012-10-19	45.811 mi
Registration #7	2012-10-19	45.811 mi
Registration #8	2013-10-18	53.407 mi
Registration #9	2014-10-22	63.037 mi
Registration #10	2015-09-05	77.545 mi
Registration #11	2015-09-05	77.545 mi
Registration #12	2016-09-05	86.177 mi
Registration #13	2017-09-05	94.809 mi
Registration #14	2018-09-05	103.441 mi
Registration #15	2019-09-05	112.073 mi
Registration #16	2020-09-05	120.705 mi
Registration #17	2021-09-05	129.337 mi
Registration #18	2022-03-30	137.969 mi
Registration #19	2022-03-30	137.969 mi
Registration #20	2022-03-30	137.969 mi
Registration #21	2022-03-30	137.969 mi
Registration #22	2022-03-30	137.969 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1706 mm
Height	1448 mm
Length	4184 mm
Wheel base	2535 mm
Kerb weight	1190 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	319019