





report date: 2024-03-29

# General information

Make	VOLKSWAGEN
Model	EOS SPORT FSI
Colour	Blue
Year of manufacture	2006
Top speed	144 mph
0 - 60 mph	7.8 seconds
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	197 BHP
Max. torque	280 Nm at 5.000 rpm
Engine capacity	1.984 сс
Cylinders	4
Fuel type	Petrol
Consumption city	24.8 mpg
Consumption extra urban	42.8 mpg
Consumption combined	33.6 mpg
CO2 emission	202 g/km
CO2 label	K



CarCheck.co.uk page 1/12




**VEZ1400**report date: 2024-03-29

# Internet history

## Entry 1

Date	2021-09-11
Pictures	1
Listing price	View report



source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2024-07-03
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	19
Total items failed	6

MOT #20	2023-07-04 07:38
MOT test number	812082634572
Result	<b>✓</b> Passed
Next expiry date	2024-07-03

MOT #19	2022-08-18 14:34
MOT test number	529669504015
Result	<b>✓</b> Passed
Advice Offside rear tyre out of shape and low inner edge	

MOT #18	2022-08-18 11:57
MOT test number	167117356254
Result	<b>X</b> Failed
Fail Offside Side repeater light intensity significantly reduced (4.4.3 (a))  Advice Offside rear tyre out of shape and low inner edge	

MOT #17	2021-08-24 09:47
MOT test number	190730453471
Result	<b>✓</b> Passed
Minor Offside Side repeater with a multiple light source up to 1/2 not for	functioning (4.4.1 (a) (i))
Advice Front Brake disc worn, pitted or scored, but not seriously weak	ened (1.1.14 (a) (ii))

CarCheck.co.uk page 3/12



report date: 2024-03-29

 MOT #16
 2021-08-23 09:32

 MOT test number
 659502710025

**Result** X Failed

Fail Offside Front Suspension arm pin or bush excessively worn back bush. (5.3.4 (a) (i))

Minor Offside Side repeater with a multiple light source up to 1/2 not functioning (4.4.1 (a) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Nearside Front Suspension arm pin or bush excessively worn back bush. (5.3.4 (a) (i))

**MOT #15** 2019-06-25 14:08

**MOT test number** 389678331864

Result \( \sqrt{Passed} \)

MOT #14 2019-06-25 11:56

**MOT test number** 974879478568

**Result** X Failed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #13 2018-06-25 15:48

**MOT test number** 236135915694

**Result** 
✓ Passed

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear. (5.3.4 (a) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear. (5.3.4 (a) (i))

CarCheck.co.uk page 4/12



(2.4.G.2)

(2.4.G.2)

**MOT** test number

**VEZ1400** 

report date: 2024-03-29

589073515050

**MOT #12** 2017-05-19 08:45

**MOT test number** 968431989447

**Result** ✓ Passed

Advice Nearside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

**Advice** Front Suspension arm rubber bush deteriorated but not resulting in excessive movement both sides rear bushes on front arms (2.4.G.2)

**MOT #11** 2016-06-22 14:01

MOT test number 879711174089

**Result** ✓ Passed

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement

MOT #10 2015-06-15 13:52 MOT test number 429316165139

Result 

Passed

**MOT #9** 2015-01-13 09:47

MOT #8 2014-01-14 15:47

**MOT test number** 629134214037

Result 

Passed

MOT #7 2013-06-21 15:44

MOT test number 825552173165

Result \( \sqrt{Passed} \)

**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)

**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)

CarCheck.co.uk page 5/12



report date: 2024-03-29

MOT #6	2013-06-21 09:50
MOT test number	278042973415
Result	<b>×</b> Failed
Advice Rear Brake pad(s) wearing thin (3.5.1g)	
Advice Offside Front Shock absorber has a light misting of oil (2.7.3)	
Fail Supplementary Restraint System warning lamp indicates a fault (5.4.2)	
Advice Nearside Front Shock absorber has a light misting of oil (2.7.3)	

MOT #5	2012-07-13 08:44
MOT test number	117384292193
Result	✓ Passed
MOT #4	2011-06-20 11:31
MOT test number	826481571192
Result	✓ Passed
MOT #3	2010-07-07 12:07
MOT test number	261278280444
Result	✓ Passed
MOT #2	2010-07-07 12:07
MOT test number	794838080191
Result	× Failed
Pass with rectification Front Head	dlamp aim too high (1.8)

MOT #1	2009-06-11 15:43
MOT test number	934362069156
Result	✓ Passed
Notice Both front tyres ON legal limit.	

CarCheck.co.uk page 6/12



report date: 2024-03-29

## Tax & MOT check





Tax status	Expired at 1 January 2024
Days left	118 days too late
MOT expiry date	3 July 2024
Full MOT history	See MOT history

# Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/12



report date: 2024-03-29

## Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.

#### Damage 1

Date	
Category	
Туре	

#### Damage 2

Date	
Category	





#### Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

More info >

# Owner history For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this VOLKSWAGEN had different number plates. mber of plates. -

CarCheck.co.uk page 9/12



VEZ1400
report date: 2024-03-29

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

**Contact info** 

 $\quad \text{More info} \quad > \quad$ 

CarCheck.co.uk page 10/12



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-07-11
Last registration	2023-07-04
Complete history	See info



Registration #1	2006-07-11	10 mi
Registration #2	2009-06-11	14.547 mi
Registration #3	2010-07-07	17.614 mi
Registration #4	2011-06-20	19.761 mi
Registration #5	2012-07-13	26.614 mi
Registration #6	2013-06-21	35.029 mi
Registration #7	2013-06-21	35.029 mi
Registration #8	2014-01-14	36.331 mi
Registration #9	2015-01-13	43.311 mi
Registration #10	2015-06-15	44.580 mi
Registration #11	2016-06-22	52.085 mi
Registration #12		77.777 es
Registration #13		77,777 66
Registration #14		77.777 es
Registration #15		77,777 66
Registration #16		71.777 ea
Registration #17		71.777 es
Registration #18		71.777 es
Registration #19		11.177 es
Registration #20		71.777 es
Registration #21		11,777 66

More info >

CarCheck.co.uk page 11/12



**VEZ1400**report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1791 mm
Height	1437 mm
Length	4407 mm
Wheel base	2578 mm
Kerb weight	1535 kg
Max. allowed weight	2000 kg

# Additional information

Fuel tank capacity	55 I
Fuel delivery	Direct Injection
Number of doors	2
0 0 1	10/10

CarCheck.co.uk page 12/12

Number of seats	4
Number of axles	2
Engine number	BWA 083606