



report date: 2024-03-29

General information

Make	VAUXHALL
Model	COMBO 2000 CDTI CREWVAN
Colour	Blue
Year of manufacture	-
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	170 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg




LABEL UNKNOWN



Internet history

Entry 2

Date	2021-09-26
Pictures	17
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-09-25
Pictures	17
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history**

<b>MOT #16</b>	2022-11-01 13:00
<b>MOT test number</b>	223433590818
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-11-07
<b>Advice</b>	Central Front Oil leak, but not excessive OIL DRIPPING BUT NOT EXCEEDING REQUIREMENTS (8.4.1 (a) (i))
<b>Advice</b>	Offside Rear SEAT BELT BUCKLE CASING MISSING BUT FUNCTIONS AS REQUIRED
<b>Minor</b>	Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated GREASE LEAKING OUT (6.1.7 (g) (i))
<b>Advice</b>	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
<b>Advice</b>	Central Front Registration plate deteriorated but not likely to be misread (0.1 (b))

<b>MOT #15</b>	2022-11-01 13:00
<b>MOT test number</b>	713292624583
<b>Result</b>	✗ Failed
<b>Advice</b>	Central Front Registration plate deteriorated but not likely to be misread (0.1 (b))
<b>Advice</b>	Central Front Oil leak, but not excessive OIL DRIPPING BUT NOT EXCEEDING REQUIREMENTS (8.4.1 (a) (i))
<b>Advice</b>	Offside Rear SEAT BELT BUCKLE CASING MISSING BUT FUNCTIONS AS REQUIRED
<b>Pass with rectification</b>	Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))
<b>Minor</b>	Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated GREASE LEAKING OUT (6.1.7 (g) (i))
<b>Advice</b>	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

<b>MOT #14</b>	2021-10-23 11:19
<b>MOT test number</b>	398731344624
<b>Result</b>	✓ Passed

**Advice** Rear Shock absorbers has light misting of oil both sides (5.3.2 (b))

**Minor** Offside Rear Registration plate lamp missing in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #13**

2021-10-21 16:59

**MOT test number**

773573005292

**Result****✗ Failed**

- Fail** Rear Exhaust catalytic converter missing where one was fitted as standard (8.2.1.1 (a))
- Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Minor** Offside Rear Registration plate lamp missing in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Rear Shock absorbers has light misting of oil both sides (5.3.2 (b))
- Fail** Oil leaking excessively from engine (8.4.1 (a) (i))

**MOT #12**

2020-11-07 13:01

**MOT test number**

884042976581

**Result****✓ Passed**

- Advice** Nearside Rear Nail in tyre
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Spare tyre missing
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11**

2020-11-07 10:57

**MOT test number**

324149724455

**Result**

✗ Failed

**Fail**

Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

**Advice**

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail**

Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**Advice**

Spare tyre missing

**Advice**

Nearside Front Play in steering rack inner joint(s)

**Advice**

Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))

**Advice**

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice**

Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**Advice**

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice**

Nearside Rear Nail in tyre

**Advice**

Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #10**

2019-05-08 14:52

**MOT test number**

243687894663

**Result**

✓ Passed

**Advice**

Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice**

Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**Advice**

Offside Front tyre has 2 punctures in it

**MOT #9**

2018-06-21 13:43

**MOT test number**

382596371358

**Result**

✓ Passed

**MOT #8** 2018-06-20 14:55**MOT test number** 839808147105**Result** ✗ Failed**Fail** Offside Rear Inner Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (i))**MOT #7** 2015-07-20 11:46**MOT test number** 769481505274**Result** ✓ Passed**MOT #6** 2014-06-24 14:45**MOT test number** 579385474147**Result** ✓ Passed**Notice** Vehicle's internal headlight adjuster altered to recheck lights**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #5** 2014-06-24 14:45**MOT test number** 487385374131**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim too high (1.8)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Pass with rectification** Offside Front Headlamp aim too high (1.8)**Notice** Vehicle's internal headlight adjuster altered to recheck lights**MOT #4** 2013-07-10 14:25**MOT test number** 618991293134**Result** ✓ Passed



MOT #3	2013-07-08 17:27
MOT test number	816439783133
Result	✗ Failed
<div>Fail</div> Offside Front Tyre has ply or cords exposed (4.1.D.1b)	

MOT #2	2012-07-20 13:59
MOT test number	435272902237
Result	✓ Passed

MOT #1	2011-08-04 16:02
MOT test number	917406711259
Result	✓ Passed



Damage history


Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Number of owners	1
Current owner since	2019-06-29
Previous owner since	2019-06-29
Number of owners	1
Current owner since	2019-06-29
Previous owner since	2019-06-29

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 EY580EK
Plate since	2019-06-29
Current registration	 EY580EK
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-09-02
Last registration	2022-11-01
Complete history	<a href="#">See info</a>



Registration #1	2008-09-02	27 mi
Registration #2	2011-08-04	31.003 mi
Registration #3	2012-07-20	42.625 mi
Registration #4	2013-07-08	53.780 mi
Registration #5	2013-07-10	53.780 mi
Registration #6	2014-06-24	61.729 mi
Registration #7	2015-07-20	70.383 mi
Registration #8	2018-06-20	71.621 mi
Registration #9	2018-06-21	71.634 mi
Registration #10	2019-06-20	71.634 mi
Registration #11	2019-06-20	71.634 mi
Registration #12	2019-06-20	71.634 mi
Registration #13	2019-06-20	71.634 mi
Registration #14	2019-06-20	71.634 mi
Registration #15	2019-06-20	71.634 mi
Registration #16	2019-06-20	71.634 mi
Registration #17	2019-06-20	71.634 mi
Registration #18	2019-06-20	71.634 mi

More info >



Dimensions & weight

Width	1892 mm
Height	1801 mm
Length	4323 mm
Kerb weight	1287 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Engine number	2804196