



report date: 2024-03-29

## General information

Make	VAUXHALL
Model	ANTARA EXCLUSIV CDTI S/S
Colour	White
Year of manufacture	2013
Top speed	117 mph
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	54.3 mpg
Consumption combined	46.3 mpg
CO2 emission	160 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-09-12
Pictures	1
Listing price	<a href="#">View report</a>



source: **cargurus.co.uk**



MOT history

MOT expiry date	2024-10-24
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	23
Total items failed	18

MOT #13	2023-10-25 09:05
MOT test number	483721405011
Result	✓ Passed
Next expiry date	2024-10-24
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Front tyre tread depth gelling low
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #12**

2023-10-24 12:48

**MOT test number**

569565970901

**Result****✗ Failed**

- Advice** Offside Front tyre tread depth gelling low
- Fail** Nearside Headlamp aim unable to be tested (4.1.2 (b))
- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Offside Rear Anti-roll bar linkage fractured (5.3.3 (b) (ii))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Offside Headlamp aim too high (4.1.2 (a))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #11**

2022-10-06 11:37

**MOT test number**

502360426547

**Result****✓ Passed**

- Advice** Nearside rear tyre worn on edges
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #10**

2022-10-05 15:36

**MOT test number**

376474680027

**Result****✗ Failed****Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Offside Front Lower Steering locking device missing ball joint split pin missing (2.1.3 (d))**Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Fail** Nearside Front Lower Steering locking device missing ball joint split pin missing (2.1.3 (d))**Advice** Nearside rear tyre worn on edges**MOT #9**

2021-09-24 10:24

**MOT test number**

700495037643

**Result****✓ Passed****MOT #8**

2021-09-21 16:04

**MOT test number**

686395109319

**Result****✗ Failed****Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Reversing lamp inoperative (4.6.1 (a))**MOT #7**

2020-11-12 15:08

**MOT test number**

745135865987

**Result****✓ Passed****Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge On legal limit (5.2.3 (e))



MOT #6	2019-11-07 15:16
MOT test number	556002278115
Result	✓ Passed

MOT #5	2019-11-07 09:51
MOT test number	749163469049
Result	✗ Failed

- Fail** Front Service brake excessively fluctuating (1.2.1 (e))
- Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Nearside Front Position lamp incorrect colour (4.2.3 (a) (i))
- Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Minor** Offside Front Position lamp incorrect colour (4.2.3 (a) (i))

MOT #4	2018-07-03 14:33
MOT test number	388393459437
Result	✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))



MOT #3	2017-05-06 10:14
MOT test number	311897583988
Result	✓ Passed

MOT #2	2017-05-06 09:39
MOT test number	129649476295
Result	✗ Failed
<div><div>Fail</div>Nearside Rear Registration plate lamp not working (1.1.C.1d)</div>	
<div><div>Fail</div>Offside Rear Outer Brake pad(s) less than 1.5 mm thick (3.5.1g)</div>	
<div><div>Fail</div>Offside Rear Registration plate lamp not working (1.1.C.1d)</div>	

MOT #1	2016-03-14 15:26
MOT test number	460405574854
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
24 October 2024

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	306
<b>MOT expiry date</b>	24 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-





Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Number of owners	1
Current owner since	2019-01-01
Previous owner since	2019-01-01
Number of owners	1
Current owner since	2019-01-01
Previous owner since	2019-01-01

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 SA13XXJ
Plate since	2019-01-01
Current registration	 SA13XXJ
Plate since	2019-01-01

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-03-27
Last registration	2023-10-25
Complete history	<a href="#">See info</a>



Registration #1	2013-03-27	22 mi
Registration #2	2016-03-14	10.821 mi
Registration #3	2017-05-06	25.560 mi
Registration #4	2017-05-06	25.560 mi
Registration #5	2018-07-03	38.964 mi
Registration #6	2019-11-07	52.032 mi
Registration #7	2019-11-07	52.032 mi
Registration #8	2020-11-12	61.476 mi
Registration #9	2020-11-12	61.476 mi
Registration #10	2020-11-12	61.476 mi
Registration #11	2020-11-12	61.476 mi
Registration #12	2020-11-12	61.476 mi
Registration #13	2020-11-12	61.476 mi
Registration #14	2020-11-12	61.476 mi
Registration #15	2020-11-12	61.476 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2085 mm
Height	1761 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1836 kg
Max. allowed weight	2505 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 263998K LNQ