



PEUGEOT



SFIOHKH


report date: 2024-03-28

General information

Make	PEUGEOT
Model	EXPERT L1 E7 TAXI
Colour	Black
Year of manufacture	2010
Top speed	99 mph
0 - 60 mph	13.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	300 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.0 mpg
Consumption extra urban	44.8 mpg
Consumption combined	39.2 mpg
CO2 emission	198 g/km
CO2 label	J





MOT history

MOT expiry date	2021-11-11
MOT pass rate	85 %
MOT passed	17
Failed MOT tests	3
Total advice items	21
Total items failed	8

MOT #20 2020-11-12 10:18

MOT test number 745377697678

Result ✓ Passed

Next expiry date 2021-11-11

- Advice** Nearside Front Inner Play in steering rack inner joint(s)
- Minor** Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #19 2020-05-06 11:45

MOT test number 795177672652

Result ✓ Passed

MOT #18 2020-05-05 08:42

MOT test number 383601166954

Result ✗ Failed

- MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- DANGEROUS** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #17** 2019-10-10 12:50**MOT test number** 417927259747**Result** ✓ Passed**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #16** 2019-05-09 12:48**MOT test number** 131724941637**Result** ✓ Passed**MOT #15** 2019-05-09 11:15**MOT test number** 507609292754**Result** ✗ Failed**MAJOR** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MAJOR** Front Exhaust system insecure (6.1.2 (a))**MOT #14** 2018-10-15 10:03**MOT test number** 114319214840**Result** ✓ Passed**MOT #13** 2018-05-23 10:56**MOT test number** 234153340494**Result** ✓ Passed**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12** 2017-10-11 12:33**MOT test number** 820878959723**Result** ✓ Passed**MOT #11** 2017-05-10 14:40**MOT test number** 152241512393**Result** ✓ Passed**Advice** Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)**Advice** Engine Management Light on**Advice** Nearside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**MOT #10** 2016-11-08 18:36**MOT test number** 755084558928**Result** ✓ Passed**Advice** Nearside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

**MOT #9** 2016-11-07 13:40**MOT test number** 547778245515**Result** ✗ Failed**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Check engine light on**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)**MOT #8** 2016-05-09 15:30**MOT test number** 919462375729**Result** ✓ Passed**MOT #7** 2015-11-25 12:19**MOT test number** 304377976257**Result** ✓ Passed**MOT #6** 2015-05-26 09:39**MOT test number** 248276345168**Result** ✓ Passed



MOT #5	2014-11-17 09:40
MOT test number	377641124331
Result	✓ Passed
MOT #4	2013-11-12 13:36
MOT test number	875206813305
Result	✓ Passed
MOT #3	2012-11-14 14:03
MOT test number	986169912348
Result	✓ Passed
MOT #2	2011-11-21 11:17
MOT test number	116805621394
Result	✓ Passed
MOT #1	2011-05-13 11:32
MOT test number	579773731191
Result	✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
11 January 2021

✕
MOT

Expired:
11 November 2021

Tax status	Expired at 11 January 2021
Days left	1203 days too late
MOT expiry date	11 November 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	SF10HKH
Plate since	2019-03-28
Current registration	SF10HKH
Plate since	2019-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2010-05-20
Last registration	2020-11-12
Complete history	See info



Registration #1	2010-05-20	7 mi
Registration #2	2011-05-13	22.387 mi
Registration #3	2011-11-21	30.254 mi
Registration #4	2012-11-14	67.379 mi
Registration #5	2013-11-12	102.525 mi
Registration #6	2014-11-17	140.436 mi
Registration #7	2015-05-26	160.885 mi
Registration #8	2015-11-25	179.344 mi
Registration #9	2016-05-09	188.218 mi
Registration #10	2016-11-07	211.425 mi
Registration #11	2016-11-08	211.431 mi
Registration #12	2016-11-08	211.431 mi
Registration #13	2016-11-08	211.431 mi
Registration #14	2016-11-08	211.431 mi
Registration #15	2016-11-08	211.431 mi
Registration #16	2016-11-08	211.431 mi
Registration #17	2016-11-08	211.431 mi
Registration #18	2016-11-08	211.431 mi
Registration #19	2016-11-08	211.431 mi
Registration #20	2016-11-08	211.431 mi
Registration #21	2016-11-08	211.431 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1998 mm
Height	1934 mm
Length	4806 mm
Wheel base	3000 mm
Kerb weight	1821 kg
Max. allowed weight	2759 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	9

Engine number	DYXB4011128
---------------	-------------